Submit 3 Copies To Appropriate District Office	State of New M Energy, Minerals and Nati		~	Form C-103 May 27, 2004
District I 1625 N. French Dr., Hobbs, NM 87240			WELL API NO.	/
District II	OIL CONSERVATIO	NOIVISION	30-025-08818	
301 W. Grand Ave., Affesia, NM 88210		5. Indicate Type of Lease		
District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM		STATE 😿 FEI	
1220 S. St Francis Dr., Santa Fe, NM 87505			6. State Oil & Gas Lease No	·
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agre STATE A A/C 2	ement Name:
1. Type of Well: Oil Well Gas Well	Other SWD		8. Well Number 006	/
2. Name of Operator			9. OGRID Number	
PETROHAWK OPERATING COMPANY 3. Address of Operator	2 /		194849 10. Pool name or Wildcat 5	1110
	COTTOMONI MW 77000		SEVEN RIVERS QUEEN	(UI), /
1000 LOUISIANA, STE 5600, HOUSTON, TX 77002 SEVEN RIVERS QUEEN 4. Well Location				
Unit Letter <u>B</u> :	660 feet from the NC	ORTH line and	1980 feet from the	EAST line
Section 7	Township 228	Range 36E	NMPM County	IFA
11. Elevation (Show whether DR, RKB, RT, GR, etc.) GR 3596				
Pit or Below-grade Tank Application or Closure				
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction Material				
NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	PLUG AND ABANDON X CHANGE PLANS MULTIPLE	REMEDIAL WORK COMMENCE DRILLI CASING TEST AND	ING OPNS. PLUG ABAND	ING CASING
	COMPLETION	CEMENT JOB		
OTHER:		OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
			RECEIVED	
Please see attached Proced	are with Wellbore Schemat	tics.	FEB 0 2 2009	
	Billiet he notified		HOBBSOCD	
The Oil Conservation Division Must be notified 24 hours prior to the beginning of plugging operations				
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan				
grade tank has been/will be constructed or ch	1		or an (attached) alternative OCI Consultant DATE	· · · —
SIGNATURE.		mail address:	seay04@leaco.net	<u> </u>
Type or print name EDDIE SEAY	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	man addless.	Telephone No.	505-390-2454
For State Use Only	Not 24King	-n)	•	1-1-000
APPROVED BY	- which are	file e	date 2	13/2007
Conditions of Approval, if any:	V	Tinto	1	,
COMPLIANCE OFFICER				

Petrohawk Operating Company

State A A/C -2 Well # 6
Jalmat Field
Sec 7B, T 22S, R 36E
Lea County, New Mexico

Plug & Abandonment Procedure:

- 1. MIRU Plugging Rig. ND wellhead. NU BOPS.
- 2. PU work string and TIH to CIBP located at 3650'. Circulate and load hole with 10 ppg gelled brine.
- 3. Mix and spot 250' (55 sks Class "C") cement plug on top of CIBP from 3650' 3400'.
- 4. Perforate 7" casing at 1500'. PU Squeeze packer on work string and TIH. Mix and squeeze 200' (70 sks Class "C") cement plug through perfs at 1500' leaving top of cement inside the 7" casing at 1300'. WOC and tag top of plug to verify depth. POOH.
- 5. Perforate 7" casing at 350'. Mix surface cement plug (125 sks Class "C") and squeeze through perfs at 350' attempting to circulate cement to surface. Leave top of cement inside casing at surface.
- 6. Cutoff wellhead, cap well and install P&A marker.
- 7. Clean location for OCD inspection.

01/29/2009

