
Office	State of New N	ICAICO	Form C-103
Office  District I  1625 N. French Dr., Hobbs, NM 88245  District II	Minerals and Na	tural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 District II	क्षा प्राप्त विद्युक्त विकर्ण		WELL API NO. 30 025 08288 🗸
District II  1301 W. Grand Ave., Artesia, NM 88210 District III	, OIL CONSERVATIO	N DIVISION	5. Indicate Type of Lease FEDERAL
District III	1220 South St. Fr	ancis Dr.	STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	<b>SOCD</b> Santa Fe, NM	87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM			NMLC-065880
87505 SUNDRY NOTICE	ES AND REPORTS ON WELI	LS .	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSAL	LS TO DRILL OR TO DEEPEN OR F	LUG BACK TO A	. North El Mar Unit
DIFFERENT RESERVOIR. USE "APPLICA" PROPOSALS.)	TION FOR PERMIT" (FORM C-101)	FOR SUCH	
1. Type of Well: Oil Well	Gas Well 🛛 Other Service	(injection)	8. Well Number 33
2. Name of Operator			9. OGRID Number 20077 /
	ara Operating Company		
3. Address of Operator	D 4400 MUL A TV 70704		10. Pool name or Wildcat
	Box 4130, Midland, TX 79704		El Mar (Delaware)
4. Well Location	•		
Unit Letter P 660	feet from the <u>South</u>	line and <u>660</u> _	feet from the <u>East</u> line
Section 26	Township 26S	Range 33E	NMPM County
	11. Elevation (Show whether D	R, RKB, RT, GR, etc.)	F T E A W W C
Pit or Below-grade Tank Application □ or C	3,113 DF		
	TDistance from nearest fresh		ance from nearest surface water
Pit Liner Thickness: mil	Below-Grade Tank: Volume	bbls; Con	nstruction Material
12. Check Ap	propriate Box to Indicate	Nature of Notice, l	Report or Other Data
NOTICE OF INT	ENTION TO:	l cub	SECUENT BEDORT OF
NOTICE OF INT			SEQUENT REPORT OF: K ⊠ ALTERING CASING □
<u></u>	PLUG AND ABANDON   CHANGE PLANS	REMEDIAL WORK	
<del></del>	MULTIPLE COMPL	CASING/CEMENT	<del></del>
FULL OR ALTER CASING	_		
OTHER:		OTHER:	
OTHER:  13. Describe proposed or complet	ed operations. (Clearly state a	OTHER:	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or complet of starting any proposed work or recompletion.	ed operations. (Clearly state al.). SEE RULE 1103. For Mult	OTHER: Il pertinent details, and iple Completions: Att	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or complet of starting any proposed work or recompletion.  Report on MIT test. Well fair	ted operations. (Clearly state al.). SEE RULE 1103. For Multilled MIT on 1-13-2009. M	OTHER: Il pertinent details, and iple Completions: Att	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion ait, POH w/tbg and packer, test BIH
OTHER:  13. Describe proposed or complet of starting any proposed work or recompletion.  Report on MIT test. Well fai w/redressed packer, found 1	ed operations. (Clearly state al.). SEE RULE 1103. For Mult led MIT on 1-13-2009. Mhole, reset tubing at 4526	OTHER: Il pertinent details, and iple Completions: Att	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or complet of starting any proposed work or recompletion.  Report on MIT test. Well fair	ed operations. (Clearly state al.). SEE RULE 1103. For Mult led MIT on 1-13-2009. Mhole, reset tubing at 4526	OTHER: Il pertinent details, and iple Completions: Att	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion ait, POH w/tbg and packer, test BIH
OTHER:  13. Describe proposed or complet of starting any proposed work or recompletion.  Report on MIT test. Well fai w/redressed packer, found 1 Work complete on 1-26-200	ed operations. (Clearly state al.). SEE RULE 1103. For Mult led MIT on 1-13-2009. M hole, reset tubing at 4526 9.	OTHER: Il pertinent details, and iple Completions: Att  foved in pulling un  c', circ w/pkr fluid,	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion ait, POH w/tbg and packer, test BIH NU WH, load ann 500# OK. SIW:
OTHER:  13. Describe proposed or complet of starting any proposed work or recompletion.  Report on MIT test. Well fai w/redressed packer, found 1	ed operations. (Clearly state al.). SEE RULE 1103. For Mult led MIT on 1-13-2009. M hole, reset tubing at 4526 9.	OTHER: Il pertinent details, and iple Completions: Att  foved in pulling un  c', circ w/pkr fluid,	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion ait, POH w/tbg and packer, test BIH NU WH, load ann 500# OK. SIW:
OTHER:  13. Describe proposed or complet of starting any proposed work or recompletion.  Report on MIT test. Well fai w/redressed packer, found 1 Work complete on 1-26-200	ed operations. (Clearly state al.). SEE RULE 1103. For Mult led MIT on 1-13-2009. M hole, reset tubing at 4526 9.	OTHER: Il pertinent details, and iple Completions: Att  foved in pulling un  c', circ w/pkr fluid,	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion ait, POH w/tbg and packer, test BIH NU WH, load ann 500# OK. SIW:
OTHER:  13. Describe proposed or complet of starting any proposed work or recompletion.  Report on MIT test. Well fai w/redressed packer, found 1 Work complete on 1-26-200	ed operations. (Clearly state al.). SEE RULE 1103. For Mult led MIT on 1-13-2009. M hole, reset tubing at 4526 9.	OTHER: Il pertinent details, and iple Completions: Att  foved in pulling un  c', circ w/pkr fluid,	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion ait, POH w/tbg and packer, test BIH NU WH, load ann 500# OK. SIW:
OTHER:  13. Describe proposed or complet of starting any proposed work or recompletion.  Report on MIT test. Well fai w/redressed packer, found 1 Work complete on 1-26-200	ed operations. (Clearly state al.). SEE RULE 1103. For Mult led MIT on 1-13-2009. M hole, reset tubing at 4526 9.	OTHER: Il pertinent details, and iple Completions: Att  foved in pulling un  c', circ w/pkr fluid,	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion ait, POH w/tbg and packer, test BIH NU WH, load ann 500# OK. SIW:
OTHER:  13. Describe proposed or complet of starting any proposed work or recompletion.  Report on MIT test. Well fai w/redressed packer, found 1 Work complete on 1-26-200	ed operations. (Clearly state al.). SEE RULE 1103. For Mult led MIT on 1-13-2009. M hole, reset tubing at 4526 9.	OTHER: Il pertinent details, and iple Completions: Att  foved in pulling un  c', circ w/pkr fluid,	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion ait, POH w/tbg and packer, test BIH NU WH, load ann 500# OK. SIW:
OTHER:  13. Describe proposed or complet of starting any proposed work or recompletion.  Report on MIT test. Well fai w/redressed packer, found 1 Work complete on 1-26-200	ed operations. (Clearly state al.). SEE RULE 1103. For Mult led MIT on 1-13-2009. M hole, reset tubing at 4526 9.	OTHER: Il pertinent details, and iple Completions: Att  foved in pulling un  c', circ w/pkr fluid,	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion ait, POH w/tbg and packer, test BIH NU WH, load ann 500# OK. SIW:
OTHER:  13. Describe proposed or complet of starting any proposed work or recompletion.  Report on MIT test. Well fai w/redressed packer, found 1 Work complete on 1-26-200	ed operations. (Clearly state al.). SEE RULE 1103. For Mult led MIT on 1-13-2009. M hole, reset tubing at 4526 9.	OTHER: Il pertinent details, and iple Completions: Att  foved in pulling un  c', circ w/pkr fluid,	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion ait, POH w/tbg and packer, test BIH NU WH, load ann 500# OK. SIW:
OTHER:  13. Describe proposed or complet of starting any proposed work or recompletion.  Report on MIT test. Well fai w/redressed packer, found 1 Work complete on 1-26-200 Retested on 2-2-2009, tested.	ed operations. (Clearly state al.). SEE RULE 1103. For Multipled MIT on 1-13-2009. M hole, reset tubing at 4526 9.  It to 500 psi f/30 minutes (Control of the control of t	OTHER: Il pertinent details, and iple Completions: Att  Toved in pulling un  Toved, circ w/pkr fluid,  OK. Original test completest of my knowledge	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion ait, POH w/tbg and packer, test BIH NU WH, load ann 500# OK. SIW:
OTHER:  13. Describe proposed or complet of starting any proposed work or recompletion.  Report on MIT test. Well fai w/redressed packer, found 1 Work complete on 1-26-200 Retested on 2-2-2009, tested.	ed operations. (Clearly state al.). SEE RULE 1103. For Multipled MIT on 1-13-2009. M hole, reset tubing at 4526 9.  It to 500 psi f/30 minutes (Control of the control of t	OTHER: Il pertinent details, and iple Completions: Att  Toved in pulling un  Toved, circ w/pkr fluid,  OK. Original test completest of my knowledge	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion wit, POH w/tbg and packer, test BIH NU WH, load ann 500# OK. SIW:  hart is attached.
OTHER:  13. Describe proposed or complete of starting any proposed work or recompletion.  Report on MIT test. Well fair w/redressed packer, found 1 Work complete on 1-26-200 Retested on 2-2-2009, tested.  I hereby certify that the information ab grade tank has been/will be constructed or closely.	ded operations. (Clearly state al.). SEE RULE 1103. For Multipled MIT on 1-13-2009. M hole, reset tubing at 4526 9.  It to 500 psi f/30 minutes (Consequence of the seed according to NMOCD guideline).	OTHER:  Il pertinent details, and iple Completions: Att  Toved in pulling un  Toved in pullin	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion bit, POH w/tbg and packer, test BIH NU WH, load ann 500# OK. SIW.  hart is attached.  e and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan  DATE 2-03-2009
OTHER:  13. Describe proposed or complet of starting any proposed work or recompletion.  Report on MIT test. Well fai w/redressed packer, found 1 Work complete on 1-26-200 Retested on 2-2-2009, tested.  I hereby certify that the information ab grade tank has been/will be constructed or close SIGNATURE.  Type or print name Robert McAlp	ded operations. (Clearly state all). SEE RULE 1103. For Multipled MIT on 1-13-2009. M hole, reset tubing at 4526 9.  It to 500 psi f/30 minutes (Consequence of the sect according to NMOCD guideline).	OTHER:  Il pertinent details, and iple Completions: Att  Toved in pulling un  Toved in pullin	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion bit, POH w/tbg and packer, test BIH NU WH, load ann 500# OK. SIW.  hart is attached.  e and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan  DATE 2-03-2009
OTHER:  13. Describe proposed or complete of starting any proposed work or recompletion.  Report on MIT test. Well fair w/redressed packer, found 1 Work complete on 1-26-200 Retested on 2-2-2009, tested on 2-2-2009, tested or close starting any proposed work or recomplete on 1-26-200 Retested on 2-2-2009, tested or SIGNATURE  Type or print name Robert McAlp For State Use Only	ed operations. (Clearly state al.). SEE RULE 1103. For Multiple MIT on 1-13-2009. M hole, reset tubing at 4526 9.  It to 500 psi f/30 minutes (Consequence of the operation of t	OTHER:  Il pertinent details, and iple Completions: Att  Toved in pulling un  coved in pullin	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion  it, POH w/tbg and packer, test BIH NU WH, load ann 500# OK. SIW:  hart is attached.  e and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan .  DATE 2-03-2009  net Telephone No. 432-697-0967
OTHER:  13. Describe proposed or complete of starting any proposed work or recompletion.  Report on MIT test. Well fair w/redressed packer, found 1 Work complete on 1-26-200.  Retested on 2-2-2009, tested on 2-2-2009, tested on 2-2-2009, tested on SIGNATURE  Type or print name Robert McAlp For State Use Only  APPROVED BY:	ded operations. (Clearly state al.). SEE RULE 1103. For Multipled MIT on 1-13-2009. M hole, reset tubing at 4526 9.  It to 500 psi f/30 minutes (Consequence of the set according to NMOCD guideline of the prine E-mail address: Saha	OTHER:  Il pertinent details, and iple Completions: Att  Toved in pulling un  Toved in pullin	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion wit, POH w/tbg and packer, test BIH NU WH, load ann 500# OK. SIW:  hart is attached.  e and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan .  DATE 2-03-2009  net Telephone No. 432-697-0967
OTHER:  13. Describe proposed or complete of starting any proposed work or recompletion.  Report on MIT test. Well fair w/redressed packer, found 1 Work complete on 1-26-200 Retested on 2-2-2009, tested on 2-2-2009, tested or close starting any proposed work or recomplete on 1-26-200 Retested on 2-2-2009, tested or SIGNATURE  Type or print name Robert McAlp For State Use Only	ed operations. (Clearly state al.). SEE RULE 1103. For Multiple MIT on 1-13-2009. M hole, reset tubing at 4526 9.  It to 500 psi f/30 minutes (Consequence of the operation of t	OTHER:  Il pertinent details, and iple Completions: Att  Toved in pulling un  coved in pullin	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion  it, POH w/tbg and packer, test BIH NU WH, load ann 500# OK. SIW:  hart is attached.  e and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan .  DATE 2-03-2009  net Telephone No. 432-697-0967



24. STEST 24. STEST Dalid Transport Jesus Salgado

SHHANA CIFARTING CS