Office	es 10 Appropriate Di		State of New Mo			Form C-103			
District I		Energy	, Minerals and Natu	ral Resources	WELLA	June 19, 2008			
1625 N French District II	Dr , Hobbs, NM 882	RECEIVE	WELL API NO. 30-025-33541						
1301 W Grand District III	Ave, Artesia, NM 8	8210 OIL C FEB 17 2001	5. Indicate Type of Le						
1000 Pro Proze	os Rd, Aztec, NM 87	STATE 🖂	FEE						
District IV 1220 S St Fran 87505	ncis Dr , Santa Fe, NM	HOBBSOCE	Santa Fe, NM 87	/303	6. State Oil & Gas Le	ase No.			
07303	SUNDRY N	NOTICES AND RI	EPORTS ON WELL	S	7. Lease Name or Uni	it Agreement Name			
			L OR TO DEEPEN OR PLU ERMIT" (FORM C-101) FO		Warner St				
PROPOSALS)			8. Well Number #20	6 . /					
	Well: Oil Well	Gas Well							
2. Name of	•	athon Oil Compa	ny 🗸		9. OGRID Number 1402	.1			
3. Address of	•	Houston, Texas	77253_3487 N	Mail Stop #3308	10. Pool name or Wile Vacu				
4. Well Loc		Trouston, Texas	<u> </u>	1411 Stop #3500	v acu	unk			
		" feet from the	North line and	400' feet fr	rom the West li	ine /			
	tion 6	Township 18-		35-E NMPN					
			on (Show whether DR)		VI County LEA				
		. O V. 10 10 10 10 10 10 10 10 10 10 10 10 10	3,967' GL ,						
12. Check	Appropriate E	Box to Indicate N	Nature of Notice, R	Report or Other I	Data				
	NOTICE O	F INTENTION	TO:	SUB	SEQUENT REPO	RT OF:			
	REMEDIAL WOR	_	REMEDIAL WOR						
	EMPORARILY ABANDON ☑ CHANGE PLANS ☐ COMMENCE DRILLING OPNS ☐ P AND A ☐								
	TER CASING	MULTIPLE		CASING/CEMEN					
DOWNHOLD	E COMMINGLE	□ Co	ndition of Approval	: Notify OCD Hob	obs				
OTHER:		ОП	ice 24 hours prior t	o running MIT Te	st & Chart				
					dates, in				
	arting any propos completion.	ed work). SEE RU	LE 1103. For Multip	le Completions: At	tach wellbore diagram o	f proposed completion			
** Marath	on Oil Compa				atus for the above				
					future date. Wellbore does not NOTE: (Wait, for 'NMC				
Procedure			.,		<u></u> . (<u></u>	, approximity			
RU well service unit. POOH laying down rods and pump. Install BOPE and test.									
POOH laying down tubing.									
RU electric wireline. Make Gauge ring/junk basket run to 10450'. RIH with dump bailer and place at least 36 of									
cement on CIBP @ 10450' RIH with CIBP and set same at 9250'. Dump bail at least 39' of cement on same. RD Wireline.									
					same. RD Wireline.				
Load casing with fresh water and test same to NMOCD requirements.									
RD WSU. S	Submit integrit	y test to NMOC	D.						
this work, and					ins to remove any fluids ug is set. The only fluid				
	Γ.		٦						
Spud Date:	<u>Estimated</u> : F	ebruary 2009.	Rig Release Da	_{ite:} <u>Estimated</u> :	: February 2009.				
			_	L					
I hereby certif	y that the inform	ation above is true	and complete to the be	est of my knowledge	e and belief.				
SIGNATURE TITLE: Regulatory Compliance Representative DATE: 09-Feb-2009									
Type or print name: Rick R Schell, E-mail address: RRSCHELL@MarathonOil.com, PHONE: 713-296-3412									
For State Use	e Only	/ In /		TRICT 1 SHE	RVISOE	FEB 18 200			
APPROVED	BY:	int WIX	TITLE	HILOT TOUTE	DATE_	T. T. Wilder			
FFR 18 200 APPROVED BY: Conditions of Approval (if any) TITLE DISTRICT 1 SUPERVISOR DATE									

							•	
Well Name & No.		WARN STATE A/C 2 #26		Field	VACUUM		Date 02/03/09	
County	LEA	API	30 025 33541	State	NEW MEXICO	Ву	RSBOSE	
Spudded	11/26/1996	Comp Drlg	1/16/1997	Location	2180' FNL & 400' FWL, Section 6, Township 18S, Range 35E, UL 'E'			

GL: 3967' KB: 3982'

TD: 11497'

