PlA'd. OK TO RELEASE.

RECEIVED

Conditions of Approval (if any):

Submit 2 Copies To Appropriate District Office JAN 20 2600	Form C-103 October 25, 2007
Office District I JAN 20 2 MEhergy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM,88240	WELL API NO. 30-025-31856
District II 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Ave., Artesia, NM 88210 District III 1302 South St. Francis Dr.	
1220 South St. 1 failets D1.	5. Indicate Type of Lease STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	WTYSR Unit
PROPOSALS.) 1. Type of Well: □Oil Well □ Gas Well ☒ Other SWD	8. Well Number 600
2. Name of Operator Chesapeake Operating, Inc.	9. OGRID Number 147179
3. Address of Operator P.O. Box 18496	10. Pool name or Wildcat
Oklahoma City, OK 73154-0496	SWD; Delaware
4. Well Location	
Unit Letter G: 1730' feet from the North line and 1980' feet from the East line	
Section 16 Township 20S Range 33E NMPM County	
11. Elevation (Show whether DR, RKB, RT, GR, et 3539' GR	<i>c.)</i>
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WO	1
	RILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEME	NT JOB
OTHER:	
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.	
🔯 Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.	
X All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.)	
All other environmental concerns have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(non-retrieved flow lines and pipelines.	b) NMAC. All fluids have been removed from
When all work has been completed, return this form to the appropriate District office to schedule an inspection. If more than one inspection has to be made to a P&A location because it does not meet the criteria above, a penalty may be assessed.	
inspection has to be made to a recent of occasion decades it does not meet the criteria above, a penalty may be assessed.	
SIGNATURE Junda Sobol TITLE Sr. Regulatory Con	ppliance Sp. DATE <u>01/19/2009</u>
TYPE OR PRINT NAME Linda Good HID BOWYTHWOOOD MICHELE BY A STATE OF THE STATE OF TH	c.com PHONE: (405)935-4275
For State Use Only	DATE 1/16/2009
APPROVED BY: COOKET (APPROVED)	DATE 1/16/2009