

Office

Energy, Minerals and Natural Resources

June 19, 2008

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St Francis Dr., Santa Fe, NM

87505

RECEIVED

FEB 20 2009

HOBBSD

OIL CONSERVATION DIVISION

220 South St. Francis Dr.

Santa Fe, NM 87505

WELL API NO. ✓

30-025-26015

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil &amp; Gas Lease No.

7. Lease Name or Unit Agreement Name

New Mexico M State ✓

8. Well Number 49 ✓

9. OGRID Number

227588 ✓

10. Pool name or Wildcat ✓

Eunice, San Andres, Southwest

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☒

2. Name of Operator

Range Operating New Mexico, Inc. ✓

3. Address of Operator

100 Throckmorton St., Ste. 1200, Fort Worth, TX 76102

4. Well Location

Unit Letter J : 2160 feet from the south line and 2310 feet from the east line  
Section 18 Township 22S Range 37 E NMPM Lea County ✓

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3427

## 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

## NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

## SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐OTHER: ☐OTHER: TA ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

3  
1-21-2009 – Prepare for TA. MIRU PU, NDWH and POOH w/1 jt of 2 7/8 tbg. NUBOP and MIRU Schlumber WLT. RIH w/ 5.5" CIBP, correlate back to log and set CIBP @ 3745'. CIBP would not set. POOH w/tools, rewired tool and RIH w/tools. Got on depth and set CIBP @ 3745'. POOH w/wireline and MIRU pmp trk. Loaded hole w/26bbl of 2% KCL. Held 500 psi, bled off pressure, NDBOP, RIH w/1 jt of 2 7/8" tbg and NUWH. Secured wellhead, RDMO PU and WLT. RU pmp trk to csg and ran a 30 minute chart. Held good, no pressure decline. RDMO pmp truck.

2-02-2009 – Met OCD representative, Maxey G. Brown, at well site. RU pmp trk to csg and began 30 minute chart at 8:45 am MST. Held good. No pressure decline. Test was witnessed and chart signed by Maxey G. Brown, Deputy Inspector Compliance Officer of the OCD. New Mexico M State #49 is officially temporarily abandoned.

This Approval of Temporary  
Abandonment Expires

2-20-2014

Spud Date: 2-26-06

Rig Release Date: 3-12-06

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE sr. Reg. Sp.

DATE 2-2-2009

Type or print name Paula Hale

E-mail address: phale@rangeresources.com

PHONE: 817-869-4216

For State Use Only

APPROVED BY:

TITLE

DISTRICT 1 SUPERVISOR

DATE

FEB 20 2009

Conditions of Approval (if any):

