Submit 3 Copies To Appropriate District	es To Appropriate District State of New Mexico		Form C-103
Office District I Energy, Minerals and Natural Resources		ral Resources	June 19, 2008 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Ave., Artesia, NM 88210			30-025-06968
Division 1000 Courtle Ct. Emprois Dr.		oris Dr	5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 874101AK 2009 Santa Fe NM 87505			STATE FEE 5. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NMOBBSOCD			
87505 SUNDRY NOTIO	CES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Control Drinkord Unit
PROPOSALS.)			Central Drinkard Unit 8. Well Number 145
	Gas Well Other		9. OGRID Number
 Name of Operator Range Operating New Mexico, In 	nc.		227588
3. Address of Operator			10. Pool name or Wildcat Orinkand
100 Throckmorton St., Ste. 1200	, Fort Worth, TX 76102		Eunice; San Andres, Southwest
4. Well Location Unit Letter 1800 feet from the South line and 515 feet from the East line			
Unit Letter 1 . 1000 leet nom the County			
Section 33 Township 21S Range 37E NMPM Lea County 11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
3442			
12. Charle Ammoniate Boy to Indicate Nature of Notice Report or Other Data			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF IN		SUBS REMEDIAL WORK	EQUENT REPORT OF: ☐ ALTERING CASING ☐
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	PLUG AND ABANDON ☐ CHANGE PLANS ☐	COMMENCE DRILL	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB			
DOWNHOLE COMMINGLE			
OTHER:	П	OTHER:	
13 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompletion.			
5005 '			
MIRU wireline. Set CIBP @ 6450'. Dump bail 35' of cement on top of CIBP. Set CIBP @ 4950'. Pressure test casing to 500psi for 30 minutes – record on chart."			
Soopsi for 50 minutes – record on chart.			
	,		
Condition of Approval : Notify OCD Hobbs			
office 24 hours prior to running MIT Test & Chart			
Spud Date: 6/03/1947	Rig Release I	Date: 10/21/1947	
Spud Date. 0/03/1947	Tug Tuliousu 2	10, 21, 22 1,	
I hereby certify-that the-information above is true and complete to the best of my knowledge and belief.			
Thereby certify that the information above is true and complete to the best of my knowledge and benefit.			
SIGNATURE	TITLE S	Sr. Reg. <u>Sp.</u>	DATE 3-09-2009
Type or print name For State Use Only	E-mail addres	s:	PHONE:
	Sign DISTRIC	T 1 SUPERVISC	MAR 1 2 2009
Cample. A	v - y		
•			