Submit 3 Copies To Appropriate District Office District I State of New Mexico Energy, Minerals and Natural Resources	Form C-103 June 19, 2008
1625 N. French Dr., Hobbs, NM 88240	WELL API NO. 30-025-38429
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1220 South St. Francis Dr. 1200 Rio Brazos Rd., Aztec, NM 87410	STATE X FEE
District IV Santa Fe, NW 8/303	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name STATE F 1
PROPOSALS.) 1. Type of Well: Oil Well \(\overline{\text{X}}\) Gas Well \(\overline{\text{D}}\) Other	8. Well Number 17
Name of Operator ConocoPhillips Company	9. OGRID Number 217817 /
3. Address of Operator 3300 N. "A" Street, Bldg. 6 Midland, TX 79705	10. Pool name or Wildcat
3. Address of Operator 3300 N. "A" Street, Bldg. 6 Midland, 1X 79705	Hardy; Bliinebry/Hardy; Tubb-Drinkard
4. Well Location	
Unit Letter J: 1980 feet from the South line and 2230 feet from the East line	
Section 1 Township 21S Range 36E	NMPM County Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc. 3497 GR	
347/ UK	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR	_
PULL OR ALTER CASING	T JOB
DOWNHOLE COMMINGLE	
OTHER: OTHER: Backfill	- Control of the Cont
13. Describe proposed or completed operations. (Clearly state all pertinent details, an	d give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At	d give pertinent dates, including estimated date
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: As or recompletion. 	d give pertinent dates, including estimated date
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. Backfill reserve pit to OCD specs. 	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. Backfill reserve pit to OCD specs. 1.Pull existing liner from edges over pit. Mix existing dirt and stabilize pit to 4' from sure. 	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. Backfill reserve pit to OCD specs. 1.Pull existing liner from edges over pit. Mix existing dirt and stabilize pit to 4' from sur 2. Put in 1' sand barrier over entire pit. 3. Install 20 mill liner over entire pit. 	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. Backfill reserve pit to OCD specs. Pull existing liner from edges over pit. Mix existing dirt and stabilize pit to 4' from sur 2. Put in 1' sand barrier over entire pit. Install 20 mill liner over entire pit. Put in 1' sand barrier over new liner. 	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. Backfill reserve pit to OCD specs. 1.Pull existing liner from edges over pit. Mix existing dirt and stabilize pit to 4' from sur 2. Put in 1' sand barrier over entire pit. 3. Install 20 mill liner over entire pit. 	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. Backfill reserve pit to OCD specs. Pull existing liner from edges over pit. Mix existing dirt and stabilize pit to 4' from sur 2. Put in 1' sand barrier over entire pit. Install 20 mill liner over entire pit. Put in 1' sand barrier over new liner. Backfill pit with existing dirt to 1' from surface. 	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. Backfill reserve pit to OCD specs. Pull existing liner from edges over pit. Mix existing dirt and stabilize pit to 4' from sur 2. Put in 1' sand barrier over entire pit. Install 20 mill liner over entire pit. Put in 1' sand barrier over new liner. Backfill pit with existing dirt to 1' from surface. Cap entire pit with 2' topsoil, level and taper. 	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. Backfill reserve pit to OCD specs. Pull existing liner from edges over pit. Mix existing dirt and stabilize pit to 4' from sur 2. Put in 1' sand barrier over entire pit. Install 20 mill liner over entire pit. Put in 1' sand barrier over new liner. Backfill pit with existing dirt to 1' from surface. Cap entire pit with 2' topsoil, level and taper. Seed all disturbed areas with BLM #2 seed mixture with approved seeder. 	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. Backfill reserve pit to OCD specs. Pull existing liner from edges over pit. Mix existing dirt and stabilize pit to 4' from sur 2. Put in 1' sand barrier over entire pit. Install 20 mill liner over entire pit. Put in 1' sand barrier over new liner. Backfill pit with existing dirt to 1' from surface. Cap entire pit with 2' topsoil, level and taper. Seed all disturbed areas with BLM #2 seed mixture with approved seeder. 	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. Backfill reserve pit to OCD specs. Pull existing liner from edges over pit. Mix existing dirt and stabilize pit to 4' from sur 2. Put in 1' sand barrier over entire pit. Install 20 mill liner over entire pit. Put in 1' sand barrier over new liner. Backfill pit with existing dirt to 1' from surface. Cap entire pit with 2' topsoil, level and taper. Seed all disturbed areas with BLM #2 seed mixture with approved seeder. Job completed on 8-5-08 by McNabb Services. 	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. Backfill reserve pit to OCD specs. Pull existing liner from edges over pit. Mix existing dirt and stabilize pit to 4' from sur 2. Put in 1' sand barrier over entire pit. Install 20 mill liner over entire pit. Put in 1' sand barrier over new liner. Backfill pit with existing dirt to 1' from surface. Cap entire pit with 2' topsoil, level and taper. Seed all disturbed areas with BLM #2 seed mixture with approved seeder. 	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. Backfill reserve pit to OCD specs. 1.Pull existing liner from edges over pit. Mix existing dirt and stabilize pit to 4' from sur 2. Put in 1' sand barrier over entire pit. 3. Install 20 mill liner over entire pit. 4. Put in 1' sand barrier over new liner. 5. Backfill pit with existing dirt to 1' from surface. 6. Cap entire pit with 2' topsoil, level and taper. 7. Seed all disturbed areas with BLM #2 seed mixture with approved seeder. Job completed on 8-5-08 by McNabb Services. Rig Release Date:	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion face. SFP - 2 2009 HOBBS OCD
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. Backfill reserve pit to OCD specs. Pull existing liner from edges over pit. Mix existing dirt and stabilize pit to 4' from sur 2. Put in 1' sand barrier over entire pit. Install 20 mill liner over entire pit. Put in 1' sand barrier over new liner. Backfill pit with existing dirt to 1' from surface. Cap entire pit with 2' topsoil, level and taper. Seed all disturbed areas with BLM #2 seed mixture with approved seeder. Job completed on 8-5-08 by McNabb Services. 	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion face. SFP - 2 2009 HOBBS OCD
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. Backfill reserve pit to OCD specs. 1.Pull existing liner from edges over pit. Mix existing dirt and stabilize pit to 4' from sur 2. Put in 1' sand barrier over entire pit. 3. Install 20 mill liner over entire pit. 4. Put in 1' sand barrier over new liner. 5. Backfill pit with existing dirt to 1' from surface. 6. Cap entire pit with 2' topsoil, level and taper. 7. Seed all disturbed areas with BLM #2 seed mixture with approved seeder. Job completed on 8-5-08 by McNabb Services. Rig Release Date:	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion face. SFP - 2 2009 HOBBS OCD
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. Backfill reserve pit to OCD specs. 1.Pull existing liner from edges over pit. Mix existing dirt and stabilize pit to 4' from sur 2. Put in 1' sand barrier over entire pit. 3. Install 20 mill liner over entire pit. 4. Put in 1' sand barrier over new liner. 5. Backfill pit with existing dirt to 1' from surface. 6. Cap entire pit with 2' topsoil, level and taper. 7. Seed all disturbed areas with BLM #2 seed mixture with approved seeder. Job completed on 8-5-08 by McNabb Services. Rig Release Date:	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion face. SFP - 2 2009 HOBBS OCD
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. Backfill reserve pit to OCD specs. 1.Pull existing liner from edges over pit. Mix existing dirt and stabilize pit to 4' from sur 2. Put in 1' sand barrier over entire pit. 3. Install 20 mill liner over entire pit. 4. Put in 1' sand barrier over new liner. 5. Backfill pit with existing dirt to 1' from surface. 6. Cap entire pit with 2' topsoil, level and taper. 7. Seed all disturbed areas with BLM #2 seed mixture with approved seeder. Job completed on 8-5-08 by McNabb Services. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledges of the second seed of the second second second seed of the second second seed of the second second second seed of the second seco	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion SFP - 2 2009 SFP - 2 2009 e and belief. DATE 08/26/2008
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. Backfill reserve pit to OCD specs. 1.Pull existing liner from edges over pit. Mix existing dirt and stabilize pit to 4' from sur 2. Put in 1' sand barrier over entire pit. 3. Install 20 mill liner over entire pit. 4. Put in 1' sand barrier over new liner. 5. Backfill pit with existing dirt to 1' from surface. 6. Cap entire pit with 2' topsoil, level and taper. 7. Seed all disturbed areas with BLM #2 seed mixture with approved seeder. Job completed on 8-5-08 by McNabb Services. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge. SIGNATURE JULIAL A. JULIAL TITLE Regulatory Specialist	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion Face. SFP - 2 2009 Complete tach wellbore diagram of proposed completion SFP - 2 2009 e and belief.
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. Backfill reserve pit to OCD specs. 1. Pull existing liner from edges over pit. Mix existing dirt and stabilize pit to 4' from sur 2. Put in 1' sand barrier over entire pit. 3. Install 20 mill liner over entire pit. 4. Put in 1' sand barrier over new liner. 5. Backfill pit with existing dirt to 1' from surface. 6. Cap entire pit with 2' topsoil, level and taper. 7. Seed all disturbed areas with BLM #2 seed mixture with approved seeder. Job completed on 8-5-08 by McNabb Services. Spud Date: Rig Release Date: TITLE Regulatory Specialist Type or print name Celeste G. Dale E-mail address: celeste.g.dale@ce	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion SFP - 2 2009 SFP - 2 2009 e and belief. DATE 08/26/2008