Office Energy Minerals and Natural Resources	Form C-103 May 27, 2004	
District I		
1625 N. French Dr., Hobbs, NM 872400	0-025-35111	
MASSIS THE CONTRACTOR DIVISION	Type of Lease	
Diotrict III 1220 South St. Francis Dr.		
1000 Rio Biazos Rd., Aziec, Min 07410 Will V 7 2003 Santa 1 c, 1111 07505	TE 🗹 FEE 🖈	
District IV 1220 S. St. Francis Dr., Santa Fe, NM BBSOCD 6. State Oil	& Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Na	ime or Unit Agreement Name:	
LIDO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	a ' '	
PHOPOSALS.)		
1. Type of Well: Oil Well Gas Well Other	1	
2. Name of Operator 9. OGRID N	Number	
EOG Resources Inc.	7377 /	
3. Address of Operator 10. Pool na	me or Wildcat	
P.O. Box 2267 Midland, Texas 79702 Eidson; S	trawn, North	
4. Well Location		
Unit Letter V : 660 feet from the South line and 1980 f	eet from the line	
Unit Letter <u>v</u> : 660 feet from the <u>South</u> line and <u>1980</u> f	eet nom the me	
Section 6 Township 16S Range 35E NMPM	County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
4004 GR		
Pit or Below-grade Tank Application or Closure		
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from near	est surface water	
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction Material		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. [PULL OR ALTER CASING MULTIPLE CASING TEST AND [Other Data FREPORT OF: ALTERING CASING PLUG AND ABANDONMENT	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK REMEDIAL WORK COMMENCE DRILLING OPNS. [PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB	F REPORT OF: ALTERING CASING PLUG AND ABANDONMENT	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK REMEDIAL WORK COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB OTHER: Plugback	F REPORT OF: ALTERING CASING PLUG AND ABANDONMENT X	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK REMEDIAL WORK COMMENCE DRILLING OPNS. [PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB	FREPORT OF: ALTERING CASING PLUG AND ABANDONMENT	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. [PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: Plugback 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent day of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore dia or recompletion. 1/29/09 MIRU to plugback to Strawn. POOH w/ 2-7/8" tubing and packer.	FREPORT OF: ALTERING CASING PLUG AND ABANDONMENT	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: Plugback 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent day of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore dia or recompletion. 1/29/09 MIRU to plugback to Strawn. POOH w/ 2-7/8" tubing and packer. RIH w/ bit and scraper. Shut-in. Prep to plugback.	ALTERING CASING PLUG AND ABANDONMENT Tes, including estimated date gram of proposed completion	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: OTHER: Plugback 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent day of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore dia or recompletion. 1/29/09 MIRU to plugback to Strawn. POCH w/ 2-7/8" tubing and packer. RIH w/ bit and scraper. Shut-in. Prep to plugback. 1/30/09 RIH and set CIBP at 12550'. RIH w/ cement bailer and dump 50' cement.	ALTERING CASING PLUG AND ABANDONMENT Tes, including estimated date gram of proposed completion	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: OTHER: Plugback 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent day of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diayor recompletion. 1/29/09 MIRU to plugback to Strawn. POCH w/ 2-7/8" tubing and packer. RIH w/ bit and scraper. Shut-in. Prep to plugback. 1/30/09 RIH and set CIBP at 12550'. RIH w/ cement bailer and dump 50' cement 1/31/09 Perforate from 11634' to 11643', 0.41", 34 holes.	ALTERING CASING PLUG AND ABANDONMENT Tes, including estimated date gram of proposed completion TESP.	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: OTHER: Plugback 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent day of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore dia or recompletion. 1/29/09 MIRU to plugback to Strawn. POCH w/ 2-7/8" tubing and packer. RIH w/ bit and scraper. Shut-in. Prep to plugback. 1/30/09 RIH and set CIBP at 12550'. RIH w/ cement bailer and dump 50' cement.	ALTERING CASING PLUG AND ABANDONMENT Tes, including estimated date gram of proposed completion TESP.	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: OTHER: Plugback 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent day of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diayor recompletion. 1/29/09 MIRU to plugback to Strawn. POCH w/ 2-7/8" tubing and packer. RIH w/ bit and scraper. Shut-in. Prep to plugback. 1/30/09 RIH and set CIBP at 12550'. RIH w/ cement bailer and dump 50' cement 1/31/09 Perforate from 11634' to 11643', 0.41", 34 holes.	ALTERING CASING PLUG AND ABANDONMENT Tes, including estimated date gram of proposed completion TESP.	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent day of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore dia or recompletion. 1/29/09 MIRU to plugback to Strawn. POOH w/ 2-7/8" tubing and packer. RIH w/ bit and scraper. Shut-in. Prep to plugback. 1/30/09 RIH and set CIBP at 12550'. RIH w/ cement bailer and dump 50' cement 1/31/09 Perforate from 11634' to 11643', 0.41", 34 holes. 2/02/09 RIH w/ 2-7/8" workstring and packer set at 11540'. Prep to swab test	ALTERING CASING PLUG AND ABANDONMENT Tes, including estimated date gram of proposed completion TESP.	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS. PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: Plugback 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent details or recompletion. 1/29/09 MIRU to plugback to Strawn. POCH w/ 2-7/8" tubing and packer. RIH w/ bit and scraper. Shut-in. Prep to plugback. 1/30/09 RIH and set CIBP at 12550'. RIH w/ cement bailer and dump 50' cement 1/31/09 Perforate from 11634' to 11643', 0.41", 34 holes. 2/02/09 RIH w/ 2-7/8" workstring and packer set at 11540'. Prep to swab test 2/04/09 Swab	ALTERING CASING PLUG AND ABANDONMENT Tes, including estimated date gram of proposed completion TESP.	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: Plugback 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent day of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore dia or recompletion. 1/29/09 MIRU to plugback to Strawn. POOH w/ 2-7/8" tubing and packer. RIH w/ bit and scraper. Shut-in. Prep to plugback. 1/30/09 RIH and set CIEP at 12550'. RIH w/ cement bailer and dump 50' cement 1/31/09 Perforate from 11634' to 11643', 0.41", 34 holes. 2/02/09 RIH w/ 2-7/8" workstring and packer set at 11540'. Prep to swab test 2/04/09 Swab 2/05/09 Acidized w/ 4000 gals 15% HCL acid & 72 ball sealers. Flowback. Thereby certify that the information above is true and complete to the best of my knowledge and belief.	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT Ets, including estimated date gram of proposed completion Con CIBP. Well.	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT Ets, including estimated date gram of proposed completion Con CIBP. Well.	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS. COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent day of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore dia or recompletion. 1/29/09 MIRU to plugback to Strawn. POOH w/ 2-7/8" tubing and packer. RIH w/ bit and scraper. Shut-in. Prep to plugback. 1/30/09 RIH and set CIBP at 12550'. RIH w/ cement bailer and dump 50' cement 1/31/09 Perforate from 11634' to 11643', 0.41", 34 holes. 2/02/09 RIH w/ 2-7/8" workstring and packer set at 11540'. Prep to swab test 2/04/09 Swab 2/05/09 Acidized w/ 4000 gals 15% HCL acid & 72 ball sealers. Flowback. Thereby certify that the information above is true and complete to the best of my knowledge and belief. grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attack)	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT X tes, including estimated date gram of proposed completion Can CIBP. Well. Gurther certify that any pit or belowhed) alternative OCD-approved plan	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK REMEDIAL WORK PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB PULL OR ALTER CASING MULTIPLE COMPLETION CHARGE PLANS COMMENCE DRILLING OPNS. [OTHER: Plugback] 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent day of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagonary recompletion. 1/29/09 MIRU to plugback to Strawn. POOH w/ 2-7/8" tubing and packer. RIH w/ bit and scraper. Shut-in. Prep to plugback. 1/30/09 RIH and set CIBP at 12550'. RIH w/ cement bailer and dump 50' cement 1/31/09 Perforate from 11634' to 11643', 0.41", 34 holes. 2/02/09 RIH w/ 2-7/8" workstring and packer set at 11540'. Prep to swab test 2/04/09 Swab 2/05/09 Acidized w/ 4000 gals 15% HCL acid & 72 ball sealers. Flowback. I hereby certify that the information above is true and complete to the best of my knowledge and belief. grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attact signature) or print name. Stan Wagner TITLE Regulatory Analyst E-mail address:	TREPORT OF: ALTERING CASING PLUG AND ABANDONMENT ABANDONMENT ABANDONMENT Ites, including estimated date gram of proposed completion Con CIBP. ABANDONMENT Ton CIBP. ABANDONMENT ABANDONMEN	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS. COMMENCE DRILLI	ALTERING CASING PLUG AND ABANDONMENT Les, including estimated date gram of proposed completion Con CTBP. Well. If further certify that any pit or belowhed) alternative OCD-approved plan DATE 2/26/09	

Submit 3 Copies To Appropriate District State of New Mexic		
Office District I Office District I	Resources May 27, 2004	
1625 N French Dr. Hohbs NM 87240	WELL AFTNO.	
District II 1301 W. Grand Ave., Artesia, NM 98AB 0 4 2011 CONSERVATION D	IVISION 5. Indicate Type of Lease	
District III		
1000 Rio Brazos Rd., Aztec, NM 8750 District IV Santa Fe, NM 8750	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State On & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PROPOSALS TO DRIVE OR TO DEEPEN OR PROPOSALS TO DRIVE OR TO DEEPEN OR PROPOSALS TO DEEPEN OR PROPOSALS TO DRIVE OR TO DEEPEN OR PROPOSALS TO DRIVE OR TO DEEPEN OR PROPOSALS TO DEEPEN OR TO DEEPEN O	OR SUCH	
PROPOSALS.)	Bullwinkle 8. Well Number	
1. Type of Well: Oil Well 🕱 Gas Well 🗌 Other	1	
2. Name of Operator	9. OGRID Number	
EOG Resources, Inc.	7377	
3. Address of Operator	10. Pool name or Wildcat	
P.O. Box 2267 Midland, TX 79702	Eidson; Strawn, North	
4. Well Location		
Unit Letter V: 660 feet from the South	line and 1980 feet from the West line	
Section 6 Township 16S Ran		
11. Elevation (Show whether DR,		
Pit or Below-grade Tank Application or Closure	- X	
	Distance from negret surface victor	
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water		
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction Material		
	SUBSEQUENT REPORT OF: MEDIAL WORK ALTERING CASING MMENCE DRILLING OPNS. PLUG AND	
PULL OR ALTER CASING	SING TEST AND ABANDONMENT MENT JOB	
OTUED OT	UED	
	HER: Plugback X	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
2/06/09 Turned to sales.		
2/09/09 POOH w/ 2-7/8" workstring and packer.		
2/10/09 Start in hole w/ 2-7/8" production tubing. Shut down for high winds.		
2/11/09 Finish in hole w/ 2-7/8" production tubing set 2/12/09 RTH w/ rods and pumping assembly. Waiting on		
2/16/09 Start pumping unit and turn to production.	puliping unit installation.	
2720707 Source pumping units out during the productions		
I hereby certify that the information above is true and complete to the best		
grade tank has been/will be constructed or closed according to NMOCD guidelines	, a general permit or an (attached) alternative OCD-approved plan	
	Regulatory Analyst DATE 2/26/09 address:	
Type or print name Stan Wagner Telephone No. 432-686-3689		
For State Use Only	PETROLEUM ENGINEES MAR 1 3 2009	
APPROVED BY TITLE	DATE WAR 1 3 ZOU	