TITLE

DATE

APPROVED BY

Conditions of Approval, if any

Red Tank 30 State #3

DATE REMARKS 3/9/09 MIRU

Nipple down well head, no slips in head - pumping tee setting on flange, OOOLD Equipment.

broke out bull plug on pumping tee (very tight & rusty) lift off flang (no slips) at 2,500# pass couplings,

inspect top joints, set back down.

3/10/09 Replace non working & missingn nipples & valves

NU BOP

pooh w/ 2 7/8" tbg - 3 jts, TAC, 6 jts, seating nipple then two joints & notched collar. (11 jts total)

Rig sand line & sinker bar & tih, found fluid level @ 500', PBTD @ 5,200' Load casing w/ 60 bbls Brine close bope and attempt to pressure up,

attempt to pressure test 5 1/2" production casing - pumped 20 bbls @ 2.5 bpm @100 psi

Load Inermiadate csg w/ 9 bbls fluid & test

Test intermiadiate casing to 500 psi for 30 minutes - Good Test

SION AND LOAD TOOLS

3/11/09 0 PSI

CHANGE PIPE RAMS FROM 2 7/8" TO 2 3/8"

UNLOAD PIPE RACKS AND 162 JTS OF 2 3/8" J-55 TBG

TOOK OFF THREAD PROTECTORS AND TALLY 162 JTS OF 2 3/8" TBG

R.I.H with 4-3/4" bit, pick up 157 jts of 2-3/8 J-55 tbg, tag @ 4,925' -5 jts out on 157th - work through 2

to 4.930'. POOH W/ 157 JTS

R.I.H with 4-3/4" bit, 5-1/2" casing scraper plus 157 jts 2-3/8 J-55blue band tbg to 4,918'.

P.O.H with 2-3/8 J-55 tbg. Lay down 5-1/2 casing scraper and 4-3/4 bit.

R.I.H with 5-1/2 CIBP and 156 jts 2-3/8 tbg.

Set CIBP @4,900' with 156 jts of 2-3/8 J-55 in hole.

SION AND LOAD TOOLS

3/12/09 0 PSI

CIRC 110 BBLS OF PKR FLUID @ 1 1/2 BPM @ 500 PSI GOT BACK 30 BBLS OIL

TEST CIBP @ 500 PSI TEST GOOD BLEED OFF PRESSURE POOH LAYING DOWN TBG LD 156 JTS 2 3/8" J-55 TBG ND BOP, NU B1 FLANGE. LOAD CSG 10 BBLS PKR FLUID

PRESSURE TEST CSG W/ CHART RECORDER 500 PSI FOR 30 MMINS GOOD TEST BLEED OFF

PRESSURE. SION AND LOAD TOOLS

3/13/09 OCD deputy inspector JR Harrison on location, notified 24 hr in advance

Ran Mechanical Integity Test (MIT) - held 500 psi for 30 minutes, good test

Rig down well service unit & move off.

