

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W Grand Ave., Artesia, NM 88201
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
June 19, 2008

OIL CONSERVATION DIVISION
220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

APR 02 2009

HOBBS

WELL API NO. <input checked="" type="checkbox"/> 30-025-06968
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Central Drinkard Unit <input checked="" type="checkbox"/>
8. Well Number 145 <input checked="" type="checkbox"/>
9. OGRID Number 227588 <input checked="" type="checkbox"/>
10. Pool name or Wildcat Drinkard <input checked="" type="checkbox"/>

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☒

2. Name of Operator
Range Operating New Mexico, Inc. ☒

3. Address of Operator
100 Throckmorton St., Ste. 1200, Fort Worth, TX 76102

4. Well Location
Unit Letter I : 1800 feet from the South line and 515 feet from the East line
Section 33 Township 21S Range 37E NMPM Lea County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: Temporarily Abandon ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

3-23-2009 – RU PU. LD PR/LNR w/stuffing box. Unseat pmp. POOH & LD rods and pmp. ND WH. PU on tbg to check for TAC. No TAC. NU BOP. POOH and LD tbg. Closed BOP. SWIFN.

3-24-2009 – RU Halliburton ELU. RIH w/3.868 GR & GR/CCL logging tool to PBTD. Correlated to Gamma Ray/Neutron Log from 3-4-61 and found PBTD @ 6532'. POOH w/GR/CCL logging tools. RBIH w/4 1/2" CIBP. Correlated to log strip and set CIBP @ 6450'. POOH w/setting tool. RBIH w/dump bailer and cumped 36' (4sx) of cmt on top of CIBP. POOH w/dump bailer. RBIH w/another 4 1/2" CIBP. Correlated to log strip and set CIBP @ 5005'. POOH w/setting tools. RDMO Halliburton ELU & PU. RU Parker pmp trk & chart recorder to csg. Load csg w/80 bbls of 2% KCl. Pressure tst csg to 500 psig w/chart recorder for 40 min. Good tst. RDMO Parker pmp trk. Secured WH. SWIFN. Will meet NMOCD in morning at 10:30 am (3-25-09) to tst csg.

3-25-2009 – RU PT and Chart recorder. Pressure tst csg to 500 psi and run MIT tst for 30 min w/chart recorder. Good tst. Released pressure. SWI. RD PT and chart recorder. Tst was witnessed by NMOCD.

CHART ATTACHED.

Spud Date: 2-26-2006

Rig Release Date:

This Approval of Temporary
Abandonment Expires 3-20-14

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Paula Hale TITLE Sr. Reg. Sp. DATE 4-01-2009

Type or print name Paula Hale E-mail address: phale@rangeresources.com PHONE: 817-869-4216

For State Use Only

APPROVED BY: Cam W. Hill TITLE DISTRICT 1 SUPERVISOR DATE APR 06 2009

Conditions of Approval (if any):

