

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
RECEIVED
OIL CONSERVATION DIVISION
APR 09 2009
1220 South St. Francis Dr.
Santa Fe, NM 87505
HOBBSOCD

Form C-103

June 19, 2008

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-08880
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other <input checked="" type="checkbox"/>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator XTO Energy, Inc.		6. State Oil & Gas Lease No.
3. Address of Operator 200 N. Loraine, Ste. 800 Midland, TX 79701		7. Lease Name or Unit Agreement Name: H.T. Mattern NCT E
4. Well Location Unit Letter <u>D</u> : <u>660'</u> feet from the <u>North</u> line and <u>660'</u> feet from the <u>West</u> line Section <u>12</u> Township <u>22S</u> Range <u>36E</u> NMPM County <u>Lea</u>		8. Well Number 3
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number 005380
		10. Pool name or Wildcat Eumont; Yates-7 Rvrs - Queen (Gas)

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTHER: ☐

Approved for plugging or well bore only.
Liability under bond is retained pending receipt
of C-103 (Subsequent Report of Well Plugging)
which may be found at OCD Web Page under
Forms, www.emnrd.state.nm.us/ccd.

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

03/26/09 MIRU P&A Unit. NDWH, NU BOP. Release 6" Lockset pkr & POOH w/2-7/8" J-55 prod tbg.
03/28/09 RU wireline equip. PU & RIH w/BJ 6" CIBP on Baker 20 setting tool & set CIBP @ 2,700'. POOH.
RU pmpg equip & load 6" csg w/72 BBW. RIH w/CBL tool & pull CBL fr 2,700'-surface. RD.
03/31/09 RIH & tag CIBP @ 2,700'. RU & circ TCA w/75 bbls 10# drlg mud. Spot 25 sx class "C" cmt @ 2,700'. PUH. RIH & tag cmt @ 2,390'. OK to proceed by OCD. PUH w/2-7/8" tbg, RU & spot 105 sx class "C" cmt @ 2,125'. PUH.
04/01/09 RIH & tag cmt @ 1,261'. POOH & LD 24 jts of 2-7/8" J-55 prod tbg. EOT @ 525'. Pmp 70 sx C1 "C" cmt, circ 5 sxs to half pit. POOH & LD tbg. ND BOP. Top off 5-1/2" csg w/3 sx cmt. RDMO. Cont'd

Spud Date:

03/26/09

Rig Release Date:

04/01/09

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kristy Ward TITLE Regulatory Analyst DATE 04/7/09
Type or print name Kristy Ward E-mail address: kristy_ward@xtoenergy.com PHONE 432-620-6740

For State Use Only

APPROVED BY [Signature] TITLE DISTRICT 1 SUPERVISOR DATE APR 13 2009
Conditions of Approval (if any):

H T Mattern NCT E #3
Plug & Abandonment
Cont'd.

04/02/09 Dig out wellhead. Check LEL's, fill out hot work permit & cut off wellheads. Install dry hole marker. Dig out anchors & cut off. Well is P&A'd.