Submit 3 Copies To Appropriate District	State of New M	lexico		Form C-103
Office District I	Energy, Minerals and Natural Resources		May 27, 2004	
District II 1625 N. French Dr., Hobbs, NM 88870 District II 1301 W. Grand Ave., Artesia, NM 88210 District III 1220 South St. Francis Dr.			WELL API NO.	
District II 1301 W. Grand Ave., Artesia, NM 88210		N DIVISION	30-025-35497 5. Indicate Type of Lease	
District III 1000 Rio Brazos Rd., Aztec, NM 8741 APR 08 2009 1220 South St. Francis Dr. Santa Fe, NM 87505		ancis Dr.	STATE STATE	
			State Oil & Gas Lease No	·.
1220 S. St. Francis Dr., Santa Fe, NHOBE 87505	ISOCD			
SUNDRY NOTICES AND REPORTS ON WELLS			Lease Name or Unit Agre	ement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			TEXACO 5 STATE \checkmark	
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				7
1. Type of Well: Oil Well Gas Well Other		8.	8. Well Number	
2. Name of Operator		9.	OGRID Number	
DEVON ENERGY PRODUCTION COMPANY, LP			6137	
3. Address of Operator			10. Pool name or Wildcat	
20 North Broadway, Ste 1500, Okla	homa City, OK 73102	405-552-4615	Vacuum Atoka-Morro	w, North
4. Well Location				
Unit Letter P: 6	560'feet from the SOUTH	H line and _660'fe		_line
Section 5	• · · · · · · · · · · · · · · · ·	Range 35E	NMPM Count	ty LEA
	11. Elevation (Show whether D	R, RKB, RT, GR, etc.)		
Pit or Below-grade Tank Application or C	3987' GL			
	rDistance from nearest fresh	water well Distance	from nearest surface water	
Pit Liner Thickness: mil	Below-Grade Tank: Volume		uction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INT	ENTION TO:	SUBSE	QUENT REPORT C	۶F: ۲
	PLUG AND ABANDON	REMEDIAL WORK		G CASING 🔲
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLIN	NG OPNS. 🗌 🛛 P AND A	\boxtimes
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT JC	B 🗌	
OTHER:		OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion				
or recompletion.				
1. 3/10/09—MIRU. POOH w/	rod string nump and 2-3/8"	production tubing		
 3/10/09—MIRU. POOH w/rod string, pump, and 2-3/8" production tubing. Set CIBP @ 12140'. Dump 40' cement on top. Circulate wellbore w/10 ppg mud. 				
3. Spot 25 sx cement @ 9787' – 9990'. (top of Wolfcamp @ 9990')				
4. Spot 25 sx cement @ 6798' – 7050'.				
 Fulled stretch, casing free @ 5900'. Cut 5-1/2" casing off @ 5900'. POOH and lay down casing. Spot 30 sx cement stub plug @ 5793' – 5950' Tagged. 				
	ig @ 5793 – 5950 Tagged. 3' - 4674'. Tagged. 8-5/8" ca		Approved for plugging of we	fl bo e only.
8. Spot 30 sx cement @ 3035			Liability under bond is retain	
9. Spot 30 sx cement @ 1905			of C-103 (Subsequent Report which may be found at OCD	
10. Spot 30 sx cement @ 420'			Forms, www.cmnrd.state.nm.	
11. Spot 30 sx cement @ surfa	ace to 120'.	-		<u> </u>
12. 4/3/09—Cut wellhead off, s	et dry hole marker, clean loc	cation. Plugged & Abar	ndoned.	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-				
grade tank has been/will be constructed or closed according to NMOCD guidelines 🗌, a general permit 🗍 or an (attached) alternative OCD-approved plan 🗍.				
SIGNATURE Romme S	ach	Engineering Technic	cianDATE	_4/6/09
Type or print nameRonnie SlackFor State Use Only	E-mail address:	Ronnie.Slack@dvn.com	-	-552-4615
	/I'M	DISTRICT 1 SUP	ERVISOR A	MK 1 3 2009
APPROVED BY: <u>(in any)</u> :	Title		DATE	

,

۰.

; • • •

