

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-005-21160
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Chevron USA Inc.		6. State Oil & Gas Lease No.
3. Address of Operator 15 Smith Rd, Midland, Tx. 79705		7. Lease Name or Unit Agreement Name: Dulce 36 State Com
4. Well Location Unit Letter <u>F</u> : 1980' feet from the <u>North</u> line and 1980' feet from the <u>West</u> line Section <u>36</u> Township <u>15-S</u> Range <u>31-E</u> NMPM Chaves County		8. Well No. 1
10. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. Pool name or Wildcat Wildcat Morrow Gas


11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐ surface restoration is completed. Liability under bond is retained until ☐
OTHER: ☐ Approved as to plugging of the Well Bore

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. MI & RU Plugging Equipment. 10-29-03
2. Set 5½ CIBP @12,450'. Spot 30sx Class H Cmt @12,450'. 10-31-03. Tag TOC @12,209'. 11-03-03.
3. Circulate 270 BBL MLF 12,209'- Surface. 11-03-03. Spot 25sx Class H Cmt 9000-8800. 11-03-03.
4. Spot 25sx Class C Cmt 6900'-6700' In 5½ Csg.
5. Spot 25sx Class C Cmt 5600'-5400' In 5½ Csg.
6. Perf. w/4 shot Gun @ 4550'. Spot 50sx Class C Cmt @4600'. Tag TOC @4125'. 11-04-03
7. Cut 5½ Csg @ 2550'. Couldn't Pull. Spot 40sx Class C Cmt @2600'. Tag TOC @2247'. 11-05-03.
8. Cut 5½ Csg @ 1800'. Spot 45sx Class C Cmt @1900'. 11-05-03. Tag TOC @1689'. 11-06-03.
9. Spot 80sx Class C Cmt @900'. Tag TOC @693'. 11-06-03.
10. Spot 40sx Class C Cmt @400'-300' In 9 5/8 Csg. 11-06-03.
11. Circulate 25sx Class C Cmt 50'- Surface In 9 5/8 Csg. 11-06-03
12. Install Dry Hole Marker. P & A Complete 11-07-03.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jimmy Bagley TITLE MANAGER/SUNSET DATE 11-07-03

Type or print name Jimmy Bagley Telephone No. 432 561-8600
(This space for State use)

APPROVED BY Chris Williams TITLE OC DISTRICT SUPERVISOR/GENERAL MANAGER DATE 11-12-03

Conditions of approval, if any: