Submit 3 Copies To Appropriate District	State of New M	exico	Form C-103 May 27, 2004		
	District I 625 N. French Dr., Hobbs, NM-88246 CEIVED				
1625 N. French Dr, Hobbs, NM <sup>2</sup> 88240 Stars &					
District II 1301 W Grand Ave., Artesia, NM 8APR 17 2009 District III 1000 Rio Brazos Rd, Aztec, NM 87408 BSSOCI District IV 1220 S. St Francis Dr, Santa Fe, NM 87505 1220 S. St Francis Dr, Santa Fe, NM 87505			30-025-34761 / 5. Indicate Type of Lease		
			STATE STATE		
			6. State Oil & Gas Lease No. V-7020-1		
	AND REPORTS ON WE		7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			STATE 11		
PROPOSALS.)			8. Well Number 1		
1. Type of Well: Oil Well     Gas Well     Other SWD       2. Name of Operator     (			9. OGRID Number 024010		
V-F PETROLEUM INC.			9. OGRID Number 024010 V		
3. Address of Operator			10. Pool name or Wildcat		
P.O. BOX 1889, MIDLAND, TEXAS 79	9702		WEST MIDWAY – UPPER PENN		
4. Well Location					
Unit Letter <u>M</u> : <u>660</u> feet from the <u>SOUTH</u> line and <u>660</u> feet from the <u>WEST</u> line $\checkmark$					
Section 11 Township 17-S Range 35-E NMPM LEA County					
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,942' GR			C.)		
Pit or Below-grade Tank Application  or Closure					
	Distance from nearest fresh w	ater well Dist	ance from nearest surface water		
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction Material					
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING					
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR					
	JLTIPLE COMPL		CASING/CEMENT JOB		
OTHER:       RE-ENTRY       OTHER:         13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of					
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.					
02/16/09 – 02/23/09 Building road/location/install cattle guards.					
02/24/09 MI roustabout crew & welder. Cut off 13 3/8" surf csg. Install 13 3/8" x 8 5/8" WH. Weld onto 8 5/8"					
csg. Install 8 5/8" x 10' 900 series WH. Nipple up BOP. Move in & set reverse unit, cuttings tank. MI & rack					
11,500' 2 7/8" tbg.					
02/25/09 Clean and inspect threads on working tubing string.					
02/26/09 MIRU Basic WSU. TIH w/7 7/8", bit sub 10 4 1/8" drill clrs + 2 7/8" 8.7# PH6 tbg. Tag top of cmt at					
334'. RU power swivel. Drl cmt to 417'.					
02/27/09 Drl cmt to 1,507'.					
02/28/09 Drl cmt to 1,635'.	CONTENT				
	CONTINUI	ED ON BACK			
			belief. I further certify that any pit or below-		
grade tank has been/will be constructed o OCD-approved plan $\Box_7$	r closed according to NMOCI	) guidelines □, a g	eneral permit 🗌 or an (attached) alternative		
SIGNATURE Mane	Luna TITLE	Production 5	perintendent DATE 04/13/09		
Type or print name	E-mail address:		Telephone No. (432) 683-3344		
(This space for State use)					
APPPROVED BY	TITLE PE	TROLEUM ENGI	NECK DATE APR 1 7 2009		
Conditions of approval, if any:					
11					

03/01/09 Drlg cmt to 1,730', drilling through 12 midnight on February 28, 2009. Cont drlg. 03/02/09 Drlg cmt to 1,743'.

03/03/09 TOH. TIH w/7 7/8" bit. Drl cmt to 3,145'.

03/04/09 Drl cmt to 4,566'. TOH. LD 4 1/4" drl clrs & 7 7/8" bit.

03/05/09 TIH w/4 <sup>3</sup>/<sub>4</sub>" bit & 6 3 <sup>1</sup>/<sub>2</sub>" drl clrs. Drill inside 5 <sup>1</sup>/<sub>2</sub>" csg to 4,575'. TOH.

03/06/09 TIH w/4 <sup>3</sup>/<sub>4</sub>" concave mill. Mill on junk.

03/07/09 Mill on junk and cmt to 4,579'. TOH. TIH w/4 <sup>3</sup>/<sub>4</sub>" mill. Mill on junk & cmt to 4,600'.

03/10/09 Mill on junk & cmt to 4,850'. TOH. TIH w/4 <sup>3</sup>/<sub>4</sub>" bit. Drill trash & cmt.

03/11/09 Drl cmt to 6,650'. Test csg to 1,000#. No leak. Drl cmt to 6,670'.

03/12/09 Push CIBP to 7,350'. TOH. TIH w/drillable cmt retainer. Position cmt retainer at 6,650'.

03/13/09 Squeeze Blineberry perforations at 6,736' – 7,318' with 200 sxs Class "C" plus fluid lose additives followed by 150 sxs Class "C" net cmt. Attained 4,000# standing squeeze pressure.

03/14 - 16/09 SD WOC.

03/17 - 19/09 Drl cmt & retainer. Fall thru cmt @ 7,250'. Test csg to 1,600# for 15 min. No leak. Set pkr @ 6,650'. Press test pkr & csg to 1,000#. Swb well

03/21/09 Set retainer. Press test tbg to 5,000#. Press test csg to 1,000#. Get injection rate on perf 0.75 bbls per min @ 4,300#. Mix & spot 100 sxs Class "H" cmt w/water loss additives plus 25 sxs Class "H" neat cmt to within 10 bbls of cmt retainer. Squeeze perf to 5,000# walking squeeze.

03/22 - 24/09. WOC.

03/24 – 26/09 Drill cmt retainer & cmt to 7,580'. Press test csg to 1,000#, 15 min. No leak. Drill CIBP and push to 11,200'.

03/27 - 28 /09 Run GR-CBL-CCL log. TOC @ 9,000'. Perf Cisco zone 11,108'to 11,120' OA w/1 deep pen JSPF 03/29–30/09 SDFW.

03/31 - 04/01/09 Swb well, recvd wtr. Break dwn Cisco perf w/500 gallons 15% NeFe HCl acid. Pmp acid & ball job w/1,500 gallons as acid as above plus 40 ball sealers. Swb well 7 hrs. Swb well, recvd wtr.

04/02 - 04/03/09 Swb well, recvd wtr. Had trace of oil throughout day.

04/04/09 Perf 11,051' - 11,056'- 11,077' OA w/1 deep pen JSPF

04/05/09-06/09 SDFW.

04/07/09 Spot 500 gallons 15% NeFe HCl acid over perf 11,051'-11,077'OA.

04/08 - 09/09 Swb well, recvd wtr. Trace of oil.

04/10/09 Perf 10,976'-11,018' (OA) w/1 dp pen JSPF (11 holes). Rec 58 bbls wtr

South and the second se

04/11- 13/09 SDF holiday.

11 £17 1 1 1.