RECEIVED

Form 3160-5 (September 200 1)

UNITED STATES DEPARTMENT OF THE INTERIOR


APR 23 2009

FORM APPROVED OMB No 1004-0135 Expires January 31, 200

	BUREAU OF LAND MANA	AGEMENT	HOF	BSOCD	5 Lease Serial No
SUNDRY NOTICES AND REPORTS ON WELLS					NMLC-032651D
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				6 If Indian, Allottee or Tribe Name	
abalidoned we	sii. Ose i oliii s loo-s (Al L	o) ioi sacii pi	oposais.		
SUBMIT IN TRIPLICATE - Other instructions on reverse side					7 If Unit or CA/Agreement, Name and/or No
1 - 1,- 1 %-11					
Oil Well 🛛 Gas Well 🖵 Other					8 Well Name and No
2. Name of Operator					Ascarte D-24 #1
Herman L. Loeb					9 API Well No
3a. Address 3b. Phone No (incl				ea code)	30-025-09794
P O Box 524, Lawrenceville, IL 62439 (618) 943-222					I 0 Field and Pool, or Exploratory Area
4 Location of Well (Footage, Sec., T, R., M. or Survey Description)					Cooper Jal (Tansil, Yates, Seven Rivers)
					I 1 County or Parish, State
1980' FSL 1980' FEL Section 24-25S-R36E					Lea County, NM
12. CHECK AP	PROPRIATE BOX(ES) To	O INDICATE	NATURE	OF NOTICE, R	EPORT, OR OTHER DATA
TYPE OF SUBMISSION		,	TYPE	OF ACTION	
	Acidize	Deepen Deepen		Production (Start	/Resume) Water Shut-Off
Notice of Intent	l	Fracture T	_	Reclamation	Well Integrity
Notice of Intent	☐ Alter Casing	_	_	_	
Subsequent Report	Casing Repair	☐ New Cons	_	Recomplete	Other
	Change Plans	Plug and A	-	Temporarily Ab	andon
Final Abandonment Notice	Convert to Injection	Plug Back	Ļ	Water Disposal	
determined that the site is ready	for final inspection.)	٠		*	mation, have been completed, and the operator has
1. RIH w/ tubing to 2,850'. C	Cap w/ adequate cement to:	fill from 2,850)' to 2,500' ((covers CIBP & 1	pase of salt)
			CH C	1.05014- 1.04)()((
2. Perforate the 7" casing @ WOC and tag no lower tha	1250'. Attempt to squeeze in 1,000'	adequate ceme	ent to fill fr	om 1,250 to 1,00	ou (covers snoe & top of sait).
3. Perforate the 7" casing @ 3	330'. Attempt to circulate c	ement to surfa	ce in/out o	f 7" casing.	
4. Cut off the well head 3' be	elow ground level, cap off a	all annulus fro	m 50' to sur	rface. SI	EE ATTACHED FOR
Note: There is a CIBP @ 2,85	50' set on 3/15/88 (see sund	dry notice of 3	/30/88).		ONDITIONS OF APPROVAL
BLM Bond # NM-2839	•				
14. 1 hereby certify that the foregoin	ng is true and correct				
Name (PrintedlTyped)					
G. A. Payne				oleum Engineer	
Signature			Date 4/15/	/09	APPROVED
	THIS SPACE	FOR FEDERA	L OR STA	TE OFFICE USE	
Approved by	·		PETRO	LEUM ENGIN	Date APR 1 6 2009
Conditions of approval, if any, are	e attached. Approval of this noti	ce does not warr		1	
certify that the applicant holds leg	gal or equitable title to those rig	hts in the subject	lease Offic	e Ky	

Titles land lanse, including of trabanch Title 43 his or representations as make it a crime for a language by and willfully to make

ASCARTE D 24 #1 30-025-09794



BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

- 2 <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed prior to commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in a cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

- 6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation (Interim/Final) Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- 1. The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation

equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Environmental Protection Specialist 575-234-5909, 575-361-2648 (Cell)

Terry Gregston Environmental Protection Specialist 575-234-5958

Bobby Ballard Environmental Protection Specialist 575-234-2230

Randy Rust Environmental Protection Specialist 575-234-5943

Linda Denniston Environmental Protection Specialist 575-234-5974

Jennifer Van Curen Environmental Protection Specialist 575-234-5905

Justin Frye Environmental Protection Specialist 575-234-5922 Cody Layton Natural Resource Specialist 575-234-5959

Trishia Bad Bear Natural Resource Specialist 575-393-3612

Todd Suter Surface Protection Specialist 575-234-5987

Doug Hoag Civil Engineering Technician 575-234-5979