Submit 3 Copies To Appropriate District Sta	Copies To Appropriate District State of New Mexico		Form C-103	
Office District I 1625 N. French Dr., Hobbs, NM 88240 District II			WELL API NO. June 19,	2008
District II 1301 W. Grand Ave., Artesia, NM 882 APR 2 4 QMIL CONSERVATION DIVISION			30-005-20826 5. Indicate Type of Lease	
District III 1220 South St. Francis Dr.			STATE 🛛 FEE 🗌	
District IV Santa Fe, NM 87505 1220 S. St. Francis Dr., Santa Fe, NM 87505			6. State Oil & Gas Lease No. LG-2426	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Na	me
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			Loveless LQ State	
1. Type of Well: Oil Well Gas Well Other SWH			8. Well Number	
2. Name of Operator Enervest Operating, L.L.C.			9. OGRID Number 143199	
3. Address of Operator			10. Pool name or Wildcat	
1001 Fannin Street, Suite 800 Houston, Tx 77002 Attn: S. Galik			Tomahawk San Andres	
4. Well Location Unit Letter E: 1980 feet from the North line and 660 feet from the West line				
	ship 7S	Range 31E	NMPM Chaves County	
		RKB, RT, GR, etc.)		
4383' GR				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUB			SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WOR				= =
TEMPORARILY ABANDON ⊠ CHANGE PLANS ☐ COMMENCE DR				
PULL OR ALTER CASING ☐ MULTIPLE COM DOWNHOLE COMMINGLE ☐	IPL 🗌	CASING/CEMENT	JOB []	
_	_			_
OTHER: 13 Describe proposed or completed operations (Clearly state all r	OTHER:	l give pertinent dates including estimate	d date
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
Contact NMOCD District Office – Hobbs at (575) 393-6161 Ext. 123 to schedule and witness a MIT Test.				
Preparing to TA the well. RIH and POOH rods and tubing.				
8-5/8" 23# K-55 @ 1698' and 4-1/2" 9.5# J-55 @ 4195'				
RU Wireline. Set CIBP @ 4084' and dump 40' of cmt on top. (Perfs 4134 – 4143)				
Call NMOCD to witness chart-recorded MIT to 500#				
Condition of Approval : Notify OCD Hobbs office 24 hours prior to running MIT Test & Chart				
Saud Data: 9/18/1981		10/0	02/1981	
Spud Date:	Rig Release Da	te:	72/1701	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
Sr. Regulatory Tech 4/22/2009				
SIGNATURE YHUULU Shirlay Galil	_TITLE	Sgalik@enervest.net DATE (713) 495-1514		
Type or print name	_ E-mail address		PHONE:	
E. Certe H. Oulu				
APPROVED BY: Approval (if ally): DISTRICT 1 SUPERVISOR DATE APR 2 7 2009				