Submit One Copy To Appropriate District Office District Linergy, Minerals and Natural Resources 1625 N. French Dr. Hobbs NM 88240	Form C-103
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Q 2000	WELL API NO. /
District II 1301 W Grand Ave Artesia NM 88210 OIL CONSERVATION DIVISION	30-025-20919
District III 1301 W. Grand Ave., Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 8/410 District IV Santa Fe, NM 8/505	5. Indicate Type of Lease
1000 Rio Biazos Rd., Aziec, Nivi 87410 Sonto E.a. NIM 97505	STATE FEE X 6. State Oil & Gas Lease No.
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Off & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	Dollie Ballenger /
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	8. Well Number #2
1. Type of Well: X Oil Well Gas Well Other	
2. Name of Operator	9. OGRID Number
Chevron USA Inc. 3. Address of Operator	4323
15 Smith Road, Midland, Texas 79705	Brunson Drinkard - Abo, South
4. Well Location	/
Unit Letter L: 1980 feet from the South line and 660 feet from the West line	e 🗸
Section 17 Township 22S Range 38E NMPM County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
TEMPORARILY ABANDON	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	T JOB
OTHER:	
X All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.	
X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
X A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT	
LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY	
STAMPED ON THE MARKER'S SURFACE.	
X The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other	
production equipment.	
X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
X If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from	
lease and well location.	
X All metal bolts and other materials have been removed. Portable bases have been removed.	red. (Poured onsite concrete bases do not have to
be removed.)	out (1 out of other control of out of have to
X All other environmental concerns have been addressed as per OCD rules.	
X Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved	
flow lines and pipelines. When all work has been completed, return this form to the appropriate District office to scho	adula a chi
work has occar completed, return hims form to the appropriate District office to sen	edule an inspection.
SIGNATURE TITLE Production Team L	eaderDATE04-21-2009
TYPE OR PRINT NAMEE-MAIL:	PHONE:
For State Use Only	
APPROVED BY: Wash Charles TITLE Why. Of. Conditions of Approval (if any):	DATE 04-24-2009
· · · · · · · · · · · · · · · · · ·	