Submit One Copy To Appropriate District Office District I  State of New Mexico Energy, Minerals and Natural Resources	Form C-103
District I Energy, Minerals and Natural Resources	March 18, 2009
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-025-32624
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION  District III 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe NM 87505	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505	STATE FEE X  6. State Oil & Gas Lease No.
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	William Weir  8. Well Number #6
PROPOSALS.)  1. Type of Well: Oil Well X Gas Well Other	o. Well ivalided #0
2. Name of Operator	9. OGRID Number
Chevron USA Inc.	9. OGRID Nullioei
3. Address of Operator	10. Pool name or Wildcat
15 Smith Road, Midland, Texas 79705	Monument - Abo
4. Well Location	/
Unit Letter N: 425 feet from the South line and 1830 feet from the West line	
Section 23 Township 19S Range 36E NMPM County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.,	
12. Chook Appropriate Doy to Indicate Nature of Nation Doy to Od. T	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING	
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A ☐	
PULL OR ALTER CASING  MULTIPLE COMPL  CASING/CEMENT JOB	
OTHER:     Description   Location is ready for OCD inspection after P&A	
X All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan	
X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
X A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT	
LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY	
STAMPED ON THE MARKER'S SURFACE.	
V. The leastion has been leveled as well as a second secon	
X The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.	
X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
X If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD	
rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from	
lease and well location.	
X All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to	
be removed.)	
X All other environmental concerns have been addressed as per OCD rules.	
X Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
	value un mapoemon.
SIGNATURE TITLE Production Team Le	eaderDATE04-21-2009
For State Use Only	PHONE:
	1 .
APPROVED BY: Wash Whatah TITLE COMP. Office	er DATE 04-29-09
Conditions of Approval (if any):	