Submit 3 Copies To Appropriate District	State of New Me	xico	20,000000000	Form C-103
Office District I 1625 N. French Dr., Hobbs, NM 88245 C C CONCERNY A THOMAD PRIVISION IN CONCERNY A THOMAD PRIVINCE A THOMAD PRIVISION IN CONCERNY A THOMAD PRIVINCE A THO			30.005.30833 WELL API NO.	June 19, 2008
District II OIL CONSEDVATION DIVISION			30-005-20883	
District II 1301 W. Grand Ave., Artesia, NM \$8310 U 1 2009 1220 South St. Francis Dr.			5. Indicate Type of Lease	
1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87505 Santa Fe, NM 87505			STATE STATE 6. State Oil & Gas Lease N	FEE L
1220 S. St. Francis Dr., Santa Fe, NM 87505			LG-2426	
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Ag	reement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			I amalana I O Ctata	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other SWE			Loveless LQ State 8. Well Number	
			8	
2. Name of Operator Enervest Operating, L.L.C.			9. OGRID Number 1	43199
3. Address of Operator			10. Pool name or Wildcat	
	ouston, Tx 77002 Attn:	S. Galik	Tomahawk San Andres	V
4. Well Location Unit Letter N: 330 feet from the South line and 2310 feet from the West line				
Unit Letter N: 330 1 Section 36	feet from the South line Township 7S	and 2310 Range 31E	feet from the West NMPM Chaves	County line
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
4414.7' GR				
12 Charle Apr	propriate Box to Indicate Na	otura of Notice	Panart or Other Data	
• •	-		•	v
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK TEMPORARILY ABANDON ☒ CHANGE PLANS ☐ COMMENCE DRILL				NG CASING 🗌
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRIL PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐ CASING/CEMENT				` ⊔
DOWNHOLE COMMINGLE			_	
OTHER:	П	OTHER: TA		⊠
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
Contact NMOCD District Office - Hobbs at (575) 393-6161 Ext. 123 to schedule and witness a MIT Test.				
4/24/09 RIH and POOH rods and tubing.				
RU Wireline. Set CIBP @ 3904' and dump 40' of cmt on top. (Perfs 3954 - 4168)				
Load and test casing to 500 psi for 30 min good test. Witnessed by Robert Harrison, NMOCD				
Enervest Operating, L.L.C. respectfully request that this well be placed on TA status.				
			oorani	
	Inis Ap	proval of Temp Inment Expires	5-1-2014	
Spud Date: 11/26/1981	Rig Release Da	10/2	30/1981	
				· · · · · · · · · · · · · · · · · · ·
I hereby certify that the information abo	ve is true and complete to the be	est of my knowledge	e and belief.	
Shirley o	\mathcal{M}_{1}, b	Sr. Regulatory Tech		9
SIGNATURE Shirlay Calil	TITLE	Sgalik@enervest	DATE	13) 495-1514
Type or print name	E-mail address	:	PHONE:	
For State Use Only		TO 10 10 10 10 10 10 10 10 10 10 10 10 10		_
APPROVED BY:	TITLE DIST	PUCT 1 SUPER	rvi sor _{date} M	AY 0 1 2009
Conditions of Approval (if any):			-	

