	TARATCO		rvation Diven	un, l'alorsol 1
Form 3160-5 UNITEDSTATES IG25 N. F (RECEIVED DEPARTMENT OF THE INTERIORDES, 1625 N. F			French Drive NM 88240	FORMAPPROVED OM B No 1004-0137 Expires: March 31, 2007
	BUREAU OF LAND MANAGEN	SUREAU OF LAND MANAGEMENT		5. Lease Serial No.
APR 28 2411 NDRY	NOTICES AND REPORT	S ON WE	15	NM 080128
HOBB abandoned w	his form for proposals to dril ell. Use Form 3160-3 (APD)	l or to re-e for such pro	nter an posals.	6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No
1 Type of Well				ĵ
Gas Well Sas Well Store			8. Well Name and No	
2. Nameof Operator CELERO ENERGY II, LP				Wakan Tanka Federal #4 9. API Well No.
3a. Address 3b. PhoneNo. (include area code)			30-005-21092	
400 W. Illinois, Ste. 1601 Midland TX 79701 (432)686-1883				10. Field and Pool, or Exploratory Area SU
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				Gaprock; Queen
2080 South 990 West UL: L, Sec: 27, T: 13S, R: 31E				11 County or Parish, State Chaves
				NM
12. CHECK A	PPROPRIATE BOX(ES)TO INDI	CATE NATUR	E OF NOTICE, R	EPORT, OR OTHER DATA
TYPE OF SUBMISSION				
	Acidize De	epen	Production (Sta	rt/Resume) 🔲 Water Shut-Off
Notice of Intent		actureTreat	Reclamation	X Well Integrity
X Subsequent Report	Casing Repair Ne	w Construction	Recomplete	X OtherC/O to PBTD
	Change Plans Plu	gand Abandon	TemporarilyAb	andon
Final Abandonment Notice	Convert to Injection	ıgBack	Water Disposal	·
CaC12 & displaced at 2 & held okay. Mix cmt at & installed 4 ½" x 2000# wiper rubber, float collar Circ hole clean. Pulled Arrowset nickel plated p nipple) & circulate pkr flittension on pkr. Treated flushed w/57 BFW, 44 b 1060#, 5 mins = 660#, 2	BPM w/1400# pressure before t 14.8 ppg w/yield of 1.32. Ci screw type WH. PU 3 3/8" r (2864'), shoe jt, guide shoe and LD work string w/bit. TI okr. Tested tbg w/5000# press uid (used 1 gal per 10 BFW). I down tbg into 5 ½" perforation bobs overflush. Treating press 10 mins = 500# & 15 mins = 3	bre bumping rc 25 sx of c bit & RIH on (2809"), con H <u>w/87 its of</u> sure. <u>Set p</u> Latched ba ons 2864-76 sures: Max 370#	plug. Bumped p mt to pit. After 2 3/8" OD tbg w posite bridge p 2 3/8" OD IPC (r @ 2773'. Ref ck onto pkr. NE w/200 gals of X = 1430#, Avg -	x & pump 120 sx of class C cmt w/29 plug w/2000# pressure. Checked flow WOC 16 ½ hrs, set slips, cut off casin vork string. Tagged @ 2861'. DO lug @ 2810' & ran bit to 2896' (PBTD tbg w/turned down collars & 4" eased from on-off tool (1.50" profile DBOP & NUWH. Pulled 20 jts of Kylene, 1000 gals of 15% NEFE acid 1260#, Avg Rate = 4.0 BPM ISIP =
	CD-Hobbs w/sundry. A copy			Sull - 4 -
14. I hereby certify that the fore		no allacheu		
Name (Printed/Typed) Lisa Hunt		Title	Regulatory Anal	lvst
Signature Lusa	Hunt		04/06/2009	<u>,,,,</u>
	FUR BEORE FOR FEDE	RAL OR S	TATE OFFICE	USE
Approved by /S/DA Conditions of approval, if any pare certify that the applicant holds legs which would entitle the applicant	VID.R. GLASS attacheon worrow of this notice does no al or equitable title to those rights in the s	ot warrant or ubject lease	Accepted Fo Subject To Injection A Injection 0	r Record Only! Approval Returning Well To Continuous nd Keeping Well On Continuou: r Plugging Well With An ugging Program!
(Instructions on page 2)				· · · · · · · ·



BECEINED

00:8 HA 8-994 6003

BUREAU OF LAND MGMT

Representation - For C=1+Ro Encontra For C=1, Ro Encontra For C= P.