Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103
Office . ~~ District I	Energy, Minerals and Natural Reso	May 27, 2004
1625 N. French Dr , Hobbs, NM 88240		WELL API NO. 30-025-29569
<u>District II</u> 1301 W Grand Ave, Artesia, NM 88210	OIL CONSERVATION DIVIS	ON 5. Indicate Type of Lease FEDERAL
District III	1220 South St. Francis Dr.	STATE FEE
1000 Rio Brazos Rd , Aztec, NM 87410 District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S St Francis Dr, Santa Fe, NM		LG-3345
SUNDRY NOTICE	ES AND REPORTS ON WELLS ALS TO DRILL OR TO DEEPEN OR PLUG BACK	7. Lease Name or Unit Agreement Name SANMAL QUEEN UNIT
DIFFERENT RESERVOIR USE "APPLICA	TION FOR PERMIT" (FORM C-101) FOR SUCH	8. Well Number
PROPOSALS.)		005
1. Type of Well: Oil Well G	ias Well 🔯 Other INJECTION	9. OGRID Number
2. Name of Operator SMITH & MARRS, INC.		020080
3. Address of Operator		10. Pool name or Wildcat Sarmal, Wr
P.O. BOX 863 KERMIT, TX 79745		VACUUM; WOLFCAMP, NORTHWEST-
4. Well Location		/
	feet from the SOUTH line and990_f	eet from the EAST line
Section 1 Township 17S_1		nty LEA, NM
Section 1 Township 175	11. Elevation (Show whether DR, RKB, R.	
Pit or Below-grade Tank Application or		
Pit typeDepth to Groundwate	erDistance from nearest fresh water well_	Distance from nearest surface water
Pit Liner Thickness: mil	Below-Grade Tank: Volume	bbls; Construction Material
	ppropriate Box to Indicate Nature of	Notice. Report or Other Data
12. CHECK A	ppropriate Box to maleute reaction	
NOTICE OF INT		SUBSEQUENT REPORT OF:
· =· · · · · · · · · · · · · · · · · ·		DIAL WORK ALTERING CASING
	=	ENCE DRILLING OPNS. P AND A
PULL OR ALTER CASING	MULTIPLE COMPL   CASIN	G/CEMENT JOB
PULL OR ALTER CASING []		
		e:
OTHER:	OTHER	details, and give pertinent dates, including estimated date
OTHER:	OTHER	details, and give pertinent dates, including estimated date etions: Attach wellbore diagram of proposed completion
OTHER:  13. Describe prop osed or complete of starting any proposed work or recompletion.	OTHER	details, and give pertinent dates, including estimated date
OTHER:  13. Describe prop osed or comple of starting any proposed work	OTHER	details, and give pertinent dates, including estimated date
OTHER:  13. Describe prop osed or complete of starting any proposed work or recompletion.  Hole in casing @ 560' Pump 290 sx @ 560' – would not	OTHER	details, and give pertinent dates, including estimated date etions: Attach wellbore diagram of proposed completion
OTHER:  13. Describe prop osed or complet of starting any proposed work or recompletion.  Hole in casing @ 560'	OTHER	details, and give pertinent dates, including estimated date
OTHER:  13. Describe prop osed or complete of starting any proposed work or recompletion.  Hole in casing @ 560' Pump 290 sx @ 560' – would not Circulate plugging mud	OTHER	details, and give pertinent dates, including estimated date etions: Attach wellbore diagram of proposed completion
OTHER:  13. Describe prop osed or complete of starting any proposed work or recompletion.  Hole in casing @ 560' Pump 290 sx @ 560' – would not Circulate plugging mud  4/2/09 set cibp @ 3750'	OTHEF eted operations. (Clearly state all pertinent k). SEE RULE 1103. For Multiple Comp	details, and give pertinent dates, including estimated date etions: Attach wellbore diagram of proposed completion  RECEIVED  MAY 1.3 2009
OTHER:  13. Describe prop osed or complete of starting any proposed work or recompletion.  Hole in casing @ 560' Pump 290 sx @ 560' – would not Circulate plugging mud  4/2/09 set cibp @ 3750' 4/16/09 spot 30 sx @ 3750' – spot 30 sx @ 3750'	OTHER eted operations. (Clearly state all pertinent k). SEE RULE 1103. For Multiple Composit hold	details, and give pertinent dates, including estimated date etions: Attach wellbore diagram of proposed completion  RECEIVED  MAY 13 2009
OTHER:  13. Describe prop osed or completed of starting any proposed work or recompletion.  Hole in casing @ 560', Pump 290 sx @ 560' – would not Circulate plugging mud  4/2/09 set cibp @ 3750', 4/16/09 spot 30 sx @ 3750', – spot 4/17/09 spot 70 sx @ 1516' tag @	OTHER  eted operations. (Clearly state all pertinent k). SEE RULE 1103. For Multiple Comp  t hold  ot 40 sx @ 2614' – spot 40 sx @ 1670' tag  @ 300' – spot 15 sx @ 63' to surface	details, and give pertinent dates, including estimated date etions: Attach wellbore diagram of proposed completion  RECEIVED  MAY 1.3 2009
OTHER:  13. Describe prop osed or complete of starting any proposed work or recompletion.  Hole in casing @ 560' Pump 290 sx @ 560' – would not Circulate plugging mud  4/2/09 set cibp @ 3750' 4/16/09 spot 30 sx @ 3750' – spot 30 sx @ 3750'	OTHER  eted operations. (Clearly state all pertinent k). SEE RULE 1103. For Multiple Comp  t hold  ot 40 sx @ 2614' – spot 40 sx @ 1670' tag  @ 300' – spot 15 sx @ 63' to surface	details, and give pertinent dates, including estimated date etions: Attach wellbore diagram of proposed completion  RECEIVED  MAY 13 2009
OTHER:  13. Describe prop osed or complet of starting any proposed work or recompletion.  Hole in casing @ 560', Pump 290 sx @ 560' – would not Circulate plugging mud  4/2/09 set cibp @ 3750', 4/16/09 spot 30 sx @ 3750' – spot 4/17/09 spot 70 sx @ 1516' tag @ Install PA marker, cut off anchors.	OTHER  eted operations. (Clearly state all pertinent k). SEE RULE 1103. For Multiple Comp  t hold  ot 40 sx @ 2614' – spot 40 sx @ 1670' tag @ 300' – spot 15 sx @ 63' to surface  s, clean up location move out	details, and give pertinent dates, including estimated date etions: Attach wellbore diagram of proposed completion  RECEIVED  MAY 13 2009  HOBBSOCD
OTHER:  13. Describe prop osed or completed of starting any proposed work or recompletion.  Hole in casing @ 560', Pump 290 sx @ 560' – would not Circulate plugging mud  4/2/09 set cibp @ 3750', 4/16/09 spot 30 sx @ 3750', – spot 4/17/09 spot 70 sx @ 1516' tag @	OTHER  eted operations. (Clearly state all pertinent k). SEE RULE 1103. For Multiple Comp  t hold  ot 40 sx @ 2614' – spot 40 sx @ 1670' tag @ 300' – spot 15 sx @ 63' to surface  s, clean up location move out	details, and give pertinent dates, including estimated date etions: Attach wellbore diagram of proposed completion  RECEIVED  MAY 13 2009  HOBBSOCD  Approved for plugging of well bore only.  Liability under bond is retained pending receipt.
OTHER:  13. Describe prop osed or complet of starting any proposed work or recompletion.  Hole in casing @ 560', Pump 290 sx @ 560' – would not Circulate plugging mud  4/2/09 set cibp @ 3750', 4/16/09 spot 30 sx @ 3750' – spot 4/17/09 spot 70 sx @ 1516' tag @ Install PA marker, cut off anchors.	OTHER  eted operations. (Clearly state all pertinent k). SEE RULE 1103. For Multiple Comp  t hold  ot 40 sx @ 2614' – spot 40 sx @ 1670' tag @ 300' – spot 15 sx @ 63' to surface  s, clean up location move out	details, and give pertinent dates, including estimated date etions: Attach wellbore diagram of proposed completion  RECEIVED  MAY 13 2009  HOBBSOCD  Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under
OTHER:  13. Describe prop osed or complet of starting any proposed work or recompletion.  Hole in casing @ 560', Pump 290 sx @ 560' – would not Circulate plugging mud  4/2/09 set cibp @ 3750', 4/16/09 spot 30 sx @ 3750' – spot 4/17/09 spot 70 sx @ 1516' tag @ Install PA marker, cut off anchors.	OTHER  eted operations. (Clearly state all pertinent k). SEE RULE 1103. For Multiple Comp  t hold  ot 40 sx @ 2614' – spot 40 sx @ 1670' tag @ 300' – spot 15 sx @ 63' to surface  s, clean up location move out	details, and give pertinent dates, including estimated date etions: Attach wellbore diagram of proposed completion  RECEIVED  MAY 13 2009  HOBBSOCD  Approved for plugging of well bore only.  Liability under bond is retained pending receipt.
OTHER:  13. Describe prop osed or complet of starting any proposed work or recompletion.  Hole in casing @ 560', Pump 290 sx @ 560' – would not Circulate plugging mud  4/2/09 set cibp @ 3750', 4/16/09 spot 30 sx @ 3750' – spot 4/17/09 spot 70 sx @ 1516' tag @ Install PA marker, cut off anchors.	OTHER  eted operations. (Clearly state all pertinent k). SEE RULE 1103. For Multiple Comp  t hold  ot 40 sx @ 2614' – spot 40 sx @ 1670' tag @ 300' – spot 15 sx @ 63' to surface  s, clean up location move out	details, and give pertinent dates, including estimated date etions: Attach wellbore diagram of proposed completion  RECEIVED  MAY 13 2009  HOBBSOCD  Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under
OTHER:  13. Describe prop osed or completed of starting any proposed work or recompletion.  Hole in casing @ 560', Pump 290 sx @ 560' – would not Circulate plugging mud  4/2/09 set cibp @ 3750', 4/16/09 spot 30 sx @ 3750' – spot 4/17/09 spot 70 sx @ 1516' tag @ Install PA marker, cut off anchors.  Steel pits were used on this plugging	OTHER  eted operations. (Clearly state all pertinent k). SEE RULE 1103. For Multiple Comp  t hold  ot 40 sx @ 2614' – spot 40 sx @ 1670' tag @ 300' – spot 15 sx @ 63' to surface  s, clean up location move out procedure	details, and give pertinent dates, including estimated date etions: Attach wellbore diagram of proposed completion  RECEIVED  MAY 13 2009  HOBBSOCD  Approved for plugging of well bore only.  Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.emnrd.state.nm.us/ned.  knowledge and belief. I further certify that any pit or below-
OTHER:  13. Describe prop osed or completed of starting any proposed work or recompletion.  Hole in casing @ 560', Pump 290 sx @ 560' – would not Circulate plugging mud  4/2/09 set cibp @ 3750', 4/16/09 spot 30 sx @ 3750' – spot 4/17/09 spot 70 sx @ 1516' tag @ Install PA marker, cut off anchors.  Steel pits were used on this plugging	OTHER  eted operations. (Clearly state all pertinent k). SEE RULE 1103. For Multiple Comp  t hold  ot 40 sx @ 2614' – spot 40 sx @ 1670' tag @ 300' – spot 15 sx @ 63' to surface  s, clean up location move out procedure	details, and give pertinent dates, including estimated date etions: Attach wellbore diagram of proposed completion  RECEIVED  MAY 13 2009  HOBBSOCD  Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under
OTHER:  13. Describe prop osed or complet of starting any proposed work or recompletion.  Hole in casing @ 560', Pump 290 sx @ 560' – would not Circulate plugging mud  4/2/09 set cibp @ 3750', 4/16/09 spot 30 sx @ 3750', – spot 4/17/09 spot 70 sx @ 1516' tag @ Install PA marker, cut off anchors.  Steel pits were used on this plugging to the spot spot 30 st. in the spot spot spot 30 st. in the spot spot 30 st. in the spot spot 30 st. in the spot spot spot 30 st. in the spot spot 30 st. in the spot spot spot 30 st. in the spot spot spot spot spot spot spot spot	OTHER  eted operations. (Clearly state all pertinent k). SEE RULE 1103. For Multiple Comp  t hold  ot 40 sx @ 2614' – spot 40 sx @ 1670' tag @ 300' – spot 15 sx @ 63' to surface  s, clean up location move out procedure  bove is true and complete to the best of my closed according to NMOCD guidelines , a gener	Approved for plugging of well bore only.  Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Porms, www.emnrd.state.nm.us/oed.  knowledge and belief. I further certify that any pit or belowal permit  or an (attached) alternative OCD-approved plan
OTHER:  13. Describe prop osed or completed of starting any proposed work or recompletion.  Hole in casing @ 560', Pump 290 sx @ 560' – would not Circulate plugging mud  4/2/09 set cibp @ 3750', 4/16/09 spot 30 sx @ 3750' – spot 4/17/09 spot 70 sx @ 1516' tag @ Install PA marker, cut off anchors.  Steel pits were used on this plugging	OTHER  eted operations. (Clearly state all pertinent k). SEE RULE 1103. For Multiple Comp  t hold  ot 40 sx @ 2614' – spot 40 sx @ 1670' tag @ 300' – spot 15 sx @ 63' to surface  s, clean up location move out procedure  bove is true and complete to the best of my closed according to NMOCD guidelines , a gener	details, and give pertinent dates, including estimated date etions: Attach wellbore diagram of proposed completion  RECEIVED  MAY 13 2009  HOBBSOCD  Approved for plugging of well bore only.  Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.emnrd.state.nm.us/ned.  knowledge and belief. I further certify that any pit or below-
OTHER:  13. Describe prop osed or completed of starting any proposed work or recompletion.  Hole in casing @ 560', Pump 290 sx @ 560' – would not Circulate plugging mud  4/2/09 set cibp @ 3750', 4/16/09 spot 30 sx @ 3750', – spot 4/17/09 spot 70 sx @ 1516' tag @ Install PA marker, cut off anchors.  Steel pits were used on this plugging in the spot of t	OTHER  eted operations. (Clearly state all pertinent k). SEE RULE 1103. For Multiple Comp  t hold  ot 40 sx @ 2614' - spot 40 sx @ 1670' tag @ 300' - spot 15 sx @ 63' to surface  s, clean up location move out procedure  bove is true and complete to the best of my closed according to NMOCD guidelines , a gener  TITLE AGENT	Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be fruind at OCD Web Page under Porms, www.cmnrd.state.nm.us/oed.  Approved gand belief. I further certify that any pit or belowal permit  or an (attached) alternative OCD-approved plan  DATE 4-24-09
OTHER:  13. Describe prop osed or complet of starting any proposed work or recompletion.  Hole in casing @ 560', Pump 290 sx @ 560' – would not Circulate plugging mud  4/2/09 set cibp @ 3750', 4/16/09 spot 30 sx @ 3750' – spot 4/17/09 spot 70 sx @ 1516' tag @ Install PA marker, cut off anchors.  Steel pits were used on this plugging properties were used on this plugging properties.  I hereby certify that the information a grade tank has been/will be constructed or constructed or constructed.	OTHER  eted operations. (Clearly state all pertinent k). SEE RULE 1103. For Multiple Comp  t hold  ot 40 sx @ 2614' – spot 40 sx @ 1670' tag @ 300' – spot 15 sx @ 63' to surface  s, clean up location move out procedure  bove is true and complete to the best of my closed according to NMOCD guidelines , a gener	Approved for plugging of well bore only.  Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Porms, www.emnrd.state.nm.us/oed.  knowledge and belief. I further certify that any pit or belowal permit  or an (attached) alternative OCD-approved plan
OTHER:  13. Describe prop osed or complet of starting any proposed work or recompletion.  Hole in casing @ 560', Pump 290 sx @ 560' – would not Circulate plugging mud  4/2/09 set cibp @ 3750', 4/16/09 spot 30 sx @ 3750', – spot 4/17/09 spot 70 sx @ 1516' tag @ Install PA marker, cut off anchors.  Steel pits were used on this plugging in Steel pits were used on this plugging in SIGNATURE.  Type or print name  For State Use Only	OTHER  eted operations. (Clearly state all pertinent k). SEE RULE 1103. For Multiple Comp  t hold  ot 40 sx @ 2614' – spot 40 sx @ 1670' tag @ 300' – spot 15 sx @ 63' to surface  s, clean up location move out procedure  bove is true and complete to the best of my losed according to NMOCD guidelines □, a gener  TITLE AGENT  E-mail address:	Approved for plugging of well bore only.  Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.emnrd.state.nm.us/ned.  knowledge and belief. I further certify that any pit or belowal permit or an (attached) alternative OCD-approved plan .  DATE 4-24-09  Telephone No.
OTHER:  13. Describe prop osed or complet of starting any proposed work or recompletion.  Hole in casing @ 560', Pump 290 sx @ 560' – would not Circulate plugging mud  4/2/09 set cibp @ 3750', 4/16/09 spot 30 sx @ 3750' – spot 4/17/09 spot 70 sx @ 1516' tag @ Install PA marker, cut off anchors.  Steel pits were used on this plugging properties were used on this plugging properties.  I hereby certify that the information a grade tank has been/will be constructed or constructed or constructed.	OTHER  eted operations. (Clearly state all pertinent k). SEE RULE 1103. For Multiple Comp  t hold  ot 40 sx @ 2614' – spot 40 sx @ 1670' tag @ 300' – spot 15 sx @ 63' to surface  s, clean up location move out procedure  bove is true and complete to the best of my losed according to NMOCD guidelines □, a gener  TITLE AGENT  E-mail address:	Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be fruind at OCD Web Page under Porms, www.cmnrd.state.nm.us/oed.  Approved gand belief. I further certify that any pit or belowal permit  or an (attached) alternative OCD-approved plan  DATE 4-24-09