

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88241  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
June 19, 2008

RECEIVED

APR 23 2009

HOBBSOC

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO.	30-025-07231
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>	
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name L.W. WARD	
8. Well Number	2
9. OGRID Number	000873
10. Pool name or Wildcat BRONCO; SILURO DEVONIAN	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3810' GL	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator  
APACHE CORPORATION

3. Address of Operator  
6120 S YALE AVE, SUITE 1500  
TULSA, OK 74136

4. Well Location

Unit Letter I : 1983 feet from the SOUTH line and 520 feet from the EAST line  
Section 11 Township 13S Range 38E NMPM County LEA

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Apache Corporation requests permission to TA this well with the following procedure:

1. POOH w/all production equipment.
2. Top of fish @ 11322'. Set bridge plug @ +/- 11320'.
3. Load the casing and pressure test to 500 psig for 30 minutes.
4. Upon completion of the procedure, Apache will send a subsequent report with an original pressure chart.

Current Perfs: 11650'-11871' Open Hole

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Amber Cooke TITLE PRODUCTION ENGINEERING TECH DATE 04/21/2009

Type or print name AMBER COOKE E-mail address: AMBER.COOKE@APACHECORPORATION.COM (918)491-4968

For State Use Only

APPROVED BY: Tony W. Hill TITLE DISTRICT 1 SUPERVISOR DATE MAY 13 2009

Conditions of Approval (if any):

**Conditions of Approval:** the operator shall give 24 hour notice the the appropriate District office before work begins.