Submit 5 Copies 10 Appropriate District	State of New Me	exico		Form C-103
Office District I	Energy, Minerals and Natural Resources		7	June 19, 2008
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-025-22165  5. Indicate Type of Lease	
District III	1220 South St. Francis Dr.		STATE *	FEE 🛛
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505		6. State Oil & Gas Lease 1	
1220 S. St. Francis Dr., Santa Fe, NM	1220 S. St. Francis Dr., Santa Fe, NM			
87505	CEC AND DEPORTS ON WELLS		7. Lease Name or Unit Ag	reement Name
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			Howse C	recinent rame
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			110.1150	
PROPOSALS.)  1. Type of Well: Oil Well X Gas Well Other			8. Well Number # 1	
2. Name of Operator			9. OGRID Number	
State of New Mexico / formerly Pronghorn Management Corp			122811	
3. Address of Operator			10. Pool name or Wildcat	
1625 N. French Drive Hobbs, NM 88240			House Abo	
4. Well Location		<u> </u>		
Unit Letter H :	1980 feet from theN_	line and	660feet from the	Ehne
Section 11 Township 20S Range 38E NMPM Lea County				
	11. Elevation (Show whether DR,	, RKB, RT, GR, etc	.)	
12. Check A	Appropriate Box to Indicate N	ature of Notice,	Report or Other Data	
NOTICE OF INTENTION TO				
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK □ PLUG AND ABANDON X □ REMEDIAL WORK □ ALTERING CAS				
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON X ☐ REMEDIAL WORK TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRII			<del></del>	
TEMPORARILY ABANDON				`
DOWNHOLE COMMINGLE				
_				
OTHER:		OTHER:		
13. Describe proposed or comp	leted operations. (Clearly state all 1	pertinent details, ar	nd give pertinent dates, includ	ing estimated date
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion				
or recompletion.				
	brari	8 Aleman		
	RECE	VED		
			MAY 1/2	tara.
			MAY 27	7009
			HOBBS	OCD
The Oil Conservation Division Must be notified				
24 hours prior to the beginning of plugging operations				
		-		
Spud Date:	Rig Release Da	ate:		
Spud Bute.			- · · · · · · · · · · · · · · · · · · ·	
I hereby certify that the information	above is true and complete to the b	est of my knowled	ge and belief.	
	<b>2</b>	,	5	, 1
$\mathcal{M}_{\alpha}$	$R$ . $\sim \Lambda_{-}$		011.	lanlanca
SIGNATURE 1 'WHILLY ST SLOW'S TITLE CONVIDENCES CYTICAL DATE 3 / 20/2009				
Time or print pages	Transit addes	<b>y</b>	PHONE:	-
Type or print name E-mail address: PHONE:  For State Use Only				
APPROVED BY: COMPLETE BATE BY EAST OF THE STATE OF THE ST				
Conditions of Approval (if any):				
<b>/</b>				

State of New Mexico Howse "C" Well No. 1 30-025-22165 UL-H, Sec. 11, T-205, R-38E

9-5/8" at 1547' - 800 sx cmt, circ. 7" at 4476' - 500 sx cmt, perf at 1350', circ cmt to surface 4-1/2 liner from 4197' to 7810' - 700 sx cmt CIBP at 7290'

Tag CIBP at 7290'.

Spot 25 sx Class C cmt.

Circ hole w/9.5 ppg brine mixed w/12.5 lb salt get per bbl.

Spot 25 sx Class C cmt at 6800'.

Spot 35 sx Class C cmt at 4530'. WOC & Tag. (Int csg and liner top).

Perf at 2760' and sqz w/ 35 sx Class C cmt. WOC & Tag. (BOS)

Perf at 1900' and sqz w/35 sx Class C cmt. WOC & Tag. (TOS)

Spot 50 sx Class C cmt at 1600'. WOC & Tag. (Surface shoe)

Spot cmt from 60' to surface.

Cut off wellhead and remove anchors.

Install Dry hole marker.