Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103
Office District I	Energy, Minerals and Natural Resources	5/25/2009
1625 N. French Dr., Hobbs, NM 88240	^	WELL API NO. 30-025-3354 7
District II  1301 W. Grand Ave. Artesia NM 88210 Ma.	CONSERVATION DIVISION	5. Indicate Type of Lease
District III	State of New Mexico Energy, Minerals and Natural Resources  PRONSERVATION DIVISION  12 South St. Francis Dr.  2010 Santa Fe, NM 87505  L. L	STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87470	2000 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM		MS-0004
87505	ND PEPOPTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO	D DRILL OR TO DEEPEN OR PLUG BACK TO A	State
DIFFERENT RESERVOIR USE "APPLICATION		8. Well Number # 1
PROPOSALS)  1. Type of Well: Oil Well	Vell Other X Brine Well	,
2. Name of Operator	CII GIRCI II BIIIC II CII	9. OGRID Number
Key Energy Services	,	171 191 3
3. Address of Operator		10. Pool name or Wildcat
P.O Box 99 Eunice NM 88231		BSW-SALADO
4. Well Location		
Unit Letter E : 1340 feet from the North line and 330 feet from the West line		
Section 15	Township 21S Range 37E	NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
Pit or Below-grade Tank Application or Closu		
Pit typeDepth to GroundwaterDistance from nearest fresh water wellDistance from nearest surface water		
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A		
PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMENT JOB		
. 022 0 2 2	_	·_
OTHER: Sonor Test & MIT OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion		
or recompletion.		
of recompletion.		
5-19-2009 MI- RUPU Install BOP, POH with 2 7/8 Tbg and 6 ¼ Bit		
5-19-2010 SION		
5-20-2009 RU Key Wire Line and Sonor Tool, Run Sonor test on Brine Well, POH with sonor tool.		
5-20-2010 SION 5-21-2009 RIH with Packer and 2 7/8 Tbg and 6 ¼ bit to 1300', Pressure test to 300#, Pressure Test leaked 30# in		
20 minutes. OCD Rep on location advised to Pull up to 1290' and Retest. Pull up to 1290' with Packer and Tbg.		
Retest to 340#, Test	held good for 30 minutes. POH with packer and	tbg. RIH with 6 ¼ Bit and tbg to 1300'
And SION.	-	
	er swivel and drill to 1701', Circulate will for 30	0 minutes. SION
5/23/2009 Pull BOP and flange v	vill head back up & return to production.	
I hereby certify that the information	on above is true and complete to the best of my	knowledge and belief. I further certify that any pit
or below-grade tank has been/will be constructed	or closed according to NMOCD guidelines, a general	permit 🗍 or an (attached) alternative OCD-approved
plan .	<u>.</u>	
SIGNATURE Sam Oline	TITLE MANAGER	DATE <b>5-25-09</b>
Sidning & Service	7.11.71	
Type or print name	/ E-mail address:	Telephone
For state use only	//·// DISTRICT 1 S	BUPERVISOF DATE MAY 2 7 200
APPROVEDBY: Way W, The IIILE BATE WITH 7 1 200		
Conditions of Approval ( if thy ):		

