RECEIVED

HOBB

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

5,	Lease Serial No.	
	LC031625h	

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					LC031621b 6. If Indian, Allottee or Tribe Name
210	CONTRACTOR TO STATE OF THE PARTY OF THE PART				
I. Type of Well	RIPLICATE- Other insti	ructions on re	verse side.	\downarrow	7. If Unit or CA/Agreement, Name and/or No.
	✓ Gas Well Other				8. Well Name and No.
2. Name of Operator John H. Hendrix Corporation					Mexico No. 1 9. API Well No.
432-68			clude area code)	\top	30-025-06163
4. Location of Well (Foolage, Sec., T., R., M., or Survey Description)				-	10. Field and Pool, or Exploratory Area Eumont (Queen) Gas Pool
330' FNL & 330' FEL, Sec 18, T20\$, R37E, Unit Letter A					11. County or Parish, State
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE,					Les Co, NM
TYPE OF SUBMISSION	TROPRIATE BOX(ES) TO				EPORT, OR OTHER DATA
	Acidize		TYPE OF ACTIO		
Notice of Intent	Alter Casing	Deepen Fracture Treat			rt/Resume) Water Shut-Off
Subsequent Report	Casing Repair	New Construction	Reclamati		Weil Integrity Other
Final Abandonment Notice	Change Plans Convert to Injection	Plug and Abando	n <u> </u>	ily Aba	indon
13. Describe Proposed or Complete	d Operation (electrical and a state of	Plug Back	Waler Dis	-	
following completion of the inv	e work will be performed or provide	the Band No. on fi	le with BLM/BIA, R	coured	/ proposed work and approximate duration thereof, vertical depths of all pertinent markers and zones, I subsequent reports shall be filed within 30 days a new interval, a Form 3160-4 shall be filed once ion, have been completed, and the operator has
and tag @ 3705°. Log. Finance 199 Cont. drill on plug 5-21-09 Cont. drill on plug 5-22-09 GIH and set plor @ 5-23-09 GIH. Tag cmt @ 3 5-26-09 Perf Queen zone with a 15 new perfs w/ 3000 gai 5-27-09 Swab dry. GIH w/ 5-28-09 Hole dry and the go unit and gas sales connection	oridge and tag plug @ 3406'. 3379' and test plug - no test. T d TOC @ 2450', Top of Queen w/ no progress. Cail Bi_M and 3263'. Obtain running squeez 265' and drillout hard cmt to 3 (1 JHPF @ 3219', 3226', 3258', 15% sefe HCl acid. Flush. W they and pkr and set @ 3200'. I 1 vacuum. POOH w/ they and p a.	get niternate con 12 @ 2250# w/ 93 s 380', new PBTD. , 3262', 3272', 327 /OA.	dition: set pkr and x in perfs, 69 sx in Called into Hobbs 9', 3263', 3287', 33	i squee eg an BLM, 98', 33	GIH w/ WL Co and find hole through plug farted drilling on plug @ 3406'. Eze off Grayburg and fill csg w/cmt to 3385', and 79 sx reversed out. POOH. WOC. Test csg to 700#. Held. 07', 3317', 3322', 3329', 3344', 3346'. Treat DMO. Leave well SI waiting on pumping
Name (Printed/Typed) Carolyn Dorno Ha		77.4			
Signature /	h //	1 iue	Engineer	+	
carry	THIS SDAOF FOR	Date		,	R/2009
	THIS SPACE FOR FEI	DERAL OR S	TATE OFFIC	E US	E
Approved by Conditions of approval, if any, are attacertify that the applicant holds legal or which would entitle the applicant to co. Title 18 U.S.C. Series 1001 and Title 18	equilibre one to those rights in the	not warrant or subject lease	itle		ACIGEPTED FOR RECORD
States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a crim statements or representations as to	ne for any person ke any matter within it	towingly and willful s jurisdiction	to rai	ake to any department Whitemery of the Alfright
(Instructions on page 2) When will go on prod	Well be ab	lle to	Ka		BUREAU OF LAND MANACEMENT
so on prod			• ,	$\mid L$	CARLSBAD FIELD OFFICE