State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE CONSERVATION DIVISION	
FILE IN TRIPLICATE DISTRICT I DISTRICT I	WELL API NO.
1625 N French Dr., Hobbs, NM 88240 JUN 1 8 2009 Santa Fe, NM 87505	30-025-29062
<u>DISTRICT II</u>	5. Indicate Type of Lease
1301 W Grand Ave, Artesia, NM 88210 HOBBSOCD	STATE FEE
<u>DISTRICT III</u>	6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410	7. Lease Name or Unit Agreement Name
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	North Hobbs (G/SA) Unit Section 24
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals) 1. Type of Well:	8. Well No 342
Oil Well Gas Well Other Injector	0. 1101 342
2. Name of Operator	9. OGRID No. 157984
Occidental Permian Ltd.	
3. Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323	
4. Well Location	
Unit Letter O: 145 Feet From The South Line and 1435 Feet	eet From The East Line
Tampakin 10 C Panga 27	.F. NMPM Lea County
Section 24 Township 18-S Range 37-	E NMPM Lea County
3665' GR	
	· ·
Pit or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well	
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction M	aterial
12. Check Appropriate Box to Indicate Nature of Notice, Report, or	Other Date
	SSEQUENT REPORT OF:
Notice of interviol	OLGOLITI IILI OITI OITI
DEMEDIAL WORK TO DILIO AND ADAMPON DEMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF	
	PNS. PLUG & ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME	PNS. PLUG & ABANDONMENT NT JOB
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: Casing	PNS. PLUG & ABANDONMENT INT JOB INT JOB XX
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: OTHER: Casing	PNS. PLUG & ABANDONMENT INT JOB Integrity Test Es, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: Casing	PNS. PLUG & ABANDONMENT INT JOB Integrity Test Ex, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: OTHER: Casing	PNS. PLUG & ABANDONMENT INT JOB Integrity Test Ex, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: Casing 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Test Date: 06-11/2009	PNS. PLUG & ABANDONMENT INT JOB Integrity Test Es, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: Casing 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed	PNS. PLUG & ABANDONMENT INT JOB Integrity Test Es, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: OTHER: Casing 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Test Date: 06-11/2009 Pressure Reading: Initial – 500 PSI; 15 min – 490 PSI; 30 min – 490 PSI	PNS. PLUG & ABANDONMENT INT JOB Integrity Test Es, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: Casing 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Test Date: 06-11/2009 Pressure Reading: Initial – 500 PSI; 15 min – 490 PSI; 30 min – 490 PSI Length of pressure test: 30 minutes	PNS. PLUG & ABANDONMENT INT JOB Integrity Test Es, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: Casing 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Test Date: 06-11/2009 Pressure Reading: Initial – 500 PSI; 15 min – 490 PSI; 30 min – 490 PSI	PNS. PLUG & ABANDONMENT INT JOB Integrity Test Ex, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: Casing 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Test Date: 06-11/2009 Pressure Reading: Initial – 500 PSI; 15 min – 490 PSI; 30 min – 490 PSI Length of pressure test: 30 minutes	PNS. PLUG & ABANDONMENT INT JOB Integrity Test Es, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: Casing 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Test Date: 06-11/2009 Pressure Reading: Initial – 500 PSI; 15 min – 490 PSI; 30 min – 490 PSI Length of pressure test: 30 minutes	PNS. PLUG & ABANDONMENT INT JOB Integrity Test Es, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: Casing 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Test Date: 06-11/2009 Pressure Reading: Initial – 500 PSI; 15 min – 490 PSI; 30 min – 490 PSI Length of pressure test: 30 minutes	PNS. PLUG & ABANDONMENT INT JOB Integrity Test Es, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: Casing 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Test Date: 06-11/2009 Pressure Reading: Initial – 500 PSI; 15 min – 490 PSI; 30 min – 490 PSI Length of pressure test: 30 minutes Witnessed: YES – Mark Whitaker NMOCD	PNS. PLUG & ABANDONMENT Integrity Test Es, including estimated date of starting any completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: Casing 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Test Date: 06-11/2009 Pressure Reading: Initial – 500 PSI; 15 min – 490 PSI; 30 min – 490 PSI Length of pressure test: 30 minutes Witnessed: YES – Mark Whitaker NMOCD	PNS. PLUG & ABANDONMENT Integrity Test Es, including estimated date of starting any completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: Casing 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Test Date: 06-11/2009 Pressure Reading: Initial – 500 PSI; 15 min – 490 PSI; 30 min – 490 PSI Length of pressure test: 30 minutes Witnessed: YES – Mark Whitaker NMOCD Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certificonstructed or closed according to NMOCD guidelines a general permit or an (attached) alternation or an (attached) alternation.	PNS. PLUG & ABANDONMENT Integrity Test Es, including estimated date of starting any completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: Casing 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Test Date: 06-11/2009 Pressure Reading: Initial – 500 PSI; 15 min – 490 PSI; 30 min – 490 PSI Length of pressure test: 30 minutes Witnessed: YES – Mark Whitaker NMOCD	PNS. PLUG & ABANDONMENT Integrity Test Es, including estimated date of starting any completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: Casing 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Test Date: 06-11/2009 Pressure Reading: Initial – 500 PSI; 15 min – 490 PSI; 30 min – 490 PSI Length of pressure test: 30 minutes Witnessed: YES – Mark Whitaker NMOCD Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certificonstructed or closed according to NMOCD guidelines a general permit or an (attached) alternation or an (attached) alternation.	PNS. PLUG & ABANDONMENT Integrity Test Es, including estimated date of starting any completion or recompletion. The system of
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: Casing 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Test Date: 06-11/2009 Pressure Reading: Initial – 500 PSI; 15 min – 490 PSI; 30 min – 490 PSI Length of pressure test: 30 minutes Witnessed: YES – Mark Whitaker NMOCD Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certificonstructed or closed according to NMOCD guidelines a general permit or an (attached) alternation plan. SIGNATURE TITLE Administrative.	PNS. PLUG & ABANDONMENT Integrity Test Es, including estimated date of starting any completion or recompletion. That any pit or below-grade tank has been/will be the OCD-approved E Associate DATE 06/16/2009
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: Casing 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Test Date: 06-11/2009 Pressure Reading: Initial – 500 PSI; 15 min – 490 PSI; 30 min – 490 PSI Length of pressure test: 30 minutes Witnessed: YES – Mark Whitaker NMOCD Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certificonstructed or closed according to NMOCD guidelines a general permit or an (attached) alternation plan SIGNATURE TITLE Administrative TYPE OR PRINT NAME Mendy Lohnson E-mail address: mendy johnson@oxy.com	PNS. PLUG & ABANDONMENT Integrity Test Es, including estimated date of starting any completion or recompletion. That any pit or below-grade tank has been/will be to occupant to the occupant of the occupant of the occupant occ
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: Casing 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Test Date: 06-11/2009 Pressure Reading: Initial – 500 PSI; 15 min – 490 PSI; 30 min – 490 PSI Length of pressure test: 30 minutes Witnessed: YES – Mark Whitaker NMOCD Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certificonstructed or closed according to NMOCD guidelines a general permit or an (attached) alternation plan SIGNATURE TITLE Administrative TYPE OR PRINT NAME Mendy A Johnson E-mail address: mendy johnson@oxy.com For State Use Only DISTRICT 1	PNS. PLUG & ABANDONMENT Integrity Test Es, including estimated date of starting any completion or recompletion. That any pit or below-grade tank has been/will be to occupant to be occ
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: Casing 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Test Date: 06-11/2009 Pressure Reading: Initial – 500 PSI; 15 min – 490 PSI; 30 min – 490 PSI Length of pressure test: 30 minutes Witnessed: YES – Mark Whitaker NMOCD Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines a general permit or an (attached) alternation plan SIGNATURE TITLE Administrative TYPE OR PRINT NAME Mendy Johnson E-mail address: mendy johnson@oxy.com	PNS. PLUG & ABANDONMENT Integrity Test Es, including estimated date of starting any completion or recompletion. That any pit or below-grade tank has been/will be to occupant to the occupant of the occupant of the occupant occ

