

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD-
OCD-HOBBS

FORM APPROVED
OMB No. 1004-0137
Expires: March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.
NM 35612

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well

☒ Oil Well

☐ Gas Well

☐ Other

2. Name of Operator

TRITEX ENERGY

3a. Address

PO BOX 1466
ARTESIA, NM 88211

3b. Phone No. (include area code)

575.308.0722

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

990' FNL 1658 FWL
SEC 31, T16S, R32E

7. If Unit of CA/Agreement, Name and/or No.

8. Well Name and No.
POLEWSKI FED #2

9. API Well No.
30-025-35340

10. Field and Pool or Exploratory Area
LUSK DELAWARE, WEST

11. Country or Parish, State
LEA CO., NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☒ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

1) Notify BLM - Pat Hutchings on 5/18/09.

2) 5/20/09 Set CIBP @ 4,600' per Pat Hutchings

3) 5/20/09 Circ. 10# MLF. Spot 75sx cmt @ 4,600' per BLM P.H.

4) 5/21/09 Tag TOC @ 3,919'. Spot 25sx cmt w/ 2% CaCl @ 2,702'. WOC-Tag TOC. Spot 25sx cmt @ 849'.

5) 5/22/09 Tag TOC @ 632'. Circ. 10sx cmt @ 100' - surface. Remove wellhead & anchors, Install P&A marker, Backfill cellar.

Approved as to plugging of the well bore.
Liability under bond is retained until
Surface restoration is completed.

RECEIVED

JUN 23 2009

HOBBSOCD

APPROVED

JUN 19 2009

JAMES A. AMOS
SUPERVISOR-EPS

14. I hereby certify that the foregoing is true and correct.

Name (Printed/Typed)
GARY EGGLESTON

Title P&A Supervisor

Signature

Date 06/09/2009

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

DISTRICT 1 SUPERVISOR

Title

Date

JUN 24 2009

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)