

Office

Energy, Minerals and Natural Resources

June 19, 2008

District I

1625 N. French Dr., Hobbs, NM 88241

District II

1301 W Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S St Francis Dr., Santa Fe, NM

87505

RECEIVED**JUN 18 2009****HOBSOCD**

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

WELL API NO.

30-025-06814

5. Indicate Type of Lease

STATE ☐FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

CHEVRON U.S.A. INC.

3. Address of Operator

15 SMITH ROAD, MIDLAND, TEXAS 79705

4. Well Location

Unit Letter J: 1874 feet from the SOUTH line and 2086 feet from the EAST line

Section 28 Township 21-S Range 37-E NMPM County LEA

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3444'GL

7. Lease Name or Unit Agreement Name

J.N. CARSON NCT-A

8. Well Number 5

9. OGRID Number 4323

10. Pool name or Wildcat

HARE SIMPSON

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐TEMPORARILY ABANDON ☐ CHANGE PLANS ☐PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐COMMENCE DRILLING OPNS. ☐ P AND A ☐CASING/CEMENT JOB ☐

OTHER:

OTHER: CLEAN OUT & RE-FRAC & TA WITH CHART

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

4-20-09: MIRU. 4-21-09: LATCH ON RODS. WORK ON STUCK PUMP. 4-22-09: COULD NOT REL TAC. FREE PT TBG ABOVE TAC 100# @ 7001, 10% @ 7004. CHEM CUT TBG @ 7018. 4-23-09: REL TAC. TOF @ 7018. 4-24-09: LATCH ON FISH. MOVE FISH UP HOLE 2'. REL FISH. 4-25-09: TAG TOF @ 7353. LATCH ON FISH. 4-26-09: MOVE FISH UP HOLE 4'. REL OFF TOF @ 7353. 4-27-09: SLIP OFF FISH. 4-28-09: BREAK CIRC @ 4025' W/FOAM. WH LEAKING. TIH W/RBP & SET @ 4990. CIRC W/200 BW. 4-29-09: SET RBP @ 1007. DUMP 4 SX DN CSG. WASH SAND OFF. REL RBP. 4-30-09: TIH & WENT OVER FISH @ 7353. C/O TO 7408. 5-01-09: WASH OVER TO 7486. CUT TBG @ 7473. 5-03-09: TAG FILL @ 7465. C/O TO 7697. 5-04-09: LATCH ON FISH @ 7535. PERF 7386-96,7406-16,7426-36,7446-56,7466-76, (200 HOLES) 5-05-09: SET PKR @ 6009. 5-07-09: FRAC W/1071 BBLS ACID. 5-08-09: TAG @ 7333. BTM PERFS COVERED W/SAND (7386-7503)REL PKR. 5-09-09: C/O 7331-7699. 5-11-09: TAG @ 7648. 5-12-09: TAG SAND @ 7647. TAG @ 7642. C/O TO 7699. TAG SAND @ 7687.

*****CONTINUED ON NEXT PAGE*****

This Approval of Temporary
Abandonment Expires

6-26-2011

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Denise Pinkerton

TITLE REGULATORY SPECIALIST

DATE 06-17-2009

Type or print name

DENISE PINKERTON

E-mail address: leakejd@chevron.com

PHONE: 432-687-7375

For State Use Only

APPROVED BY:

Ken W. Hill

TITLE

DISTRICT 1 SUPERVISOR

DATE

JUN 26 2009

Conditions of Approval (if any):

Continuation of J.N. Carson NCT-A #5

5-13-09: TOF @ 7668. 5-14-09: BREAK CIRC W/FOAM @ 5000'. 5-15-09: TAG FILL @ 7614. CLN DN TO TOF & CIRC SAND OUT OF WELL. LATCH ONTO FISH. 5-16-09: SET RBP @ 7590. 5-17-09: TAG SAND @ 7582. 5-18-09: SET PKR @ 7289. REL PKR. 5-19-09: SET PKR @ 6008. REL PKR. SAND ON PKR. SET PKR @ 6894. REL PKR. 5-27-09: TAG SAND @ 7490. C/O TO 7707. 6-02-09: TAG FILL @ 7532. 6-03-09: EASY DRILLING 7532-7668. HARD DRILLING 7668-7682. FELL THRU @ 7682. EOT @ 7698. 6-04-09: TIH W/23 JTS – EOT @ 7759. SET PKR @ 7305. SWABBING. 6-06-09: PU PRISM LOGGING TOOLS. TAG FILL @ 7490. SET CIBP @ 7750 W/10' CMT ON TOP. REL PKR. 6-07-09: BREAK CIRC @ 7460. C/O 7477-7782. FELL OUT OF SAND @ 7760. 6-08-09: SET CIBP @ 7740. CALLED JOHN HARRISON, NMOCD, OF INTENT TO TA. DUMP 35' CMT ON TOP OF CIBP TO PUT US @ 7705. TIH W/2ND CIBP & SET @ 7310. 6-09-09: TIH W/TBG TO 7303. SET PKR @ 7300. TEST CIBP @ 7310. TEST CSG & OLD SQZD PERFS 7072-7277. TEST PERFS TO 500- HELD. SET PKR BELOW SQZ PERFS 5090-5262 & SET PKR @ 5296. REL PKR. RESET PKR @ 5358. 6-10-09: SET PKR @ 5045. REL PKR. SET PKR @ 6097. REL PKR. ,PKR @ 5541, PKR @ 5478, PKR @ 5418, PKR @ 5388. **CSG LEAK FR 5041-5418.**

6-11-09: TIH W/CIBP & SET @ 5041. PRETEST CIBP TO 500 PSI FOR 15 MINS. HELD.

MIT ON CIBP TO 500 PSI. (ORIGINAL CHART & COPY OF CHART ATTACHED). (NMOCD WAS NOTIFIED ON 6-10-09) RIG DOWN. FINAL REPORT

WELL IS TEMPORARILY ABANDONED.

