Office Date M.C. and L. 1314	exico Form C-103
Office Energy, Minerals and Natu	
District II 1625 N French Dr., Hobbs, NM 87240 District III 1301 W Grand Ave, Artesia, NM 88270 District III 1000 Pro Proper Rd. Artes NM 87441 101 2 C 00000	WELL API NO.
District II 1301 W Grand Ave Artesia NM 8270 C ONSERVATIO	N DIVISION ancis Dr 5. Indicate Type of Lease
District III F220 South St. Fr	ancis Dr.
Santa Fe, NM 87400N 20 //// Santa Fe, NM 8	S/SUS STATE IXI FEE LI
1220 S St Francis Dr , Santa Fe SSOCO	6. State Oil & Gas Lease No.
	110
SUNDRY NOTICES AND REPORTS ON WE (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-10 PROPOSALS)	OR PLUG BACK TO A FINTOR MONIMENT SOUTH INTT
1. Type of Well:	8. Well Number
Oil Well X Gas Well Other	448
2. Name of Operator	9. OGRID Number
XTO ENERGY, INC.	005380
3. Address of Operator	10. Pool name or Wildcat
200 N. LORAINE, SUITE 800, MIDLAND, TEXAS 79701	EUNICE MONUMENT; GRAYBURG-SAN ANDRES
4. Well Location	
Unit Letter <u>H</u> : 2080 feet from the NC	RTH line and 660 feet from the EAST line
Section 22 Township 21s	
11. Elevation (Show whether	DR, RKB, RT, GR, etc.)
Pit or Below-grade Tank Application □ or Closure □	as as a surrence of the state o
Pit type STEEL Depth to Groundwater Distance from nearest from	esh water well * Distance from nearest surface water *
	bbls; Construction Material * NONE WITHIN 1,000'.
TR Ellier Thickness: iiii Below-Grade Tank: Voldin	
12. Check Appropriate Box to Indicat NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON	Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: REMEDIAL WORK
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS. PLUG AND
PULL OR ALTER CASING MULTIPLE COMPLETION	Approved for plugging of well bore only. CASING TEST Albority under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD West as Proving and Proving a Company of C-103 (Subsequent Report of Well Plugging)
OTHER:	which may be found at OCD with plugging)
OTHER:	which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd.
13. Describe proposed or completed operations. (Clearly state all p	which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd.
 13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 1103. For Multip or recompletion. 06/16/09: TAG EXISTING CIBP @ 3,690; CIRC. WELL W 06/17/09: MIX & PUMP A 35 SX. OMT. PLUG ON TOP OF 	which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd. pertinent details, and give pertinent dates, including estimated date le Completions: Attach wellbore diagram of proposed completion / PXA MUD. CIBP @ 3,690'; WOC & TAG OMT. PLUG @ 3,633'; PRES. UP
13. Describe proposed or completed operations. (Clearly state all pof starting any proposed work). SEE RULE 1103. For Multipor recompletion. 06/16/09: TAG EXISTING CIBP @ 3,690'; CIRC. WELL WO6/17/09: MIX & PUMP A 35 SX. CMT. PLUG ON TOP OF ON 4-1/2" CSG. TO 500# FOR 15 MIN. PER S	which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd. pertinent details, and give pertinent dates, including estimated date le Completions: Attach wellbore diagram of proposed completion / PXA MUD. CIBP @ 3,690'; WCC & TAG CMT. PLUG @ 3,633'; PRES. UP YIVIA W/ NMCCD - HELD CK; MIX & PUMP A 35 SX. CMT.
13. Describe proposed or completed operations. (Clearly state all pof starting any proposed work). SEE RULE 1103. For Multipor recompletion. 06/16/09: TAG EXISTING CIBP @ 3,690'; CIRC. WELL WORLDOWN MIX & PUMP A 35 SX. CMT. PLUG ON TOP OF CN 4-1/2" CSG. TO 500# FOR 15 MIN. PER SPLUG @ 3,633'-3,363' (CALC.); MIX & PUMP.	which may be round at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd. pertinent details, and give pertinent dates, including estimated date le Completions: Attach wellbore diagram of proposed completion / PXA MUD. CIBP @ 3,690'; WOC & TAG CMT. PLUG @ 3,633'; PRES. UP YLVIA W/ NMOCD - HELD OK; MIX & PUMP A 35 SX. CMT. A 30 SX. CMT. PLUG @ 2,600'; WOC & TAG CMT. PLUG @
13. Describe proposed or completed operations. (Clearly state all pof starting any proposed work). SEE RULE 1103. For Multipor recompletion. 06/16/09: TAG EXISTING CIBP @ 3,690'; CIRC. WELL W 06/17/09: MIX & PUMP A 35 SX. CMT. PLUG CN TOP OF CN 4-1/2" CSG. TO 500# FOR 15 MIN. PER S PLUG @ 3,633'-3,363'(CALC.); MIX & PUMP . 2,210'; PRES. TEST 4-1/2" CSG. TO 500# F	which may be round at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd. pertinent details, and give pertinent dates, including estimated date le Completions: Attach wellbore diagram of proposed completion / PXA MUD. CIBP @ 3,690'; WOC & TAG OMT. PLUG @ 3,633'; PRES. UP YLVIA W/ NMOCD - HELD OK; MIX & PUMP A 35 SX. OMT. A 30 SX. CMT. PLUG @ 2,600'; WOC & TAG CMT. PLUG @ OR 15 MIN. PER SYLVIA W/ NMOCD - HELD OK.
13. Describe proposed or completed operations. (Clearly state all pof starting any proposed work). SEE RULE 1103. For Multipor recompletion. 06/16/09: TAG EXISTING CIBP @ 3,690'; CIRC. WELL W 06/17/09: MIX & PUMP A 35 SX. CMT. PIUG CN TOP OF CN 4-1/2" CSG. TO 500# FOR 15 MIN. PER S PIUG @ 3,633'-3,363'(CALC.); MIX & PUMP 2,210'; PRES. TEST 4-1/2" CSG. TO 500# F 06/18/09: MIX & PUMP A 30 SX. CMT. PIUG @ 1,550';	which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd. pertinent details, and give pertinent dates, including estimated date le Completions: Attach wellbore diagram of proposed completion / PXA MUD. CIBP @ 3,690'; WCC & TAG CMT. PLUG @ 3,633'; PRES. UP YIVIA W/ NMOCD - HELD OK; MIX & PUMP A 35 SX. CMT. A 30 SX. CMT. PLUG @ 2,600'; WCC & TAG CMT. PLUG @ OR 15 MIN. PER SYIVIA W/ NMOCD - HELD OK. WCC & TG CMT. PLUG @ 1,362' (SYIVIA W/ NMOCD OK'D TAG);
13. Describe proposed or completed operations. (Clearly state all pof starting any proposed work). SEE RULE 1103. For Multipor recompletion. 06/16/09: TAG EXISTING CIBP @ 3,690'; CIRC. WELL WO6/17/09: MIX & PUMP A 35 SX. CMT. PLUG CN TOP OF CN 4-1/2" CSG. TO 500# FOR 15 MIN. PER SPLUG @ 3,633'-3,363'(CALC.); MIX & PUMP A 2,210'; PRES. TEST 4-1/2" CSG. TO 500# FOR 15 MIX & PUMP A 30 SX. CMT. PLUG @ 1,550'; MIX & CIRC. TO SURF. A 40 SX. CMT. PLUG	which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd. pertinent details, and give pertinent dates, including estimated date le Completions: Attach wellbore diagram of proposed completion / PXA MUD. CIBP @ 3,690'; WCC & TAG CMT. PLUG @ 3,633'; PRES. UP YIVIA W/ NMCCD - HELD OK; MIX & PUMP A 35 SX. CMT. A 30 SX. CMT. PLUG @ 2,600'; WCC & TAG CMT. PLUG @ OR 15 MIN. PER SYLVIA W/ NMCCD - HELD OK. WCC & TG CMT. PLUG @ 1,362' (SYLVIA W/ NMCCD CK'D TAG); @ 500'-3'; DIG CUT & CUT OFF WELLHEAD 3' B.G.L.; WELD
13. Describe proposed or completed operations. (Clearly state all p of starting any proposed work). SEE RULE 1103. For Multip or recompletion. 06/16/09: TAG EXISTING CIBP @ 3,690'; CIRC. WELL W 06/17/09: MIX & PUMP A 35 SX. CMT. PLUG CN TOP OF CN 4-1/2" CSG. TO 500# FOR 15 MIN. PER S PLUG @ 3,633'-3,363'(CALC.); MIX & PUMP . 2,210'; PRES. TEST 4-1/2" CSG. TO 500# F 06/18/09: MIX & PUMP A 30 SX. CMT. PLUG @ 1,550'; MIX & CIRC. TO SURF. A 40 SX. CMT. PLUG CN STEEL PLATE TO CASINGS & INSTALL DRY	which may be round at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd. pertinent details, and give pertinent dates, including estimated date le Completions: Attach wellbore diagram of proposed completion / PXA MUD. CIBP @ 3,690'; WOC & TAG CMT. PLUG @ 3,633'; PRES. UP YLVIA W/ NMOCD - HELD OK; MIX & PUMP A 35 SX. CMT. A 30 SX. CMT. PLUG @ 2,600'; WOC & TAG CMT. PLUG @ OR 15 MIN. PER SYLVIA W/ NMOCD - HELD OK. WOC & TG CMT. PLUG @ 1,362' (SYLVIA W/ NMOCD OK'D TAG); @ 500'-3'; DIG OUT & CUT OFF WEILHEAD 3' B.G.L.; WEILD HOLE MARKER. WELL PLUGGED & ABANDONED 06/18/09.
13. Describe proposed or completed operations. (Clearly state all pof starting any proposed work). SEE RULE 1103. For Multipor recompletion. 06/16/09: TAG EXISTING CIBP @ 3,690'; CIRC. WELL W 06/17/09: MIX & PUMP A 35 SX. CMT. PLUG CN TOP OF CN 4-1/2" CSG. TO 500# FOR 15 MIN. PER S PLUG @ 3,633'-3,363'(CALC.); MIX & PUMP . 2,210'; PRES. TEST 4-1/2" CSG. TO 500# F 06/18/09: MIX & PUMP A 30 SX. CMT. PLUG @ 1,550'; MIX & CIRC. TO SURF. A 40 SX. CMT. PLUG CN STEEL PLATE TO CASINGS & INSTALL DRY	which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd. pertinent details, and give pertinent dates, including estimated date le Completions: Attach wellbore diagram of proposed completion / PXA MUD. CIBP @ 3,690'; WCC & TAG CMT. PLUG @ 3,633'; PRES. UP YIVIA W/ NMCCD - HELD OK; MIX & PUMP A 35 SX. CMT. A 30 SX. CMT. PLUG @ 2,600'; WCC & TAG CMT. PLUG @ OR 15 MIN. PER SYLVIA W/ NMCCD - HELD OK. WCC & TG CMT. PLUG @ 1,362' (SYLVIA W/ NMCCD CK'D TAG); @ 500'-3'; DIG CUT & CUT OFF WELLHEAD 3' B.G.L.; WELD
13. Describe proposed or completed operations. (Clearly state all pof starting any proposed work). SEE RULE 1103. For Multipor recompletion. 06/16/09: TAG EXISTING CIBP @ 3,690'; CIRC. WELL WORLD OF MIX & PUMP A 35 SX. CMT. PLUG ON TOP OF CN 4-1/2" CSG. TO 500# FOR 15 MIN. PER SPLUG @ 3,633'-3,363' (CALC.); MIX & PUMP 2,210'; PRES. TEST 4-1/2" CSG. TO 500# FOR 15 MIX & PUMP A 30 SX. CMT. PLUG @ 1,550'; MIX & CIRC. TO SURF. A 40 SX. CMT. PLUG CN STEEL PLATE TO CASINGS & INSTALL DRY I hereby certify that the information above is true and complete to the grade tank has been will be constructed or closed according to NMOCD guidely.	which may be round at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd. pertinent details, and give pertinent dates, including estimated date le Completions: Attach wellbore diagram of proposed completion / PXA MUD. CIBP @ 3,690'; WCC & TAG CMT. PLUG @ 3,633'; PRES. UP YLVIA W/ NMCCD - HELD OK; MIX & PUMP A 35 SX. CMT. A 30 SX. CMT. PLUG @ 2,600'; WCC & TAG CMT. PLUG @ OR 15 MIN. PER SYLVIA W/ NMCCD - HELD OK. WCC & TG CMT. PLUG @ 1,362' (SYLVIA W/ NMCCD OK'D TAG); @ 500'-3'; DIG CUT & CUT OFF WELLHEAD 3' B.G.L.; WELD HOLE MARKER. WELL PLUGGED & ABANDONED 06/18/09. The best of my knowledge and belief. I further certify that any pit or below-
13. Describe proposed or completed operations. (Clearly state all pof starting any proposed work). SEE RULE 1103. For Multipor recompletion. 06/16/09: TAG EXISTING CIBP @ 3,690'; CIRC. WELL WO6/17/09: MIX & PUMP A 35 SX. CMT. PIUG ON TOP OF CN 4-1/2" CSG. TO 500# FOR 15 MIN. PER SPLUG @ 3,633'-3,363'(CALC.); MIX & PUMP 2,210'; PRES. TEST 4-1/2" CSG. TO 500# FOR 1500# FOR 15 MIN. PER SPLUG @ 3,633'-3,363'(CALC.); MIX & PUMP 2,210'; PRES. TEST 4-1/2" CSG. TO 500# FOR 1500 CON STEEL PLATE TO CASINGS & INSTALL DRY I hereby certify that the information above is true and complete to the grade tank has been will be constructed or closed a cording to NMOCD guidely SIGNATURE	which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd. pertinent details, and give pertinent dates, including estimated date the Completions: Attach wellbore diagram of proposed completion / PXA MUD. CIBP @ 3,690'; WOC & TAG CMT. PLUG @ 3,633'; PRES. UP YLVIA W/ NMOCD - HELD OK; MIX & PUMP A 35 SX. CMT. A 30 SX. CMT. PLUG @ 2,600'; WOC & TAG CMT. PLUG @ OR 15 MIN. PER SYLVIA W/ NMOCD - HELD OK. WOC & TG CMT. PLUG @ 1,362' (SYLVIA W/ NMOCD OK'D TAG); @ 500'-3'; DIG OUT & CUT OFF WELLHEAD 3' B.G.L.; WELD HOLE MARKER. WELL PLUGGED & ABANDONED 06/18/09. The best of my knowledge and belief. I further certify that any pit or belowines X, a general permit or an (attached) alternative OCD-approved plan
13. Describe proposed or completed operations. (Clearly state all pof starting any proposed work). SEE RULE 1103. For Multipor recompletion. 06/16/09: TAG EXISTING CIBP @ 3,690'; CIRC. WELL W 06/17/09: MIX & PUMP A 35 SX. CMT. PLUG ON TOP OF CN 4-1/2" CSG. TO 500# FOR 15 MIN. PER S PLUG @ 3,633'-3,363'(CALC.); MIX & PUMP 2,210'; PRES. TEST 4-1/2" CSG. TO 500# F 06/18/09: MIX & PUMP A 30 SX. CMT. PLUG @ 1,550'; MIX & CIRC. TO SURF. A 40 SX. CMT. PLUG CN STEEL PLATE TO CASINGS & INSTALL DRY I hereby certify that the information above is true and complete to the grade tank has been will be constructed or closed according to NMOCD guidely SIGNATURE	which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd. pertinent details, and give pertinent dates, including estimated date le Completions: Attach wellbore diagram of proposed completion / PXA MUD. CIBP @ 3,690'; WCC & TAG CMT. PLUG @ 3,633'; PRES. UP YIVIA W/ NMOCD - HELD OK; MIX & PUMP A 35 SX. CMT. A 30 SX. CMT. PLUG @ 2,600'; WCC & TAG CMT. PLUG @ OR 15 MIN. PER SYIVIA W/ NMOCD - HELD OK. WCC & TG CMT. PLUG @ 1,362' (SYIVIA W/ NMOCD OK'D TAG); @ 500'-3'; DIG OUT & CUT OFF WELLHEAD 3' B.G.L.; WELD HOLE MARKER. WELL PLUGGED & ABANDONED 06/18/09. The best of my knowledge and belief. I further certify that any pit or belowines X, a general permit or an (attached) alternative OCD-approved plan TLE
13. Describe proposed or completed operations. (Clearly state all pof starting any proposed work). SEE RULE 1103. For Multipor recompletion. 06/16/09: TAG EXISTING CIBP @ 3,690'; CIRC. WELL WO6/17/09: MIX & PUMP A 35 SX. CMT. PLUG ON TOP OF CN 4-1/2" CSG. TO 500# FOR 15 MIN. PER SPLUG @ 3,633'-3,363' (CALC.); MIX & PUMP A 2,210'; PRES. TEST 4-1/2" CSG. TO 500# FOR 15 MIN. EVIL @ 1,550'; MIX & CIRC. TO SURF. A 40 SX. CMT. PLUG @ 1,550'; MIX & CIRC. TO SURF. A 40 SX. CMT. PLUG CN STEEL PLATE TO CASINGS & INSTALL DRY I hereby certify that the information above is true and complete to the grade tank has been will be constructed or closed according to NMOCD guided SIGNATURE Type or print name DAVID A. EYLER For State Use Only	which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd. pertinent details, and give pertinent dates, including estimated date le Completions: Attach wellbore diagram of proposed completion / PXA MUD. CIBP @ 3,690'; WOC & TAG OMT. PLUG @ 3,633'; PRES. UP YLVIA W/ NMOCD - HELD OK; MIX & PUMP A 35 SX. CMT. A 30 SX. CMT. PLUG @ 2,600'; WOC & TAG CMT. PLUG @ OR 15 MIN. PER SYLVIA W/ NMOCD - HELD OK. WOC & TG CMT. PLUG @ 1,362' (SYLVIA W/ NMOCD OK'D TAG); @ 500'-3'; DIG OUT & CUT OFF WELLHEAD 3' B.G.L.; WELD HOLE MARKER. WELL PLUGGED & ABANDONED 06/18/09. The best of my knowledge and belief. I further certify that any pit or belowines X, a general permit or an (attached) alternative OCD-approved plan TLE