

Submit 3 Copies To Appropriate District Office

District I

1625 N French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1030 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO. 30-025-07200 ✓
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> ✓
6. State Oil & Gas Lease No. B-11589
7. Lease Name or Unit Agreement Name: LEA "AV" STATE ✓
8. Well No 4 ✓
9. Pool name or Wildcat Gladiola Wolfcamp ✓

<p>SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</p> <p>1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/> ✓</p> <p>2. Name of Operator PURVIS OPERATING CO. ✓</p> <p>3. Address of Operator P O Box 51990, Midland, TX 79710-1990</p> <p>4. Well Location Unit Letter: <u>F</u> : <u>1980</u> feet from the <u>North</u> line and <u>1980</u> feet from the <u>West</u> line ✓ Section <u>19</u> Township <u>12S</u> Range <u>38E</u> NMPM Lea County</p> <p>10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3872 GL</p>	
---	--

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Temporarily Abandon ☒

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

6-19-09 Run and set cast iron bridge plug at 9025' (78' above top open perforation).

6-29-09 Load casing with packer fluid and pressure to 530 psig on chart. Lost 30 psi in 30 min. Witnessed by Robert Harrison of OCD. Harrison said pressure test was OK. Took pressure chart to OCD office in Hobbs.

This Approval of Temporary
Abandonment Expires 6-29-2014

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Donnie E. Brown TITLE Petroleum Engineer DATE June 30, 2009

Type or print name Donnie E. Brown

Telephone No. 432-682-7346

APPROVED BY Tim W. Hill TITLE DISTRICT 1 SUPERVISOR DATE JUL 01 2009
Conditions of approval, if any:

