<i>,</i>	<b>y</b>						
Submit 3 Copies To Appropriate District Office District 1	ice Distance Mineral and Network Deserves		Form C-103 June 19, 2008				
1301 W Grand Ave. Artesia NM 88210			30-025-29451 5. Indicate Type of Lease				
1000 Rio Brazos Rd, Aztec, NM 87410 JUL 00 2005 South St. Francis Dr. Santa Fe. NM 87505			STATE FEE X   6. State Oil & Gas Lease No.				
1220 S St Francis Dr , Santa Fe, NHOBL 87505							
SUNDRY NOTICE	7. Lease Name or Unit Agreement Name						
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM G-101) FOR SUCH PROPOSALS )			Reed AXV Com 🧹				
1. Type of Well: Oil Well 🔲 Ga	8. Well Number 1						
2. Name of Operator	9. OGRID Number 255333 /						
3. Address of Operator	10. Pool name or Wildcat						
Heritage Plaz 4. Well Location	Edison; Morrow, North						
Unit Letter: <u>K: 1,870</u> feet from the <u>South</u> line and <u>2,080</u> feet from the <u>West</u> line							
Section 12 Township 15S Range 34E NMPM Lea County							
	1. Elevation <i>(Show whether DR</i> 4,063'						
		· · · · · · · · · · · · · · · · · · ·					
12. Check App	propriate Box to Indicate N	lature of Notice, 1	Report or Other Data				
NOTICE OF INTE	ENTION TO: PLUG AND ABANDON		SEQUENT REPORT OF:				
PERFORM REMEDIAL WORK F TEMPORARILY ABANDON	ALTERING CASING   LING OPNS.   P AND A						
PULL OR ALTER CASING							
OTHER.		OTHER:					
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.							
6/9/09 - Safety meeting – move in, rig u	p – bleed well down – ND well	head – NU BOP – S	DFD.				
6/10/09 - Safety meeting - RIH w/ Gau			15' of cement on top – Weld on pull nipple –				
SDFD. 6/11/09 – Safety meeting – pull stretch	on casing – free @ 6,000' – Ca	ll OCD and office –	RIH and cut casing @ 6,000' – POH w/ TH 3				
C Joints – SDFD.							
6/12/09 - Safety meeting - finish layin 6/15/09 - Safety meeting - RIH w/ 4,44		wind.					
6/16/09 - Safety meeting - RIH and cir 6/17/09 - Safety meeting - RIH and to	culate Plugging Mud – Spot 16	Sacks on top of CIB	P per OCD – WDC – SDFD. t 15 sacks @ 8,780' – PUH – spot 25 sacks @				
6,064' – POH – SDFD.							
6/18/09 – Safety meeting – POH – Lay down 1 ½" tubing – RIH and TAG @ 5,787' – Start out of hole. SDFD due to storm. 6/19/09 – Safety meeting – Spot 25 sacks @ 4,656' – POH – WOC – RIH and Tag @ 4,376' – POH – Spot 40 Sacks @ 2,354' – POH –							
WOC – SDFD		_	- •				
6/22/09 – Safety meeting – RIH and T surface – SDFD	AG (a) $2,151' - POH - RIH$ an	d Spot 45 sacks @	457' – POH – Circulate 15 sacks from 60' to				
6/23/09 – Safety meeting – Rig down –	Dig out Cellar – Cut off Well H	ead – Install PA Ma	rker <u>- Cut off anchors - Move out.</u>				
Well P&A'd on <u>06/23/2009</u> .			Approved for plugging of well bore only. Liability under bond is retained pending receipt				
I hereby certify that the information abo	ve is true and complete to the be	est of my knowledge	and beilef may be found at OCD Web Page under Lorms, www.cmnrd.state.nm.us/ocd.				
SIGNATURE (	TITLE Vice F	President – Operatior	DATE <u>06-30-2009</u>				
Type or print name C. Tim Miller	E-mail address: tmiller@lime	rockresources.com					
Type or print name C. Tim Miller   E-mail address:   tmiller@limerockresources.com   PHONE:   (713) 292-9514     For State Use Only   Miller   DISTRICT 1 SUPERVISOR   DISTRICT 1 SUPERVISOR   DATE   JUL 0 7 2009							
APPROVED BY: Conditions of Approval (if any):	TITLE TITLE		DATE JUL 07 2009				

\_\_\_\_

			~		-nn	~
Сс	onditic	ons of	f App	oroval	(if an	Y)

