Submit 3 Copies To Appropriate District	State of New Me	exico	Form C-103
Office District I	Energy, Minerals and Natural Resources		June 19, 2008
1625 N. French Dr., Hobbs, NM 88240			PI NO.
District II 1301 W. Grand Ave., Artesia, NM 882 FCEMEDNSERVATION DIVISION			30-025-35246
			te Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410UL 07 2009 Santa Fe, NM 87505			TATE FEE X
District IV			Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, N <b>HOBBSOCD</b>			
SUNDRY NOTICES AND REPORTS ON WELLS			Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			binson /
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			,
1. Type of Well: Oil Well X Gas Well Other			Number 1
			D Number /
2. Name of Operator Chesapeake Operating, Inc.			147179
3. Address of Operator P.O. Box 18496			name or Wildcat
Oklahoma City, OK 73154-0496			
Oklahoma City, OK 73154-0496     DK; Drinkard       4. Well Location			
Unit Letter O : 660' feet from the South line and 1980' feet from the East line			
Section 19 Township 20S Range 39 E NMPM County Lea 🗸			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
	3560' GR		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK			
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL			NS. PANDA 🛛
PULL OR ALTER CASING  MULTIPLE COMPL CASING/CEMENT JOB			
		OTHER:	·
OTHER <sup>1</sup>	ted operations (Clearly state all 1		nent dates including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompletion.			
-			
Please find the following work performed in the plug and abandonment of this well from 6/27/09 through 7/01/2009.			
MIRU PU & SE. TOOH w/ produc	tion rods & pump, NDWH, NU I	BOP. Release TAC. TOOH w/	2 7/8" tbg.
TIH w/ wireline & set 5 $1/2$ " CIBP @ 7450' & dump bail 35' of cmt on plug. Wireline set CIBP @ 6800'. TIH w/tbg to 6800'.			
CIRCU hole w/plug mud & spot 25 sxs on plug @ 6800'. PU & spot 25 sxs @ 4909'. PU & spot 25 sxs @ 2933'. PU & spot 25 sxs @			
1667'. WOC & tag @ 1427'. Perf @ 60' & squeeze 15 sxs to surface. ND BOP, NU WH. RDMO.			
Well P&A'd on 7/01/09. Well turned over to production for final clean up.			
which may be found to (OD ) where the plugging)			
Forms, www.smird.state.nm.us/ocd.			
Spud Date:	Rig Release Da	ate:	
_		L	
I hereby certify that the information ab	pove is true and complete to the b	est of my knowledge and belie	f.
0 1			
	J.		
SIGNATURE May Man	TITLE Senior	Regulatory Compl. Sp.	DATE_07/06/2009
Type or print name Bryan Arrant	E-mail address	s: <u>bryan.arrant@chk.com</u>	PHONE: (405)935-3782
For State Use Only DISTRICT 1 SUPERVISOR      0.8 2009			
Conditions of Approval (Alany):			
containe of reprover grang).			