

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised June 10, 2003

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-35947
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Liberty 4
8. Well Number 2
9. OGRID Number 018917
10. Pool name or Wildcat Wildcat Bone Spring
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,629' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
Read & Stevens, Inc.

3. Address of Operator
P. O. Box 1518 Roswell, NM 88202

4. Well Location
Unit Letter **J** : **2020** feet from the **South** line and **2310** feet from the **East** line
Section **4** Township **20S** Range **36E** NMPM County **Lea**

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: Perf/Acidize <input checked="" type="checkbox"/>

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

10/13/03 MIRUSU. Unseat pump. POOH w/ rods, pump. NDWH. RIs TAC. NUBOP. RIH & correlate depth. Perforate 2 spf @ 6,620'-32', 7,702'-08', total of 38 holes. Isolate perfs 7,702'-08' and acidize with 500 gal 15% NEFe HCl via tbq. Swab well recovering an average of 25 BF per hr. Oil cut remain static at no more than 5%. No gas evident. Isolate perfs 6,620'-32' and acidize by pumping 500 gal 15% NEFe HCl via tbq. Swab well to SN in 7 runs recovering 47 BLW. Began making 2 runs per hr averaging 9 BFPH for 3 hrs. Load recovered. No oil or gas show. Day 2, BFL @ 1,300'. No oil on first run. Swab well lowering fluid to SN recovering 36 BW. No oil or gas evident. Lay down 21 jts tbq. Lay down pkr, RBP. RIH w/ BPMA, SN, 196 jts tbq. NDBOP. NUWH. RIH w/ rods. Clamp rods at wellhead. Clean location. RDMOSU. Well SI for evaluation.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *John C. Maxey, Jr.* TITLE **Operations Manager**

Type or print name **John C. Maxey, Jr.**

E-mail address:

Telephone No. **505/622-3770**

(This space for State use)

OC FIELD REPRESENTATIVE II/STAFF MANAGER

APPROVED BY *Larry W. Wink*

TITLE

DATE

Conditions of approval, if any:

JAN 02 2004