

Submit One Copy To Appropriate District Office

State of New Mexico

Form C-103

District I

1625 N French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

Energy, Minerals and Natural Resources

RECEIVED

JUL 10 2009

HOBBSOCD

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

March 18, 2009

WELL API NO.

30-025-30829

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

B-9613

7. Lease Name or Unit Agreement Name

West Dollarhide Drinkard Unit

8. Well Number

107

9. OGRID Number

10. Pool name or Wildcat

Dollarhide Tubbs Drinkard

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: ☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Chevron USA Inc.

3. Address of Operator

P.O. Box 7139, Midland, Tx 79708

4. Well Location

Unit Letter I : 1435 feet from the South line and 1211 feet from the East line

Section 32 Township 24S Range 38E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3191' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ P AND A ☐

CASING/CEMENT JOB ☐

OTHER: ☐

☒ Location is ready for OCD inspection after P&A

- ☒ All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.
- ☒ Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.
- ☒ A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the

**OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.**

- ☒ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.
- ☒ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.
- ☒ If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.
- ☒ All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)
- ☒ All other environmental concerns have been addressed as per OCD rules.
- ☒ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.

When all work has been completed, return this form to the appropriate District office to schedule an inspection.

SIGNATURE Ronnie Hazelwood TITLE Operations Supervisor DATE 7/9/09

TYPE OR PRINT NAME Ronnie Hazelwood E-MAIL: rhazelwood@Chevron.com PHONE: 432-523-5629  
For State Use Only Ext 7602

APPROVED BY: [Signature] TITLE Compliance Officer DATE 7/14/09

Conditions of Approval (if any):

PA OK TO RELEASE BY MW ON 4/22/09

# Print work order cards

<b>Work order</b>	DS10902085	WDDU #107 PA WELL BACKHOE AND GANG	WELDER ,	<b>Target Start Date</b>	02-19-2009	Reprint
<b>Status</b>	Waiting Work Order Completion					

<b>Parent work order</b>	<b>WO type</b> SOM		<b>Class</b>
<b>Department</b>	DOLLARHIDE	Dollar Hide	<b>Priority</b> 4
<b>PM schedule</b>			<b>Warranty</b>
<b>Cost code</b>			<b>Safety</b>
<b>Problem code</b>	INSP	Inspection/Condition Monitoring	<b>Equipment criticality</b> NA
<b>Requested by</b>	HGCF	GALINDO, HUMBERTO	<b>Assigned to</b> DHGNG1
<b>Project</b>			<b>Scheduling group</b>
<b>Standard work order</b>			

<b>Equipment</b>	WDDU (MCA)	FIELD; WDDU
	DOLLARHIDE (MCA)	DOLLARHIDE OPERATIONS

**Manufacturer**  
**Model**  
**Serial number**

<b>Date started</b>		<b>Date completed</b>		<b>Time completed</b>	
---------------------	--	-----------------------	--	-----------------------	--

## WO description

NEED BACK HOE TO SPREAD CALLIGE THAT IS ON THE WESTISDE OF THE LOCATION SMOOTH ON LOCATION  
ABOUT 3 HRS

NEED WELDER TO GO AND CUT UP ABOUT 5 JT OF FLOWLINE THAT IS AT THE NORTH END OF THE LOCTION SO GANG CAN  
HAUL OFF  
ABOUT 3HRS

NEED GANG TO GO AND PICK UP FLOWLINE AFTER THE WELDER CUTS IT UP AND PICK UP TRASH AROUND LOCTION AND  
JUNK IF ANY QUESTION CALL BERT  
ABOUT 3 HRS  
COMPLETED AS WRITTEN

**RECEIVED**  
JUL 10 2009  
HOBBSOC

## Print work order cards

Activity 3				
Work order	DS10902085	Activity 3	Target Start Date	02-19-2009
Trade	ELEC2	Electrician (2 Person Crew)	Duration (days)	1
Estimated hours	3		People req	2

Act Schedule				
Person responsible	Description	Maintenance equipment	Start time	Hours
DHELEC2	DH 2 MAN ELE CREW (DIXIE)		02-19-2009 00:00	3

Booked hours					
Employee	Date	Time on	Time off	Total time	Tariff group

Remarks

# Print work order cards

<b>Work order</b>	DS10902085	WDDU #107 PA WELL BACKHOE AND GANG	WELDER	<b>Target Start Date</b>	02-19-2009	Reprint:
<b>Status</b>	Waiting Work Order Completion					
<b>Parent work order</b>				<b>WO type</b>	SOM	
<b>Department</b>	DOLLARHIDE	Dollar Hide				
<b>PM schedule</b>						
<b>Cost code</b>						
<b>Problem code</b>	INSP	Inspection/Condition Monitoring		<b>Class</b>		
<b>Requested by</b>	HGCF	GALINDO, HUMBERTO		<b>Priority</b>	4	
<b>Project</b>				<b>Warranty</b>		
<b>Standard work order</b>				<b>Safety</b>		
				<b>Equipment criticality</b>	NA	
				<b>Assigned to</b>	DHGNG1	
				<b>Scheduling group</b>		
<b>Equipment</b>	WDDU (MCA)	FIELD; WDDU				
	DOLLARHIDE (MCA)	DOLLARHIDE OPERATIONS				
<b>Manufacturer</b>						
<b>Model</b>						
<b>Serial number</b>						
<b>Date started</b>		<b>Date completed</b>		<b>Time completed</b>		
<b>WO description</b>						

NEED BACK HOE TO SPREAD CALLIGE THAT IS ON THE WESTISDE OF THE LOCATION SMOOTH ON LOCATION  
ABOUT 3 HRS

NEED WELDER TO GO AND CUT UP ABOUT 5 JT OF FLOWLINE THAT IS AT THE NORTH END OF THE LOCTION SO GANG CAN  
HAUL OFF  
ABOUT 3HRS

NEED GANG TO GO AND PICK UP FLOWLINE AFTER THE WELDER CUTS IT UP AND PICK UP TRASH AROUND LOCTION AND  
JUNK IF ANY QUESTION CALL BERT  
ABOUT 3 HRS  
COMPLETED AS WRITTEN

**RECEIVED**  
JUL 10 2009  
HOBBSOCD

## Print work order cards

Activity 2				
Work order	DS10902085	Activity 2	Target Start Date	02-19-2009
Trade	BHOE	Backhoe and Operator	Duration (days)	1
Estimated hours	3		People req	2
Act Schedule				
Person responsible	Description	Maintenance equipment	Start time	Hours
DHBHOE1	DOLLARHIDE BACKHOE No. 1		02-19-2009 00:00	3

Booked hours					
Employee	Date	Time on	Time off	Total time	Tariff group

Remarks

# Print work order cards

<b>Work order</b>	DS10902085	WDDU #107 PA WELL BACKHOE AND GANG	WELDER	<b>Target Start Date</b>	02-19-2009	Reprint
<b>Status</b>	Waiting Work Order Completion					
<b>Parent work order</b>		<b>WO type</b>	SOM	<b>Class</b>		
<b>Department</b>	DOLLARHIDE	Dollar Hide		<b>Priority</b>	4	
<b>PM schedule</b>				<b>Warranty</b>		
<b>Cost code</b>				<b>Safety</b>		
<b>Problem code</b>	INSP	Inspection/Condition Monitoring		<b>Equipment criticality</b>	NA	
<b>Requested by</b>	HGCF	GALINDO, HUMBERTO		<b>Assigned to</b>	DHGNG1	
<b>Project</b>				<b>Scheduling group</b>		
<b>Standard work order</b>						

**Equipment** WDDU (MCA) FIELD; WDDU  
DOLLARHIDE (MCA) DOLLARHIDE OPERATIONS

**Manufacturer**

**Model**

**Serial number**

**Date started**  **Date completed**  **Time completed**

## WO description

NEED BACK HOE TO SPREAD CALLIGE THAT IS ON THE WESTISDE OF THE LOCATION SMOOTH ON LOCATION  
ABOUT 3 HRS

NEED WELDER TO GO AND CUT UP ABOUT 5 JT OF FLOWLINE THAT IS AT THE NORTH END OF THE LOCTION SO GANG CAN  
HAUL OFF  
ABOUT 3HRS

NEED GANG TO GO AND PICK UP FLOWLINE AFTER THE WELDER CUTS IT UP AND PICK UP TRASH AROUND LOCTION AND  
JUNK IF ANY QUESTION CALL BERT  
ABOUT 3 HRS  
COMPLETED AS WRITTEN

**RECEIVED**  
JUL 10 2009  
HOBBSOCD

# Print work order cards

Activity 1				
Work order	DS10902085	Activity 1	Target Start Date	02-19-2009
Trade	GNG3	Gang (3 Person)	Duration (days)	1
Estimated hours	3		People req	3

Act Schedule				
Person responsible	Description	Maintenance equipment	Start time	Hours
DHGNG1	DOLLARHIDE GANG NO. 1 (3 MAN GANG)		02-19-2009 00:00	5

Booked hours					
Employee	Date	Time on	Time off	Total time	Tariff group

Remarks