Submit 3 Copies To Appropriate District State of New Mexico Office Energy, Minerals and Natural Resource	s Form C-103 June 19, 2008
District I	WELL API NO. /
1625 N. French Dr., Hobbs, NM <b>SECENCE</b> District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISIO	N <u>30-025-26561</u> 5. Indicate Type of Lease
1301 W. Grand Ave., Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410L 15 (201) 220 South St. Francis Dr. Santa Fe, NM 87505	STATE FEE XX
District IV 1220 S St. Francis Dr, Santa Fe, NHOBBSOCD 87505	6. State Oil & Gas Lease No.
1220 S St. Francis Dr , Santa Fe, NMS COC C C C S St. Francis Dr , Santa Fe, NMS C C C C C C C C C C C C C C C C C C C	0. State off te Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	TOA 7. Lease Name or Unit Agreement Name: West Lovington Strawn Unit
1. Type of Well:     Oil Well     XX     Gas Well   Other	8. Well Number 26
2. Name of Operator	9. OGRID Number 162928
Energen Resources Corporation       3. Address of Operator	102 920
3300 N. 'A', Bldg 4, Ste 100, Midland, TX 79705	Lowington Strawn West
4. Well Location / e <sup>LeD</sup>	
Unit Letter P: <u>662</u> feet from the South line	and <u>660</u> feet from the East line
	5 E NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.) Gr: 3956'	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
12. Check Appropriate Box to indicate Nature of N	once, Report, of Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
OTHER: OTHER:	
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.</li> </ol>	
See attached procedure	
The Oil Conservation Division Must be notified	
24 hours prior to the beginning of plugging operations	
Spud Date: Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my kr	owledge and belief.
SIGNATURE Main DATE 07-13-09	
Type or print name Tracie J Cherry       E-mail address:       PHONE 432/684-3692	
For State Use Only MICH I AP	
APPROVED BY Aley Alaw TITLE Compliance Officerdate 7/16/2009	
Conditions of Approval (if any):	
V	

J

# ENERGEN RESOURCES CORPORATION

## WLSU # 26

## 662' FSL, 660' FEL, Sec. 32, T-15-S, Rge- 35-E West Lovington Strawn Field Lea County, New Mexico

### P&A Well

Date: July 1, 2009

AFE No: PB070109

Cost: \$35,000

WI: 89.976573855% NRI: 73.977906%

See Attached Wellbore Diagrams:

Plugging Procedure:

- 1. RIH w/ tbg to PBTD. Fill hole with PB Mud.
- 2. Spot cement plug @ 9,200'. Fill hole w/ MLF to 6,000'
- 3. Spot cement plug @ 6,200'. Fill hole w/ MLF to 4,000'
- 4. Perforate casing @ 4,781" with 4 squeeze holes.
- 5. Squeeze 60 sx cement through perfs @ 4,781'.
- 6. Tag cement plug. Circulate MLF to 1,700'.
- 7. Perforate casing @ 1,850" with 4 squeeze holes.
- 8. Squeeze 60 sx cement through perfs @ 1,850'.
- 9. Tag cement plug. Circulate MLF to 350'
- 10. Perforate casing @ 452' with 4 squeeze holes.
- 11. Circulate cement to surface cement through perfs.
- 12. Top off casing with cement.
- 13. Cut off wellhead 3' from surface and weld on P&A marker.

PERF@ 2900'. SQZ 60 SKS CMT. WOC & TAG.



1 1 1