

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD-HOBBS

FORM APPROVED
OMB No 1004-0137
Expires March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.
NMLC 030556-B

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well

☒ Oil Well

☒ Gas Well

☐ Other

2. Name of Operator

APACHE CORPORATION

3a. Address

6120 S. Yale, Ste 1500
Tulsa, OK 74136

3b. Phone No. (include area code)

(918) 491-4900

7. If Unit of CA/Agreement, Name and/or No.

8. Well Name and No
Stevens "B" #6

9. API Well No
30-025-10709

10. Field and Pool or Exploratory Area
Jalmar, Tan-Yates-7 Rivers (Gas)

11. Country or Parish, State
Lea County, NM

Langlie, Matt
7 Rivers
Grayburg

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation. Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

6/16/09 MI RU

6/17/09 Circulated well w/ 95bbl of MLF. Tag CIBP @ 3,600'.

6/17/09 Spot 25sx cmt @ 3,600'. WOC-Tag @ 3,353'.

6/17/09 Spot 25sx cmt @ 2,885'. WOC-Tag @ 2,650'.

6/18/09 Spot 40sx cmt @ 1,613' to 1,218'.

6/18/09 Spot 40sx cmt @ 403' to surface.


6/18/09 RD MO.

RECEIVED

JUL 16 2009

HOBBSOCD

Cut off WH + anchors. Install dry hole marker.



14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

GARY EGGLESTON

Title P&A SUPERVISOR

Signature

Date 06/24/2009

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

DISTRICT 1 SUPERVISOR

Date JUL 17 2009

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.