Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103	
<u>District I</u> Er	nergy, Minerals and Natural Resources		
1625 N. French Dr., Hobbs, NM 88240 WELL API NO.			
District II 1301 W. Grand Ave., Artesia, NM CONSERVATION DIVISION		30-025-38241	
1301 W. Grand Ave., Artesia, NM CECETOE CONSERVATION DIVISION District III T220 South St. Francis Dr.		5. Indicate Type of Lease STATE ☐ FEE 🛛 ✓	
District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV JUL 2 3 2009 Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM			
87505 HOBBSOCD SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name or Unit Agreement Name	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		Pearl 26 State	
PROPOSALS.)		8. Well Number	
1. Type of Well: Oil Well X Gas Well Other		1	
2. Name of Operator Mewbourne Oil Company		9. OGRID Number	
3. Address of Operator		14744 10. Pool name or Wildat	
PO Box 5270 Hobbs, NM 88240		Pearl Bone Springs	
4. Well Location		1 car bone Springs	
/			
Unit Letter G: 1980 feet from the N line and 1800 feet from the E line			
Section 26 Township 19S Range 35E NMPM Lea County			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
3695' GL Pit or Below-grade Tank Application or Closure			
District Note the first water			
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF			
	_	UBSEQUENT REPORT OF:	
_	AND ABANDON REMEDIAL W	ORK ALTERING CASING	
TEMPORARILY ABANDON CHAN	GE PLANS COMMENCE	DRILLING OPNS. P AND A	
PULL OR ALTER CASING MULT	PLE COMPL CASING/CEM	IENT JOB	
OTHER: Bone Springs Completion Sundry			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompletion.			
1 27 00 POOII w/th a Caticalation when @ 122501 /251			
1-27-09 POOH w/tbg. Set isolation plug @ 12350' w/35' cement. (Top Morrow perf @ 12432'). Perforate Bone Springs @ 10628-694'. (46', 1 SPF, 49 holes). RIH w/tbg. Acidize w/5000 gals 15% HCL & ball sealers. Swab test.			
2-6-09 Swab test results 160 bbls/12 hrs w/3% oil cut. POOH. Set isolation plug @ 10610' w/15' cement. Perforate Bone Springs @			
10500-10512' (12', 2 SPF, 24 holes). Frac w/1500 gals 15% HCl., 35000 gals WF 25 w/20000# 20/40 sands.			
2-10-09 RIH w/tbg & swab test.			
2-13-09 Swab test results 5 bbls/12 hrs w/30	% oil cut & gas TSTM.		
2-15-09 POOH w/tbg. ND BOP & NU well head. SWI for evaluation.			
TI I CO I AND I CO			
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines \Box , a general permit \Box or an (attached) alternative OCD-approved plan \Box .			
general permit or an (attached) afternative OCD-approved plan			
SIGNATURE CACLE FA	TITLE_Hobbs Regulatory	DATE 07/08/09	
Type or print name Jackie Lathan	E-mail address:	Telephone No. 505-393-5905	
For State Use Only			
APPROVED BY:	TITLE PETROLEUM E	NGINEER DATE UL 27 2009	
Conditions of Approval (if any):	DAIRUICILO		