Submit 3 Copies 10 Appropriate District State of New Mexico	Form C-103	
District 1 1625 N. French Dr., Hobbs, NM 88240 Energy, Minerals and Natural Resources	S June 19, 2008 WELL API NO.	
District II 1301 W. Grand Ave, Artesia, NM 88210 OIL CONSERVATION DIVISION	30-025-33424	
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease FED X STATE FEE	
1000 Rio Brazos Rd , Aztec, NM 87410Santa Fe, NM 87505District IV	6. State Oil & Gas Lease No.	
1220 S St Francis Dr., Santa Fe, NM 87505		
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Thistle Unit	
PROPOSALS.) 1. Type of Well: Oil Well x x Gas Well Other	8. Well Number #2	
2. Name of Operator	9. OGRID Number	
State of New Mexico/ formerly C W Trainer	3474	
3. Address of Operator	10. Pool name or Wildcat	
1625 N. French Drive Hobbs, NM 88240	Binninstool, Wolfcamp,West	
4. Well Location		
Unit Letter_E_: 1980_feet from theNorth line and660feet from theWest _line         Section 28       Township 23S       Range 33E       NMPM       Lea       County		
11. Elevation (Show whether DR, RKB, RT, GR,		
12 Check Appropriate Boy to Indicate Nature of Not	ice Report or Other Data	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A		
DOWNHOLE COMMINGLE		
	_	
OTHER: OTHER: OTHER:	s and give pertinent dates including estimated date	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion		
or recompletion.		
AMENDED C-103 WITH ADDITIONS FROM WESLEY INGRAM—BLM		
1. Set 7" CIBP at 11,500' and spot 25 sxs cmt on top of CIBP.		
2. Cicr hole w/ plugging mud (9.5 ppg brine w/12.5 lbs salt gel per bbl.		
3. Spot 40 sxs Class H cmt @9127'.		
<ol> <li>Spot Class H cmt 8150' to 7950'.</li> <li>Perf at 5051' and sqz w/ 35 sxs Class C cmt. WOC and TAG. (Int. shoe plug</li> </ol>	x)	
6. Perf at 1300' and sqz w/35 sxs Class C cmt. WOC and TAG, (TOS)		
7. Perf at 655' and sqz w/30 sxs Class C cmt. WOC and TAG. (Surface shoe)		
<ol> <li>Perf at 60' and circ cmt to surface, inside and outside.</li> <li>Cut off wellhead and anchor. Install dry hole marker.</li> </ol>		
9. Cut off wellhead and anchor. Install dry hole marker.		
	Oil Conservation Division Must be notified	
	ours prior to the beginning of plugging operations.	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
MINHK. J / I' Oli Montono		
SIGNATURE Maker Altrown TITLE Compliances Officer Date 7/29/2009		

Type or print name	E-mail address:	PHONE:
For State Use-Only		
APPROVED BY Alex Drown	TITLE COMPLIANCE Officer	DATE 7/29/2009
Conditions of Approval (if any):		