rew Mexico Oil Conservation Division, District 1

Form 3160-5 (February 2005)

UNITED STATES Т

Cut off well head and weld on dry hole marker.

1625 N. French Drive Hobbs, NM 88240

FORM APPROVED OMB No 1004-0137

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMEN

Expires. March 31, 2007 5. Lease Serial No. NMNM 03431

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.			7	Indian, Allottee or Tribe Name	
SUBM	T IN TRIPLICATE - Other inst	ructions on page 2.	7. If Unit of CA	/Agreement, Name and/or No.	
I. Type of Well Gas Well Other		8 Well Name a	nd No. Cruces "B" #3		
2 Name of Operator Kerns Petroleum, I	nc.		9. API Well No	-041-00236 /	
3a. Address		Phone No. (include area co	ode) 10. Field and Po	ool or Exploratory Area par	
1777 NE Loop 410, San	Antonio, TX 78217	210-829-7881	All	ison Penn	
4. Location of Well (Footage, Sep., T.			II Country or I		
1830' FNL, 660' FWL, S	ec. 30, T08S, R37E	Writ. H	Roose	velt County, NM ✓	
	CK THE APPROPRIATE BOX(E		E OF NOTICE, REPORT OR	OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent Subsequent Report	Acidize Alter Casing Casing Repair Change Plans	Deepen Fracture Treat New Construction Plug and Abandon	Production (Start/Resurble Reclamation Recomplete Temporarily Abandon	me) Water Shut-Off Well Integrity Other	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal		
the proposal is to deepen direction Attach the Bond under which the following completion of the invol	nally or recomplete horizontally, g work will be performed or provide ved operations. If the operation re Abandonment Notices must be fi or final inspection.)	tive subsurface locations and e the Bond No. on file with esults in a multiple completi	I measured and true vertical de BLM/BIA. Required subseque on or recompletion in a new in	ed work and approximate duration thereof. It epths of all pertment markers and zones, ent reports must be filed within 30 days atterval, a Form 3160-4 must be filed once we been completed and the operator has	
·					
2. Circulate 3. Perf @ 4. Cut and 5. Set 150	IBP @ 9,500' with 35' c e Hole with mud-laiden f 7,000' and squeeze 35 s pull 5-1/2" casing @ ± 4 sx cement from 4,450-4	fluid. sx cement from 7,00 4,400'. 1144'; tag	00-6,900'; tag.	RECEIVED JUL 30 2009	
7. Cut and 8. Set 65 s	x cement at 2,310-2,210 pull 8-5/8" casing, 65 sx cement @ 433-333'; tx cement @ 60' to surfa	x cement @ stub w/ ag.	50' in and 50' out.	HOBBSOCD	

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	ROSWELL FIELD OFFICE	
/S/ DAVID R. GLASS	PETROLEUM ENGINEER	JUL 2 4 2009
THIS SPACE FOR FEDERA	L OR STATE OFFICE USE	
Signature Junya Johnston Date	July 14, 2009	
14. Thereby certify that the foregoing is true and correct. Name (Printed/Typed) Kerry Johnston Tul	· Vice President	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section-1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

10.

DISTRICT 1 SUPERVISOR

SEE ATTACHED FOR CONDITIONS OF APPROVAL

BUREAU OF LAND MANAGEMENT

Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201 (575) 627-0272

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

- 1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon. If you are unable to plug the well by the 90th day provide the BLM Roswell Field Office, prior to the 90th day, with the reason for not meeting the deadline and a date when the BLM Roswell Field Office can expect the well to be plugged. Failure to do so will result in enforcement action.
- 2. <u>Notification:</u> Contact the BLM Roswell Field Office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, during office hours call (575) 627-0205 or after office hours call (575) 910-6024. Engineer on call during office hours phone (575) 627-0275 or phone (after hours) call (575) 626-5749.
- 3. <u>Blowout Preventers:</u> A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9090 feet; a 3M system for a well not deeper than 13636 feet; and a 5M system for a well not deeper than 22727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at a rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement:</u> Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 50 feet of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either class "C" for up to 7500 feet of depth, mixed at 14.8 lbs./gal with 6.3 gallons of fresh water per sack or class "H" for deeper than 7500 feet plugs, mixed at 16.4 lbs./gal with 4.3 gallons of fresh water per sack.

- 6. Monument: Upon abandonment of the well, all casing shall be cut-off at the base of the cellar or 3-feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. The following information shall be permanently inscribed on the dry hole marker: Well name and number, the name of the operator, the lease serial number, the surveyed location (the quarter-quarter section, township and range or other authorized survey designation acceptable to the authorized officer; such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to the BLM Roswell Field Office. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged.</u>

Following the submittal and approval of the Subsequent Report of Abandonment, a Notice of Intent for Final Abandonment with the proposed surface restoration procedure must be submitted for approval.