Submit 3 Copies To Appropriate District	State of New Mexico		Form C-103
Office District I	Energy, Minerals and Natural Resources		June 19, 2008 WELL API NO.
1625 N French Dr., Hobbs, NM 88240 District II			3000500674
1301 W. Grand Ave., Artesia, NM			5. Indicate Type of Lease
District III 1000 Rio Brazos Rd, Aztec, NM 8741 AUG 10 2009 Santa Fe, NM 87505			STATE S FEE 6. State Oil & Gas Lease No.
1220 S St. Francis Dr., Santa Fe, NM 87505			E-8665
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name SOUTH CAPROCK QUEEN UNIT
PROPOSALS)  1. Type of Well: Oil Well			8. Well Number 003
2. Name of Operator Kevin O. Butler and Associates, Inc.			9. OGRID Number
3. Address of Operator			10. Pool name or Wildcat
P. O. Box 1171; Midland, TX 79702		8559 CAPROCK QUEEN	
4. Well Location			
Unit Letter C 330 feet from the NORTH line and 1633 feet from the EAST line Section 31 Township 15S Range 31E			
NMPM CHAVES County  11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
	,		1,05,124
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WOR		K ⊠ ALTERING CASING □	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL	CASING/CEMEN	I JOB
DOWNHOLL COMMINGEL			
OTHER:		OTHER.	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
9 5/8 SURFACE CSG SET @245'. CMT CIRC 5 1/2" PROD CSG SET @3059' TOC?			
PERFS 2991' – 2998' TOS 1200' BOS 2078'.			
A NARY TO DAY MARY			
<ol> <li>MIRU TO P/A WELL.</li> <li>COULD NOT GET PKR BELOW 1800' WHILE CHECKING CASING INTERGRITY REQUEST FOREGO CIBP AND</li> </ol>			
REPLACE WITH 25 SACKS OF CEMENT ACROSS PERFS			
3. CIRC HOLE W/MFL (9.5 PPG BRINE 7W/125.5 LLBS PER BBL OF SALT GEL.			
4. PERF AT 2100', SQZ 25 SXS CMT. WOC AND TAG (BOS PLUG). 5. PERF AT 1150', SQZ 25 SXS CMT. WOC AND TAG (TOS PLUG).			
6. PERF AT 295', (50' BELOW SURFACE SHOE). SQZ 25 SXS CMT AND WOC AND TAG AT 195' OR SQZ			
SUFFICENT CMT INSIDE AND OUTSIDE TO CIRC TO SURFACE. (SHOE AND SURFACE). 7. CUT OFF WELLHEAD AND ANCHORS, INSTALL DRY HOLE MARKER.			
8. CLEAN LOCATION.			
The Oil Conservation Division <b>Must be notified</b> 24 hours prior to the beginning of plugging operations			
Spud Date:	Rig Release Da	<del>-</del>	
Spud Date.	Kig Kelease De		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE TITLE President/Owner DATE 07/28/2009			
Type or print name Kevin O. Butler E-main address: Lisa@geedmidland.com PHONE: 432-682, 178 For State Use Only			
APPROVED BY! Valey HS 10wn TITLE (OM PLANCE SECUNDATE 7/29/2009			
Conditions of Approval (if any): (Verbal i fax COPY) HARD COPY REC. 8/10/2009			
7/29/2009			

KEVIN O BUTLER & ASSOCIATES

SOUTH CAPROCK QUEEN UNIT #003

C-31-15-31

