08/27/2009 THU 13:31 FAX 4325862453 MARRS MAYO CASING

Submit 3 Copies To Appropriate District Office State of New Mexico	Form C-103
District 1 Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240	June 19, 2008 WELL 30-025-25702API NO.
District II	WELL 30-023-23 /02AFT NO.
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd, Aztec, NM 87410 District IV Santa Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.
1220 S, St. Francis Dr., Santa Fe, NM 87505	L-6315
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name LEA, 7406 JV-S
1. Type of Well: Oil Well Gas Well Other	8. Well Number 002
2. Name of Operator BTA OIL PRODUCERS	9. OGRID Number 003019
3. Address of Operator 1045 SOUTH PECOS MIDLAND, TX 79701	10. Pool name or Wildcat SCARBOROUGH, WEST
4. Well Location	
Unit Letter N : 2310 feet from the WEST line and 330 feet from the SOUTH line	
Section 28 Township 26S Range 36E NMPM LEA	County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WORK ☐ ALTERING CASING ☐	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A PULL OR ALTER CASING. MULTIPLE COMPL CASING/CEMENT JOB	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN DOWNHOLE COMMINGLE	TJOB []
OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
1) MIRU-PLUGGING EQUIPMENT AND STEEL PITS	
2) ND WELLHEAD-NU BOP-SET CIBP @ 3115'-CIRC PLUGGING MUD-SPOT 15 SXS ON TOP CIBP 3) SPOT 25 SXS @2204' SQUEEZE	
4) PERF AND SPOT 30 SXS @ 1454 1464 - WOC-1 AG	
5) PERF AND SPOT 20 SXS @ 60° AND CIRCULATE TO SURFACE — WOC + TAG 6) CUT OFF WELLHEAD, CUT OFF ANCHORS. COVER CELLAR, CLEAN LOCATION, AND MOVE OUT	
J.	
SQUEEZE	
V. DI 15 11/1 1 1 0 mg/ o 100 Tio	
* PERF. + Squezze Water board plug @ 550: 30 sx. WOC-TAG	
Spud Date: Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE Many Beston TITLE President	DATE 8-24-09
Type or print name Monty Beckham E-mail address:	PHONE: <u>575-390-2</u> 07
APPROVED BY: TOTALE DISTRICT 1 SUPERVISOR DATE AUG 28 2009	
Conditions of Approval (if any):	