Submit 3 Copies To Appropriate District State of New Mexico	Form C-103
District I	June 19, 2008 WELL API NO.
1625 N French Dr., Hobbs, NM RECEIVEONSERVATION DIVISION District II 1301 W Grand Ave., Artesia, NM 88210	30-025-34815 5. Indicate Type of Lease
1301 W Grand Ave., Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 8744016 3 1 2009 ¹²²⁰ South St. Francis Dr. Santa Fe, NM 87505	STATE X FEE
District IV 1220 S St. Francis Dr., Santa Fe, HOBBSOCD	6. State Oil & Gas Lease No.
87505	24636
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name:
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Mayfly 14 State
1. Type of Well: Oil Well 🕱 Gas Well 🗌 Other	8. Well Number 5
2. Name of Operator	9. OGRID Number
EOG Resources, Inc.	7377
3. Address of Operator P.O. Box 2267 Midland, TX 79702	10. Pool name or Wildcat
4. Well Location	· Size fair, Scrawn, Withwest
Unit Letter : 330 feet from the line and feet from the line	
Section 14 Township 16S Range 35E NMPM County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
10. Cl. 1. A	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
	ILLING OPNS. 🔲 P AND A 🗌
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	т јов
OTHER: Plugback and Squeeze 7" leak IX OTHER:	
 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 	
1. RIH and set 7" CIBP at +/- 10540'.	
 Spot 192' cement plug from +/- 10540' to 10348' with 35 sx Class H, 15.6 ppg, 1.18 yield. Trip out of hole. 	
3. Trip out of hole. 4. RIH and locate and repair leaks in 7" casing with previously located leak at 5780'.	
5. Shut in to evaluate recompletion potential.	
Spud Date: Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE The Wagner TITLE Regula	atory Analyst DATE 8/28/09
Type or print name Stan Wagner E-mail address:	PHONE <u>432.686.3689</u>
For State Use Only PETROLEIN	MENGINEER SEP012009
APPROVED BY TITLE	DATE
Conditions of Approval (if any):	

.

Mayfly "14" State Com No. 5 Lea County, New Mexico Northwest Shoe Bar API 30-025-34815 Plug & Abandon the Cisco and Strawn Perforations

Wellbore:

13 38" 48# H40 STC surface casing @ 465'. Cemented to surface. 9 5/8" 40# J55 intermediate casing @ 4,760'. Cemented w/ 1,710 sacks. Ran 1" to 870' & circulated cement..

7" 23#, 26# 29# production casing set @ 11,475'. TOC @ 9,170'.

Perforations:

Cisco: 10,870' – 10,892' Strawn: 11,300' – 11,390' overall

Completion Status:

Cisco & Strawn co-mingled. Well on pump.

History:

Probable 7" casing leak w/ trace of H2S.

- 7/2/09 Pump stuck. Jarred rods loose. Left parted pull rod & pump in hole. Unable to release TAC.
- 7/6/09 Unable to jar TAC free. Moved 7" uphole.
- 8/13/09 RIH w/ wire line. Located TAC @ 10,775' w/ 15 joints of tubing below TAC then SN. Top of pump @ 11,302' & stuck in seating nipple. RIH w/ free point tools. Tubing stuck @ 10,650'. Free @ 10,584'.
- 8/14/09 Chemical cut 2 7/8" tubing @ 10,560'
- 8/15/09 RIH w/ 5 3/4" overshot. Shut down.
- 8/16/09 No activity.
- 8/17/09 No activity.
- 8/18/09 RIH w/ 5 ¾" overshot. Set down @ 5,814'. Unable to rotate & wash down. Took 15,000# to pull free. Lay down 5 ¾" overshot. TIH w/ 4 ¾" bit to 10,531'. TOOH.
- 8/19/09 TOOH & lay down 4 ¾" bit. TIH w/ 5 ¾" tapered mill. Unable to circulate. Pump down tubing & annulus. Wash & mill to 5,950'. Tubing stuck. Pulled 30,000# over sting weight. Jarred twice & came free. Reciprocated tubing w/ 1 joint. Pulled free. TOOH.
- 8/20/09 TOOH. Lay down 5 ³/₄' tapered mill. No marks. TIH w/ 6" bit. Set down w/ 20,000# @ 5,837'. Washed & drilled 6,131' & fell through. Established full returns. Circulated bottoms up. Recovered black rubber pieces, LCM & minimal scale. TIH to 10,540'. TOF @ 10,560'.Reverse circulate bottoms up. Recovered 3 gallons of iron sulfide sediments. CO2 max. 236 ppm. TOOH.

- 8/21/09 FOOH. Normal wear on bit. TIH w/ 5 ¾" overshot. Tagged @ 10,540'. Unable to get over TOF. Pick up power swivel. Established circulation. Wash over & latch onto fish @ 10,560'. Set off jars w/ 100,000# pull. Pulled loose. Had additional 4,500# string weight. Able to go down hole 15'. Washed 4 full joints out of hole. TOOH without washing.
- 8/22/09 FOOH. No recovery. No marks on grapple or O.D. of overshot. TIH w/ 4 11/16" overshot. Tagged @ 10,561'. Pick up power swivel. Reverse circulate. Set down to wash over fish & immediately plugged overshot. Unable to clear tubing w/ 4,000 psi.
- 8/23/09 TOOH pulling wet. Found large quarter size pieces of shale like rocks had plugged jars & 1 joint of 2 7/8" tubing. TIH w/ 7" casing scraper to 7,653'. No indications of scraping casing. Picked up & tubing was stuck from above. Pulled 90,000# & tubing slowly came free after working tubing 12' up hole. TOOH. Lay down casing scraper. No marks on scraper.
- 8/24/09 TIH w/ 7" packer. Set packer @ 5,797'. Load annulus w/ 67 barrels fresh water. Began pumping into annulus @ 4 bpm W 300 psi. Reset packer @ 5,735'. Tested annulus to 1,000 psi w/ no leak off. Reset packer @ 5,767'. Test annulus to 1,000 psi. Established top of hole @ 5,780'. POOH. LD work string.
- 8/25/09 ND BOP's. NU 900 series 3,000 psi flange w/ valve. Rig down.

Fish:

½ joint of 2 7/8" 6.50# N80 EUE tubing
6 joints of 2 7/8" 6.50# N80 EUE tubing
7" TAC
15 joints of 2 7/8" 6.50# N80 EUE tubing
Seating nipple w/ pump stuck inside

Procedure:

- Rig up wireline. Run in the hole with a 5.71" gauge ring / junk basket to the top of the 2 7/8" tubing fish @ 10,560'. Run in the hole with a 7" 29# 10,000 psi Cast Iron Bridge Plug (HES running O.D. 5.610"). Tag the top of the fish @ 10,560'. Pick up & set the CIBP @ +/-10,540'. Top Cisco perforation is at 10,870'.
- 2. TIH w/ collar & 2 7/8" tubing. Tag the CIBP @ +/-10,540.
- Spot a 192' cement plug from +/-10,540' to 10,348' with 35 sacks (7.375 barrels) of Class "H" cement mixed @ 15.6 ppg. Yield 1.18 cf/sk. BHT 150 degrees @ 11,475'.
- 4. Trip out of the hole.
- 5. Continuing operations will be to locate, squeeze & pressure test the hole(s) in the 7" casing with the top leak previously located at 5,780'.
- 6. An upper interval is being evaluated for recompletion after plugging and abandoning the Strawn & Cisco and the squeezing the 7" casing leak.

WELL STATUS MAYFLY "14" STATE COM #5

