Submit 3 Copies To Appropriate District Office	State of New Mex		26068	Form C-103 June 19, 2008
District I Energy, Minerals and Natural Resources		WELL 3	30-025-28702API NO	
District II 1301 W. Grand Ave, Artesia, NN CE CEIVE CONSERVATION DIVISION			ate Type of Lease	
District III Plant of Page 1220 South St. Francis Dr.			TATE FEI	
1220 S. St. Francis Dr., Santa Fe, NOPRSOCD			Oil & Gas Lease No	
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C 101) FOR SUCH		G BACK TO A LEA, 74	7. Lease Name or Unit Agreement Name LEA, 7406 JV-S	
PROPOSALS.)  1. Type of Well: Oil Well  Gas Well  Other /			Number 009Y	$\checkmark$
2. Name of Operator BTA OIL PRODUCERS			VID Number 00301	9
3. Address of Operator			10. Pool name or Wildcat  COMANCHE STATELINE -YATES	
1045 SOUTH PECOS MIDLAND, TX 79701			NCHE STATELINE	-TATES
4. Well Location Unit Letter D: 99	00_feet from theWEST1	line and · 700 feet from	theNORTH	_line
Section 28 Townsh	nip 26S Range 36E N	IMPM LEA Coun		
	11. Elevation (Show whether DR,	RKB, RT, GR, etc.)		
12. Check Ap	opropriate Box to Indicate Na	ature of Notice, Report of	or Other Data	
NOTICE OF INT	·		ENT REPORT C	F:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WOF			☐ ALTERIN	G CASING 🔲
TEM OF CHARLES AND COLOR		COMMENCE DRILLING OF CASING/CEMENT JOB	PNS.□ PANDA	
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL []	CASING/CEMENT 30B		
	П	OTHER:		П
OTHER:  13. Describe proposed or comple	ted operations. (Clearly state all p	pertinent details, and give per	rtinent dates, includir	g estimated date
of starting any proposed wor or recompletion.	k). SEE RULE 1103. For Multipl	le Completions: Attach well	bore diagram of prop	osed completion
1) MIRU-PLUGGING EQUIPM	MENT AND STEEL PITS	25		
2) ND WELLHEAD-NU BOP-	SET CIBP @ 3109'-CIRC PLUG	GING MUD-SPOT 😿 SXS	ON TOP CIBP	
3 <del>) SPOT 25 SXS @ <u>2</u>207'</del> (4) PERF AND SPOT 30 SXS @	1450' WOC FTAG			
5) PERF AND SPOT 20 SXS (a	0 60' AND CIRCULATE TO SUI	RFACE	I AND MOVE OUT	
	T OFF ANCHORS. COVER CEI	LLAR, CLEAN LOCATION	H-Doul & SOZ	4 <b>7</b> 0 5 5 5 .
8 <sup>5</sup> /8@ 1400' 5 <sup>1</sup> /2@ 3270' (TOC	./\		@14	3050 150' WOCFTAL
51/2@ 3270' (TOC	2375 The Oil Conserva	tion Division <b>Must be notif</b>	ied	0'-
T SALT 2207 B.	24 hours prior to SALT 2817	o the beginning of plugging (	operations. ; Per	4@59730sx
ישור איניין איניין	2010		@5	50' WOLF TAG
			<del></del> 1.	
Spud Date:	Rig Release Da	ite:	\ 	
I hereby certify that the information a	bove is true and complete to the be	est of my knowledge and bel	ief.	
SIGNATURE Moto Kell	TITLE /	usilet	DATE_	-24-09
Type or print name Monty B		•	PHONE: <u>く</u>	:75-390-2076
For State Use Only	$oldsymbol{\wedge}$			
APPROVED BY: Make	hitale TITLE CO	upliance Officer	<u>— </u> рате <u>09</u>	102/2009
Conditions of Approval (if any):		ų .	,	