

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED  
SEP 17 2009  
HOBSBOLD

CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-025-03494
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-392
7. Lease Name or Unit Agreement Name State KT
8. Well Number 24-1
9. OGRID Number 264953
10. Pool name or Wildcat Eumont Yates 7 Rivers Queen
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,637' KB 3,627' GL

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well  Gas Well  Other

2. Name of Operator Herman L. Loeb LLC

3. Address of Operator  
P O Box 838 Lawrenceville, IL 62439

4. Well Location  
Unit Letter J Section 24 Township 21S Range 35E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
3,637' KB 3,627' GL

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion

- Set cast iron bridge plug @ 3490', RIH w/ tbg to 3,490', spot 25 sk of cement on plug, POH w/ 7 jts tbg, spot 33 bbl of mud-laden water, POH w/ tbg.
- Perforate 2 holes @ 1,910', RIH w/ tbg & packer; set pkr @ 1,400', attempt to squeeze w/ 100 sk cement to fill 1,910' to 1,620'. Displace cement to 1,600'. WOC release pkr, RIH w/ tbg & tag.
- Perforate 2 holes @ 365', attempt to circulate cement to the surface. WOC.
- Cut off well head 3' below ground level, top off casing & annulus as necessary. We plan to start this work as soon as the procedure is approved.

The Oil Conservation Division **Must be notified 24 hours prior** to the beginning of plugging operations.

Spud Date:  Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Petroleum Engineer DATE 9/10/09

Type or print name G. A. Payne E-mail address: gapayne@sigeocom.net PHONE: 812.453.0385

For State Use Only  
APPROVED BY: [Signature] TITLE Compliance Officer DATE 09/15/2009

Conditions of Approval (if any):

