

Submit 3 Copies To Appropriate District

Office

District I

1625 N. French Dr., Hobbs, NM 88249

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM

87505

State of New Mexico

Geology, Minerals and Natural Resources

Form C-103

June 19, 2008

RECEIVED

SEP 18 2009

HOBBSOCD

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

WELL API NO

30-025-37466

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

35120

7. Lease Name or Unit Agreement Name

Twitty BHF State

8. Well Number

1

9. OGRID Number

168906

10. Pool name or Wildcat

Wildcat Strawn

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other

2. Name of Operator

GMX Resources Inc.

3. Address of Operator

9400 No Broadway, Suite 600 Oklahoma City, OK 73114

4. Well Location

Unit Letter J : 1650 feet from the South line and 1980 feet from the East line

Section 36 Township 9S Range 33E County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

4274

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL. ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

14. See Attached procedure.

Condition of Approval : Notify OCD Hobbs
office 24 hours prior to running MIT Test & Chart

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Dianne Newman TITLE Regulatory Specialist DATE 9/4/09

Type or print name Dianne Newman

E-mail address: dnewman@gmx-resources.com

PHONE: (405) 254-5821

or State Use Only

APPROVED BY: [Signature]
Conditions of Approval (if any):

TITLE DISTRICT 1 SUPERVISOR DATE SEP 21 2009

GMX RESOURCES, INC.

TWITTY BEH STATE #1

Lea Co, NM

PROCEDURE TO TA Well

1. MIRM PU
2. NPWH NUBOP
3. REL PKR @ 10813'. PDH w/ thg & pkv.
4. RU WL & GIH w/ CIBP to 10950'± and
Set CIBP. PDH RD WL
5. GIH w/ thg to CIBP tag up and RU pump
truck. Load hole as needed and test to
500 # w/ recording device for 30 min or
as required by STATE OF NM. Note: Proper
notice to be give state prior to pressure
test.
6. Circulate hole w/ proper pkv fluid.
7. NUBOP NUWH. CLEAN & CLEAR location
RDPV & MO.