UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

RECEIVED	
OSED A LYDRA	ľ
HORPO	┝

FORM APPROVED OMB NO. 1004-0135

□ Other

	Expires:		
Lease Seri	al No.		

SUNDRY NOTICES AND REPORTS ON WELLS NMNM16835 Do not use this form for proposals to drill or to re-enter an

abandoned w	6. If Indian, Allottee	or Tribe Name			
SUBMIT IN TR	IPLICATE - Other instru	ctions on reverse side.	7 If Unit or CA/Agr	eement, Name and/or No	
T Type of Well ☐ Gas Well ☐ O	ther /		8. Well Name and No NEUHAUS 14 F		
Name of Operator CHESAPEAKE OPERATING	Contact E-Mail: linda.good	LINDA GOOD d@chk com	9. API Well No. 30-025-36353-	-00-S1 /	
3a Address P O BOX 18496 OKLAHOMA CITY, OK 7315	54-0496	3b. Phone No (include area co Ph: 405-935-4275		DNE, Bone	
4. Location of Well (Footage, Sec.,	T., R., M., or Survey Description	on)	11. County or Parish		
Sec 14 T20S R35E SWNE 1	980FNL 1650FEL		LEA COUNTY	, NM 🖌	
12. CHECK APP	PROPRIATE BOX(ES) T	O INDICATE NATURE O	F NOTICE, REPORT, OR OTHI	ER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent Acidize Alter Casing		ce of finein 1		☐ Water Shut-Off ☐ Well Integrity	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) determined that the site is ready for final inspection)

□ Plug Back

☐ New Construction

☐ Plug and Abandon

CHESAPEAKE, RESPECTFULLY, REQUESTS PERMISSION TO TEMPORARY ABANDON THIS WELL FOR POSSIBLE WATERFLOOD EVALUATION PER THE FOLLOWING PROCEDURE.

1. NOTIFY THE BLM 24 HOURS IN ADVANCE PRIOR TO PERFORMING MIT.

☐ Casing Repair

☐ Change Plans

Convert to Injection

- 2. HOLD TAILGATE SAFETY MEETING PRIOR TO BEGINNING WORK EACH MORNING AND AS REQUIRED FOR SPECIFIC OPERATIONS.
- 3. NDWH. NU BOP.

☐ Subsequent Report

Final Abandonment Notice

4 RIH W/CIBP AND SET @ 9,700' AND SPOT 35' CEMENT ON TOP.

SEE ATTACHED FOR CONDITIONS OF APPROVAL

□ Recomplete

Temporarily Abandon ☐ Water Disposal

14. Thereby certify	that the foregoing is true and correct. Electronic Submission #73963 verifi For CHESAPEAKE OPERA Committed to AFMSS for processing by K	TING IN	C, sent to the Hobbs	66SE)	
Name (Printed/I	Typed) LINDA GOOD	Title	SR. REGULATORY COMPL	JANCE SPEC	
Signature	(Electronic Submission)	Date	09/03/2009		
	THIS SPACE FOR FEDER	AL OR	STATE OFFICE USE		
Approved By DU	NCAN WHITLOCK SEP 2 2 2009 CAULY	Title	LEAD PET	Da	te 09/17/200
certify that the applic	al, if any, are attached. Approval of this notice does not warrant of ant holds legal or equitable title to those rights in the subject lease the applicant to conduct operations thereon.	i	e Hobbs		
Title 18 U.S.C. Section States any false, fice	on 1001 and Title 43 U.S.C. Section 1212, make it a crime for any titious or fraudulent statements or representations as to any matter	person ki within its	nowingly and willfully to make to any jurisdiction.	department or agency of	the United

Additional data for EC transaction #73963 that would not fit on the form

32. Additional remarks, continued

- 5. LOAD WELL WITH PACKER FLUID.
- $6.\ PRESSURE\ UP\ WELL\ TO\ 500\ PSI.\ RECORD\ MIT\ FOR\ 30\ MINUTES.$ IF LESS THAN 10% PRESSURE CHANGE IS 30 MINUTES MIT IS ACCEPTABLE.
- 7. BLEED PRESSURE OFF WELL. ND BOP. NU WH.
- 8. RDMO. CLEAN LOCATION.

(CHK PN 890895)



Proposal - Workover

NEUHAUS 14 FEDERAL 4

FEATHERSTONE B, SPRING EAST Field:

County: LEA

NEW MEXICO State:

SEC 14, 20S-35E, 1980 FNL & 1650 FEL GL 3,671.00 KB 3,686.00 Location:

Elevation:

KB Height: 15.00

157 B.5


8110

2rd B.5

9322

10025

Spud Date: 8/24/2003 Initial Compl. Date: API #: 3002536353 CHK Propterty #: 890895 1st Prod Date: 11/22/2005 PBTD: Original Hole - 10180.0 TD: 10,288.0



BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status provided that the operator:

- Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Neuhaus 14 Federal #4. Well may be approved to be TA/SI for a period of 1 Year after successful MIT and subsequent report is submitted. This will be the last and only TA/SI approval. Well must be P&A or plans to convert to WIW submitted by September 1, 2010. IF well is going to be used as a WIW cement behind Production string needs to be verified by Bond log to prove TOC into Intermediate casing string. No bleed off is allowed on WIW MIT