Form 3160-5 (February 2005)

## UNITED STATES . DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SEP 2 2 2000 OCD-HORI

FORM APROVED OMB NO. 1004-0137 EXPIRES: March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELJ Lease Serial No. Do not use this form for proposals to drill or to re-**NMNM 97157** abandoned well. Use Form 3160-3 (APD) for such proposals 6. If Indian, Allottee or Tribe Name SUBMIT IN TRIPLICATE - Other instructions on page 2 7. Unit or CA Agreement Name and No. 1. Type of Well ☑ Oil Well Gas Well Other 8 Well Name and No. 2. Name of Operator Paloma Blanco 17 Fed 1 **DEVON ENERGY PRODUCTION COMPANY, LP** 9. API Well No. 3a, Address 3b. Phone No. (include area code) 30-025-35033 10. Field and Pool, or Exploratory Area 20 North Broadway, Ste 1500, Oklahoma City, OK 73102 405-552-4615 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) North Bell Lake Delaware 1980 FNL 660 FWL 17 T23S R34E 11. County or Parish, State NM LEA 12. CHECK APPROPRIATE BOX(es) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF ACTION Deepen Acidize Production (Start/Resume) ✓ Notice of Intent Fracture Treat ] Well Integrity Alter Casing Reclamation Subsequent Report New Construction Casing Repair Recomplete Other Temporarily Abandon Plug and Abandon \_\_\_ Change Plans Final Abandonment Notice Plug Back Water Disposal Convert to Injection 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work and approximate duration thereof If the proposal deepen directionally or recomplete horizontally, give subsurface location and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has

## **PROPOSED PLUG & ABANDONMENT**

- 1. MIRU. POOH w/rod string & 2-7/8" production tubing assembly.
- 2. Circulate wellbore w/10 ppg mud.

determined that the site is ready for final inspection)


- 3. TIH & dump 35' cmt on existing CIBP @ 7440'.
- 4. TIH & set CIBP @ 6770'. Cap w/35' cmt.
- 5. Free point 7" casing & cut @ +/-6400'. POOH and lay down casing. (TOC shown @ 6520' by temp survey)
- 6. Spot 30 sx stump plug, 50' cmt below & 50' cmt above stump. Tag TOC. (calc 30 sx stump=120' cmt) woc Tag 160' plus


7. Spot 35 sx cmt @ 5043'. Tag TOC. (calc TOC @ 4934'. 9-5/8" shoe @ 4993') /50' plag

- 8. Spot 80 sx cmt @ 4650'. Tag TOC. (salt section from 4454' to 4600'. Calc. TOC @ 4402')
- 9. Spot 35 sx cmt @ 1425'. (calc TOC @ 1316')
- 10. Spot 35 sx cmt @ 1074'. Tag TOC. (calc TOC @ 965'. 13-3/8" shoe @ 1024')
- 11. Spot 35 sx cmt for surface plug. (calc 35 sx plug=109' cmt)
- 12. Cut wellhead off 3' below ground level & set dry hole marker.

SEE ATTACHED FOR CONDITIONS OF APPROVAL

14. I hereby certify that the foregoing is true and correct Name: Ronnie Slack	Title Engineerin	g Technician		
Signature Roung Slaw	Date 9/14	·/2009	APPROVED	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE				
Approved by	UISTRICT 1 90		SEP 2 0 2009	
Conditions of approval, if any are attached. Approval of this notice does not warrant or certify that the applicant holds legal equitable title to those rights in the subject lease which would entitle the applicant to conduct or operations thereon.		Date	JAMES A. AMOS SUPERVISOR-EPS	





## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed prior to commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet, a 3M system for a well not deeper than 13,636 feet, and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in a cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

- 6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash</u>. All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.