

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD-HOBBS

FORM APPROVED
OMB NO. 1004-0137
Expires March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well ☐ Gas Well ☒ Other WIW

2. Name of Operator

Occidental Permian Limited Partnership Attn: Mark Stephens, Rm. 20.099

3a. Address

P.O. Box 4294, Houston, TX 77210-4294

3b. Phone No. (include area code)

(713) 366-5158

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1400' FSL & 2430' FEL, Letter J, Sec. 30, T-18-S, R-38-E

5. Lease Serial No.

LC-032233(A)

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

North Hobbs G/SA No. 333
Unit

9. API Well No.

30-025-28955

10. Field and Pool, or Exploratory Area

Hobbs; Grayburg-San Andres

11. County or Parish, State

Lea Co. NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent☒ Subsequent Report☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize☐ Alter Casing☐ Casing Repair☐ Change Plans☐ Convert to Injection☐ Deepen☐ Fracture Treat☐ New Construction☐ Plug and Abandon☐ Plug Back☐ Production (Start/Resume)☐ Reclamation☐ Recomplete☐ Temporarily Abandon☐ Water Disposal☐ Water Shut-Off☐ Well Integrity☒ Other Repairpacker leak

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recomple in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

8/5/09 - 8/10/09:

MI x RU. ND WH x NU BOP. POOH with injection equipment. Test packers in hole x find leak. POOH with packers x send to Schlehuber for redressing. RBIH with tandem injection packer assembly - set 5-1/2" KTC hydraulic tandem packer at 4173' - 4175' and 5-1/2" Arrowset 1-X packer at 4038' - 4045' on 128 jts. 2-7/8" Duoline-20 injection tubing. Circulate well with 85 bbls 10# brine packer fluid. ND BOP x NU WH. Pressure test casing for 30 minutes (initial at 610 psi, ending at 600 psi). Test witnessed by the NMOCD (John R. Harrison). Turn well over to injection. RD x MO and clean location.

RECEIVED

OCT 08 2009

HOBBSOCD

ACCEPTED FOR RECORD

OCT 6 2009

/s/ Chris Walls

14 I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

Mark Stephens

Title

Regulatory Compliance Analyst

Date

9/23/09

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

PETROLEUM ENGINEER


Date

OCT 09 2009

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon

Office

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



GRAPHIC CONTROLS CORPORATION
BUFFALO, NEW YORK

TEST DATE
8/10/09

BR 2221

DATE 8/10/09
TIME 10:00
TEST NUMBER
30-333
3002529755
NHT-5411
DEPARTMENT
- FLD
- 40004

Signature

START
STOP