

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103

Revised June 10, 2003

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-36432
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/> TA		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Tom Brown, Inc.		6. State Oil & Gas Lease No.
3. Address of Operator P O Box 2608, Midland, TX 79702		7. Lease Name or Unit Agreement Name Shelley 34 State
4. Well Location Unit Letter <u>B</u> : <u>990</u> feet from the <u>North</u> line and <u>1700</u> feet from the <u>East</u> line Section <u>34</u> Township <u>19S</u> Range <u>37E</u> NMPM Lea County		8. Well Number 003
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3606 GR		9. OGRID Number 023230
		10. Pool name or Wildcat Skaggs; Drinkard (57000)

## 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

## NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐TEMPORARILY ABANDON ☐ CHANGE PLANS ☐PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐OTHER: ☐

## SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐CASING TEST AND CEMENT JOB ☐OTHER: TA ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

11/17/03 Perf Drinkard 6998-7012 w/ 4 SPF

11/18/03 Acidize Drinkard perfs 6998-7012 w/ 3000 gals 15% HCL NEFE acid

11/20/03 Re-Acidize Drinkard perfs 6998-7012 w/ 3000 gals 15% HCL NEFE acid. Swab well

11/24/03 RIH &amp; set 5-1/2" CIBP @ 6950 w/ 10' cmt on top. Perf Drinkard 6700-6710, 6736-6738, 6784-6788, 6794-6798 w/ 4 SPF. RIH &amp; set pkr @ 6591

11/25/03 RIH &amp; released pkr and re-set @ 6591, Acidize Drinkard perfs 6700-6798 w/ 3000 gals 15% HCL NEFE. Swab well

12/10/03 POOH w/ tbg &amp; pkr

12/11/03 RIH &amp; set 5-1/2" CIBP @ 6687 w/ 10' cmt on top. Perf Tubb 6622-6644 w/ 4 SPF

12/12/03 RIH w/ Tbg &amp; pkr. Pkr set @ 6526. Acidize Tubb 6622-6644 w/ 3000 gals 15% HCL NEFE acid. Swab well

12/18/03 SI well pending evaluation

1/01/04 POOH w/ tbg & pkr. RIH w/ 50' cmt bailer, dump 25' cmt on top of existing cmt & CIBP @ 6687. RIH & set 5-1/2" CIBP @ 6595. POOH w/ setting tool. TIH w/ bailer, make 2 runs & dump 35' cmt on top of CIBP. RD ND BOP, NU wellhead, load csg w/ 20 bbls fresh water pkr fluid and test to 500 psi for 30 minutes. NMOC was notified but they chose not to witness the test. See attached chart. (copy of chart on back)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Diane Kuykendall TITLE Operations Asst/Tech DATE 1/09/04Type or print name Diane Kuykendall E-mail address: dkuykendall@tombrown.com Telephone No. 432-688-9773

(This space for State use)

APPROVED BY Larry W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER

Conditions of approval, if any:

This Approval of Temporary  
Abandonment Expires 1/14/09

JAN 14 2004

