
District I	s To Appropriate Dist		State of New N	Mexico		Form C-103	
District	R	CENT	Minerals and Na	itural Resources	WELL ADINO	June 19, 2008	
1625 N French District II	Dr , Hobbs, NM 8824				WELL API NO. 30-025-39193		
1301 W Grand	Ave , Artesia, NM 8	10T ] 4 200!	CONSERVATIO	N DIVISION	5. Indicate Type of Le	ease	
	s Rd , Aztec, NML87			ancis Di.	STATE	FEE 🔽	
	cıs Dr , Santa Fe, NM		J Santa Fe, NM	87505	6. State Oil & Gas Le	ase No.	
87505	icis Di , Santa Fe, INM				NA		
			REPORTS ON WELL		7. Lease Name or Uni	it Agreement Name	
DIFFERENT R			RILL OR TO DEEPEN OR I R PERMIT" (FORM C-101)		House SWD		
PROPOSALS)  1. Type of V	Vell: Oil Well	☐ Gas Well	☑ Other: Disposal We	ell	8. Well Number	001	
2. Name of Apache Corp					9. OGRID Number 873		
3. Address of	•				10. Pool name or Wil		
6120 S Yale Ave, Suite 1500, Tulsa, OK 74136-4224 SWD; San Andres							
4. Well Location							
	t Letter M	: 990	feet from the South	line and <u>500</u>			
	ion 12	r		Range 38E		ounty Lea	
		Military	ration (Show whether L	OR, RKB, RT, GR, etc.			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data							
	NOTICE O				SEQUENT REPO		
	REMEDIAL WORK	_	ND ABANDON	REMEDIAL WOR		TERING CASING	
	ILY ABANDON TER CASING		E PLANS   LE COMPL	CASING/CEMEN	_	ND A	
	E COMMINGLE		LE COMPL	CASING/CLIVIEN	1 300		
5011111021		_			_		
OTHER:				OTHER: Complet		1 1:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion							
	completion.	a work). BLL	ROLL 1103. 1 of William	upic Completions. 71	וו ביל נה	Vell POD±	
	•	d as a SWD we	II via the following proc	edure:	NOW.		
	This new drill was completed as a SWD well via the following procedure:						
7/14/2009 Acid San Andres open hole fr/ 4600' - 5500' w/ 19,992 gals 15% acid.							
				gals 15% acid.			
7/20/2009	Re-acid San An	dres w/ 13,902	gals 15% acid.				
7/20/2009 7/31/2009 8/05/2009	Re-acid San An Frac San Andre Clean out open	dres w/ 13,902 s w/ 50,526 gal: hole to TD @ 5	gals 15% acıd. s gel and 100,000 # 20 500' and circulate cleaı	./40 sand. n.			
7/20/2009 7/31/2009 8/05/2009	Re-acid San An Frac San Andre Clean out open Ran tbg to 4570	dres w/ 13,902 s w/ 50,526 gal hole to TD @ 5 '. Set packer @	gals 15% acıd. s gel and 100,000 # 20 500' and circulate cleaı e 4570'. Test and chart	./40 sand. n.	e attached chart.		
7/20/2009 7/31/2009 8/05/2009 8/06/2009	Re-acid San An Frac San Andre Clean out open	dres w/ 13,902 s w/ 50,526 gal hole to TD @ 5 '. Set packer @ ding installation	gals 15% acıd. s gel and 100,000 # 20 500' and circulate cleaı e 4570'. Test and chart	./40 sand. n.	e attached chart.		
7/20/2009 7/31/2009 8/05/2009 8/06/2009	Re-acid San An Frac San Andre Clean out open Ran tbg to 4570 Shut well in pen	dres w/ 13,902 s w/ 50,526 gal hole to TD @ 5 '. Set packer @ ding installation	gals 15% acıd. s gel and 100,000 # 20 500' and circulate cleaı e 4570'. Test and chart	./40 sand. n.	e attached chart.		
7/20/2009 7/31/2009 8/05/2009 8/06/2009	Re-acid San An Frac San Andre Clean out open Ran tbg to 4570 Shut well in pen	dres w/ 13,902 s w/ 50,526 gal hole to TD @ 5 '. Set packer @ ding installation	gals 15% acıd. s gel and 100,000 # 20 500' and circulate cleaı e 4570'. Test and chart	/40 sand. n. casing, held okay, se	e attached chart.  D-1169		
7/20/2009 7/31/2009 8/05/2009 8/06/2009	Re-acid San An Frac San Andre Clean out open Ran tbg to 4570 Shut well in pen	dres w/ 13,902 s w/ 50,526 gal hole to TD @ 5 '. Set packer @ ding installation	gals 15% acid. s gel and 100,000 # 20 500' and circulate clear g 4570'. Test and chart g of SWD line.	/40 sand. n. casing, held okay, se	,		
7/20/2009 7/31/2009 8/05/2009 8/06/2009	Re-acid San An Frac San Andre Clean out open Ran tbg to 4570 Shut well in pen	dres w/ 13,902 s w/ 50,526 gal hole to TD @ 5 '. Set packer @ ding installation	gals 15% acıd. s gel and 100,000 # 20 500' and circulate cleaı e 4570'. Test and chart	/40 sand. n. casing, held okay, se	,		
7/20/2009 7/31/2009 8/05/2009 8/06/2009 8/12/2009	Re-acid San An Frac San Andre Clean out open Ran tbg to 4570 Shut well in pen Commence disp	dres w/ 13,902 s w/ 50,526 gal hole to TD @ 5 '. Set packer @ ding installation	gals 15% acid. s gel and 100,000 # 20 500' and circulate clear g 4570'. Test and chart g of SWD line.	/40 sand. n. casing, held okay, se	,		
7/20/2009 7/31/2009 8/05/2009 8/06/2009 8/12/2009 Spud Date:	Re-acid San An Frac San Andre Clean out open Ran tbg to 4570 Shut well in pen Commence disp	dres w/ 13,902 s w/ 50,526 gals hole to TD @ 5 '. Set packer @ ding installation losal.	gals 15% acid. s gel and 100,000 # 20 500' and circulate clear g 4570'. Test and chart g of SWD line.	July 2009  Date: 07/07/2009	D-1169		
7/20/2009 7/31/2009 8/05/2009 8/06/2009 8/12/2009 Spud Date:	Re-acid San An Frac San Andre Clean out open Ran tbg to 4570 Shut well in pen Commence disposed of the formation of the forma	dres w/ 13,902 s w/ 50,526 gals hole to TD @ 5 '. Set packer @ ding installation posal.	gals 15% acid. s gel and 100,000 # 20 500' and circulate clear 4570'. Test and chart of SWD line.  Rig Release	Date: 07/07/2009	D-1169 ge and belief.		
7/20/2009 7/31/2009 8/05/2009 8/06/2009 8/12/2009 Spud Date:	Re-acid San An Frac San Andre Clean out open Ran tbg to 4570 Shut well in pen Commence disposed of the formation of the forma	dres w/ 13,902 s w/ 50,526 gals hole to TD @ 5 '. Set packer @ ding installation losal.	gals 15% acid. s gel and 100,000 # 20 500' and circulate clear 4570'. Test and chart of SWD line.  Rig Release	July 2009  Date: 07/07/2009	D-1169 ge and belief.	10/01/2009	
7/20/2009 7/31/2009 8/05/2009 8/06/2009 8/12/2009 Spud Date:  I hereby certification SIGNATURE Type or print	Re-acid San An Frac San Andre Clean out open Ran tbg to 4570 Shut well in pen Commence disposed of the formation of the forma	dres w/ 13,902 s w/ 50,526 gall hole to TD @ 5 '. Set packer @ ding installation losal.	gals 15% acid. s gel and 100,000 # 20 500' and circulate clear 4570'. Test and chart of SWD line.  Rig Release Tue and complete to the	Date: 07/07/2009	D-1169 ge and belief.  DATE		
7/20/2009 7/31/2009 8/05/2009 8/06/2009 8/12/2009 Spud Date:	Re-acid San An Frac San Andre Clean out open Ran tbg to 4570 Shut well in pen Commence disposed of the formation of the forma	dres w/ 13,902 s w/ 50,526 gall hole to TD @ 5 '. Set packer @ ding installation losal.	gals 15% acid. s gel and 100,000 # 20 500' and circulate clear 4570'. Test and chart of SWD line.  Rig Release Tue and complete to the	Date: 07/07/2009	ge and belief.  DATE  ACHECOTP COM  PHONE	10/01/2009	



25 ST BANK